

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: _____ (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

CONT

0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | At 1300, the Decay Heat Removal Flow Control Valve (DHV-111) would not

0 3 | respond to an open command after being closed to check for low pressure

0 4 | injection low flow alarm. DHV-111 was manually opened. Remote control

0 5 | was immediately re-established. Subsequent investigation and cycling re-

0 6 | vealed no anomalies. Health and safety of public and plant were not

0 7 | endangered since manual control was available.

0 8 | _____

0 9 | _____

17 | LER NO. REPORT NUMBER: 7 8

18 | EVENT YEAR: 7 8

19 | SEQUENTIAL REPORT NO.: 0 3 4

20 | OCCURRENCE CODE: 0 3

21 | REPORT TYPE: L

22 | REVISION NO.: 0

23 | ACTION TAKEN: Z

24 | FUTURE ACTION: Z

25 | EFFECT ON PLANT: Z

26 | SHUTDOWN METHOD: Z

27 | HOURS: 0 0 0 0

28 | ATTACHMENT SUBMITTED: Y

29 | NRC-4 FORM 365: N

30 | PRIME COMP. SUPPLIER: X

31 | COMPONENT MANUFACTURER: C 6 6 5

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | Cause of this event is undetermined as full control was re-established

1 1 | and subsequent investigation revealed no apparent cause. This is the first

1 2 | occurrence of this event.

1 3 | _____

1 4 | _____

1 5 | FACILITY STATUS: H

1 6 | ACTIVITY RELEASED OR RELEASE: Z

1 7 | PERSONNEL EXPOSURES NUMBER: 0 0 0 0

1 8 | PERSONNEL INJURIES NUMBER: 0 0 0 0

1 9 | LOSS OF OR DAMAGE TO FACILITY TYPE: Z

2 0 | NRC USE ONLY

2 1 | METHOD OF DISCOVERY: C

2 2 | DISCOVERY DESCRIPTION: Operator observation

2 3 | AMOUNT OF ACTIVITY: NA

2 4 | LOCATION OF RELEASE: NA

2 5 | DESCRIPTION: NA

2 6 | DESCRIPTION: NA

2 7 | DESCRIPTION: NA

2 8 | NAME OF PREPARER: J. COOPER

2 9 | PHONE: (904) 795-6486

POOR ORIGINAL

(SEE ATTACHED SUPPLEMENTARY INFORMATION SHEET)

8002270676

SUPPLEMENTARY INFORMATION

1. Report No.: 50-302/78-034/03L-0
2. Facility: Crystal River Unit #3
3. Report Date: 14 July 1978
4. Occurrence Date: 21 June 1978
5. Identification of Occurrence:

No control of the Decay Heat Removal Flow control Valve DHV-111 rendering in a condition contrary to Technical Specification 3.1.2.5.

6. Conditions Prior to Occurrence:

Mode 6 refueling.

7. Description of Occurrence:

At 1300 with Decay Heat Removal Flow at approximately 1000 GPM to check for low pressure injection low flow alarm, Decay Heat Removal Flow Control Valve (DHV-111) would not respond to an open command while in "bypass mode". DHV-111 was manually reopened to regain required flow. Valve control was placed in both "automatic" and "bypass" by the operators and DHV-111 responded in all cases. Maintenance electricians investigated and found no discrepancies. Valve DHV-111 was cycled several times and responded satisfactorily to commands.

8. Designation of Apparent Cause:

Cause of this event is undetermined as full control was re-established and subsequent investigation revealed no apparent cause.

9. Analysis of Occurrence:

There were no safety implications presented by this occurrence as manual control of flow was available and utilized until remote controls responded.

10. Corrective Action:

None required as cause is a transient anomaly.

11. Failure Data:

This is the first occurrence of this event.