

# LICENSEE EVENT REPORT

CONTROL BLOCK: 1 2 3 4 5 6

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME										LICENSE NUMBER										LICENSE TYPE					EVENT TYPE													
F L C R P 3										0 0 - 0 0 0 0 0 0 - 0 0										4 1 1 1 1					0 3													
7	8	9	14	15	25	26	30	31	32	7	8	9	10	11	12	13	14	15	16	7	8	9	10	11	12	13	14	15	7	8	9	10	11	12	13	14	15	
CATEGORY										DOCKET NUMBER										EVENT DATE					REPORT DATE													
01 CONT - -										0 5 0 - 0 3 0 2										0 3 0 7 7 7					0 3 3 0 7 7													
7	8	57	58	59	60	61	68	69	74	75	80	7	8	9	10	11	12	13	14	15	7	8	9	10	11	12	13	14	15	7	8	9	10	11	12	13	14	15

**EVENT DESCRIPTION**

02 To perform necessary preplanned maintenance (repacking) on Makeup Valve (MUV-26) "B" loop of the high pressure injection system was isolated contrary to Technical Specification 3.5.2. Redundant systems were available and operable. First occurrence of this type. System restored in less than 72 hours in accordance with Technical Specifications. (77-25)

SYSTEM CODE		CAUSE CODE		COMPONENT CODE				PRIME COMPONENT SUPPLIER		COMPONENT MANUFACTURER				VIOLATION	
I B		F		V A L V E X				N		W O 3 0				N	
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22

**CAUSE DESCRIPTION**

08 Makeup Valve MUV-26 was repacked and the "B" HPI loop was restored operable within 72 hours in accordance with the Technical Specification.

FACILITY STATUS		% POWER			OTHER STATUS			METHOD OF DISCOVERY			DISCOVERY DESCRIPTION		
E		0 4 0			N/A			B			N/A		
7	8	9	10	11	12	13	14	15	16	17	18	19	20

FORM OF ACTIVITY RELEASED		CONTENT OF RELEASE		AMOUNT OF ACTIVITY				LOCATION OF RELEASE					
Z		Z		N/A				N/A					
7	8	9	10	11	12	13	14	15	16	17	18	19	20

**PERSONNEL EXPOSURES**

NUMBER		TYPE		DESCRIPTION	
0 0 0		Z		N/A	
7	8	9	10	11	12

**PERSONNEL INJURIES**

NUMBER		DESCRIPTION	
0 0 0		N/A	
7	8	9	10

**OFFSITE CONSEQUENCES**

13 N/A

**LOSS OR DAMAGE TO FACILITY**

TYPE		DESCRIPTION	
Z		N/A	
7	8	9	10

**PUBLICITY**

17 N/A

**ADDITIONAL FACTORS**

18 See attached Supplementary Information

8002270 747

19

NAME: W. P. Stewart PHONE: (813) 866-4159

Supplementary Information

1. Report No: 50-302/77-25
2. Facility: Crystal River Unit #3
3. Report Date: 30 March 1977
4. Occurrence Date: 7 March 1977
5. Identification of Occurrence:

High pressure injection capabilities to "B" HPI loop inoperable contrary to Technical Specification 3.5.2.
6. Conditions Prior to Occurrence:

Plant was operating normally in Mode 1 at 40% power steady state.
7. Description of Occurrence:

In order to perform maintenance on one of two "B" loop high pressure injection isolation valves (MUV-26), the "B" loop was isolated. During this time period, two independent High Pressure Injection Pumps were available and operable from independent power supplies to the "A" high pressure injection loop. Following maintenance, the "B" HPI loop was restored to original configuration.
8. Designation of Apparent Cause of Occurrence:

The cause of this event was performance of necessary planned maintenance.
9. Analysis of Occurrence:

There were no safety implications as either subsystem in conjunction with core flooding would maintain temperatures within prescribed limits in the event of accident conditions and redundancy was maintained.
10. Corrective Action:

No corrective action is required as Makeup Valve MUV-26 was repacked and the "B" HPI loop was restored operable within 72 hours in accordance with the Technical Specification.
11. Failure Data:

This occurrence was non-repetitive.