

LICENSE EVENT REPORT

CONTROL BLOCK: [] [] [] [] [] [] [] [] [] []

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSE NAME: F I C R 3 | LICENSE NUMBER: 0 0 - 0 0 0 0 0 0 - 0 0 | LICENSE TYPE: 4 1 1 1 1 | EVENT TYPE: 0 3

REPORT TYPE: L | REPORT SOURCE: L | DOCKET NUMBER: 0 5 0 - 0 3 0 2 | EVENT DATE: 0 5 3 0 7 7 | REPORT DATE: 0 6 3 0 7 7

EVENT DESCRIPTION

01 In the process of reviewing completed surveillance procedure SP-349, it was discovered that the operability of the Motor Driven Emergency Feedwater Pump flow path had not been verified within the time frame set forth by Technical Specification 4.7.1.2.a.2. Redundancy NA. First occurrence of this event. SP-349 was performed immediately with satisfactory results and personnel instructed to ensure total SP requirements are met.

SYSTEM CODE: C H | CAUSE CODE: A | COMPONENT CODE: Z Z Z Z Z Z | PRIME COMPONENT SUPPLIER: Z | COMPONENT MANUFACTURER: Z 9 9 9 | VIOLATION: N (LER 77-58)

CAUSE DESCRIPTION

08 This occurrence was the result of the failure to ensure that the total requirements of a surveillance procedure had been met within the time frame required by Tech Specs. Personnel have been instructed to insure these requirements are met.

FACILITY STATUS: C | % POWER: 0 0 0 | OTHER STATUS: NA | METHOD OF DISCOVERY: Z | DISCOVERY DESCRIPTION: Review of completed surveillance procedure

FORM OF ACTIVITY RELEASED: Z | CONTENT OF RELEASE: Z | AMOUNT OF ACTIVITY: NA | LOCATION OF RELEASE: NA

PERSONNEL EXPOSURES

13 NUMBER: 0 0 0 | TYPE: Z | DESCRIPTION: NA

PERSONNEL INJURIES

14 NUMBER: 0 0 0 | DESCRIPTION: NA

OFFSITE CONSEQUENCES

15 OFFSITE CONSEQUENCES: NA

LOSS OR DAMAGE TO FACILITY

16 TYPE: Z | DESCRIPTION: NA

PUBLICITY

17 PUBLICITY: NA

ADDITIONAL FACTORS

18 See attached Supplementary Information

8002 270 779

19 NAME: W. P. Stewart | PHONE: (813) 866-4159

Supplementary Information

1. Report No.: 50-302/77-58
2. Facility: Crystal River Unit #3
3. Report Date: 30 June 1977
4. Occurrence Date: 30 May 1977 - Discovered: 7 June 1977
5. Identification of Occurrence:

Failure to verify the operability of the Motor Driven Emergency Feedwater Pump flow path within the time frame required by Technical Specification 4.7.1.2.a.2.

6. Conditions Prior to Occurrence:

Mode 3 hot standby in the process of plant startup.

7. Description of Occurrence:

In the process of reviewing completed surveillance procedures on 7 June 1977, it was discovered that the portion of surveillance procedure SP-349 covering the operability of the Motor Driven Emergency Feedwater Pump's flow path had not been performed to meet Tech Spec. time frame requirement to enter mode 3. Supervision was immediately notified and surveillance procedure SP-349 Emergency Feedwater Pump operability demonstration was performed. The results of SP-349 were satisfactory.

- Designation of Apparent Cause:

This occurrence was due to an error in evaluation of the performed SP-349 prior to entering mode 3.

9. Analysis of Occurrence: The safety of the plant and general public was not jeopardized as EFP-1 was operable on the previous SP-349 and no valve repositioning had been performed.
10. Corrective Action:

The Shift Supervisors have been instructed to insure that the total requirements of surveillance procedures have been satisfied.
11. Failure Data:

This occurrence is non-repetitive.