LICENSEE EVENT REFURI

	하는 맛이 가다면 보통 중에 가는 사람이 되었다.
CONTROL BLOCK:	(PLEASE PRINT ALL REQUIRED INFORMATE
UCENSEE NAME LICENSE NUMBER	LICENSE EVENT
01 F L C R P 3 0 0 - 0 0 0 0	
7 8 9 14 . 15	25 26 30 31 32
CATEGORY TYPE SQUACE DOCKET NUMBER	2 0 7 2 9 7 7 0 8 1 2 7
7 8 57 58 59 60 61	68 69 74 75
EVENT DESCRIPTION	
7 89	
old and 2 August 1977, probable unplanned radioac	ctive gas releases to the Auxiliary Building
04 occurred contrary to E.T.S. 5.6.2.A. Redunda	mcy NA. The fifth occurrence of this
7 8 9 OS event. Due to the brevity of these releases	there were no measurable changes in the
7 8 9 [continuous release concentrations.	(LER 77-93E)
7 8 9 PRME	COMPONENT
SYSTEM CAUSE COMPONENT CODE SUPPLIES	MANUFACTURER VIOLATION
7 8 9 10 11 12 17 43	44 47 48
CAUSE DESCRIPTION 5	
7 8 9	seal on the Waste evaporator. The loop
seal was re-established on each occurrence.	
To [
	OF DISCOVERY DESCRIPTION
11 E 100 NA	A High radiation alarm on RMA-2g
7 · 6 9 .10 12 13 44 4	15 46
	Auxiliary Building
7 8 9 10 11 44	45
NUMBER TYPE DESCRIPTION	
7 8 9 11 12 13 NA	
PERSONNEL INJURIES NUMBER DESCRIPTION	
7 8 9 11 12 NA	
OFFSITE CONSEQUENCES	
7 8 9	- FUUIN
LOSS OR DAMAGE TO FACILITY	முற்றும்
TYPE DESCRIPTION .	
7 8 9 10 PUBLICITY	
17 L NA	
7 8 9	900000
ADDITIONAL FACTORS	8002 280 777
7 8 9	
SEE ATTACHED SUPPLEME	ENTARY INFORMATION
7 8 9 NAME: W. P. Stewart	PHONE: 813/866-4159
NAME:	PHONE: 0107 000-4137

SUPPLEMENTARY INFORMATION

1. Report No.:

50-302/77-93E

2. Facility:

Crystal River Unit #3

3. Report Date:

12 August 1977

4. Occurrence Date:

29 July 1977 and 2 August 1977 (discovered 4 August 1977)

5. Identification of Occurrence:

Unplanned radioactive gas release contrary to Environmental Technical Specification 5.6.2.A.

6. Conditions Prior to Occurrence:

Mode 1 power operation.

7. Description of Occurrence:

It was discovered on 4 August 1977 that radiation monitor RMA-2 went into high alarm on two occasions. The alarms occurred on 29 July and 2 August 1977. The Plant Review Committee determined that a probable unplanned radioactive gas release had occurred on each date. Upon each occurrence, the high alarm cleared immediately and ventilation to the Auxiliary Building was resumed. Investigation revealed that on each occasion the loop seal on the waste evaporator had blown. Because of the brevity of the incident, there were no measurable changes in the release concentration on either occasion.

Designation of Apparent Cause:

Blown loop seal of the waste evaporator causing a probable radioactive gas release to the Auxiliary Building.

9. Analysis of Occurrence:

The health and safety of the plant and public were not affected, as the releases were of such short durations that they could not be measured.

10. Corrective Action:

The waste gas system is now being evaluated by Production and Plant Engineering, and corrective action will be implemented upon receipt of recommendations.

11. Failure Data:

This is the fifth occurrence of this event, as reported on LER's 77-49E, 77-61E, 77-73E, and 77-80E.