



LER SUPPLEMENTAL INFORMATION

SQRO-50-327/8007 Technical Specification Involved 3.7.3.1

Reported Under Technical Specification 6.9.1.12.h

Date of Occurrence: 3/15/80 Time of Occurrence: 0900 EST Unit 1

Identification and Description of Occurrence:

Notification was received from TVA Division of Engineering Design that the incorrect (non-conservative) valve operator weight was used in the seismic analysis for component cooling water valves FCV-70-133, 134, and 183.

Conditions Prior to Occurrence:

Unit 1 in Mode 6 following initial core loading.

Action specified in the Technical Specification Surveillance Requirements met due to inoperable equipment. Describe.

---

N/A

Apparent Cause of Occurrence:

Incorrect valve operator weight used in seismic analysis.

Analysis of Occurrence:

There was no hazard to the public health or safety.

Corrective Action:

The seismic analysis will be rerun using the correct valve operator weights.

Failure Data:

N/A