

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | C O F S V I | 2 0 0 0 - 0 0 0 0 0 0 - 0 0 | 3 4 1 1 2 0 | 4 | 5
7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CON'T
0 1 | REPORT SOURCE | L | 6 0 5 0 0 0 2 6 7 | 7 | 0 3 0 3 8 0 | 8 | 0 4 0 2 8 0 | 9
7 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | On March 3, 1980, with the reactor plant at approximately 10% thermal power, it was
0 3 | discovered that "A" emergency diesel generator would not load as required for the
0 4 | weekly 50% load test surveillance because of erratic governor control. This is being
0 5 | reported as a degraded mode of LCO 4.6.1(d) per Fort St. Vrain Technical Specification
0 6 | AC 7.5.2(b)2. There was no affect on public health or safety. No accompanying occur-
0 7 | rence. Redundant system available and operable.

0 8 | _____ 80

0 9 | SYSTEM CODE | CAUSE CODE | CAUSE SUBCODE | COMPONENT CODE | COMP SUBCODE | VALVE SUBCODE
| E D | 11 | E | 12 | X | 13 | M E C F U N | 14 | Z | 15 | Z | 16
7 8 9 10 11 12 13 14 15 16 17 18 19 20

17 | LER RO REPORT NUMBER | EVENT YEAR | SEQUENTIAL REPORT NO. | OCCURRENCE CODE | REPORT TYPE | REVISION NO.
| 8 0 | 21 | 0 1 0 | 24 26 | 0 3 | 28 29 | L | 30 | 0 | 32
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

ACTION TAKEN | FUTURE ACTION | EFFECT ON PLANT | SHUTDOWN METHOD | HOURS | ATTACHMENT SUBMITTED | NPRD-4 FORM SUB. | PRIME COMP. SUPPLIER | COMPONENT MANUFACTURER
| A | 18 | B | 19 | Z | 20 | Z | 21 | 0 0 0 0 | 22 | Y | 23 | N | 24 | N | 25 | W 2 9 0 | 26
33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | The emergency diesel generator governor developed a problem which reduced its speed
1 1 | control response to the point where it could not operate in parallel with the rest of
1 2 | the system. The generator was replaced with a spare and sent to the manufacturer for
1 3 | repair. The generator was successfully retested. No further corrective action is
1 4 | anticipated or required. The unit was a Woodward Type 2301.

1 5 | FACILITY STATUS | % POWER | OTHER STATUS | METHOD OF DISCOVERY | DISCOVERY DESCRIPTION
| C | 28 | 0 1 0 | 29 | N/A | 30 | B | 31 | Routine Surveillance Test | 32
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

1 6 | ACTIVITY CONTENT | RELEASED OF RELEASE | AMOUNT OF ACTIVITY | LOCATION OF RELEASE
| Z | 33 | Z | 34 | N/A | 35 | N/A | 36
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

1 7 | PERSONNEL EXPOSURES | NUMBER | TYPE | DESCRIPTION
| 0 0 0 | 37 | Z | 38 | N/A | 39
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

1 8 | PERSONNEL INJURIES | NUMBER | DESCRIPTION
| 0 0 0 | 40 | N/A | 41
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

1 9 | LOSS OF OR DAMAGE TO FACILITY | TYPE | DESCRIPTION
| Z | 42 | N/A | 43
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

2 0 | PUBLICITY ISSUED | DESCRIPTION
| N | 44 | N/A | 45
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

8004080427

NAME OF PREPARER

M. Davis for J.W. Gahan

PHONE:

(303) 785-2253

NRC USE ONLY