



LER SUPPLEMENTAL INFORMATION

SQRO-50-327/8008 Technical Specification Involved 3.3.3.9

Reported Under Technical Specification 6.9.1.13.b

Date of Occurrence: 3/3/80 Time of Occurrence: 1200 CST Unit 1

Identification and Description of Occurrence:

Operations personnel noted during routine checks that the cooling tower blowdown effluent line flow monitor (O-FR-27-175) was inoperable.

Conditions Prior to Occurrence:

Unit 1 initial fuel loading in progress.

Action specified in the Technical Specification Surveillance Requirement met due to inoperable equipment.

---

Flow rates are being estimated once per 4 hours during discharge of liquid wastes as required by action 30 of Table 3.3-12 under LCO 3.3.3.9.

Apparent Cause of Occurrence:

Inoperable flow rate monitor.

Analysis of Occurrence:

There was no hazard to the public health or safety.

Corrective Action:

Replace instrument with different design.

Failure Data:

N/A