

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: \_\_\_\_\_ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | T | N | S | N | P | 1 | 0 | 0 | - | 0 | 0 | 0 | 0 | - | 0 | 0 | 0 | 4 | 1 | 1 | 1 | 1 | 0 | 1 | 0  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32  
FACILITY CODE LICENSE NUMBER LICENSE TYPE

01 | R | C | 0 | 5 | 1 | 0 | 0 | 0 | 3 | 2 | 7 | 0 | 3 | 0 | 3 | 8 | 0 | 0 | 0 | 4 | 0 | 2 | 8 | 0 | 0  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32  
REPORT SOURCE SOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

01 | Liquid radwaste effluent line flow monitor 0-FI-77-42 was declared  
02 | inoperable on 3/3/80 at 1200 CST (T.S. 3.3.3.9). There was no danger  
03 | to the health and safety of the public. Previous occurrences - none.  
04 |  
05 |  
06 |  
07 |  
08 |

09 | M | A | B | A | I | N | S | T | R | U | E | Z  
9 10 11 12 13 14 15 16 17 18 19 20  
SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP SUBCODE VALVE SUBCODE  
17 | 8 | 0 | 0 | 0 | 9 | 0 | 3 | L | 0  
21 22 23 24 25 26 27 28 29 30 31  
LER RD REPORT NUMBER EVENT YEAR SEQUENTIAL REPORT NO OCCURRENCE CODE REPORT TYPE REVISION NO  
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NRC-4 FORM 50B PRIME COMP SUPPLIER COMPONENT MANUFACTURER  
F Z Z Z 0 0 0 0 0 Y N L F 1 8 0  
32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 | Flow monitor consistently indicated a higher discharge flowrate than  
11 | actually observed (conservative). The flow monitor was modified and  
12 | placed back into service.  
13 |  
14 |

15 | H | 0 | 0 | 0 | 0 | B | Operator observation  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32  
FACILITY STATUS N POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION  
16 | Z | Z | N/A | N/A |  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32  
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE  
17 | 0 | 0 | 0 | Z | N/A |  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32  
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION  
18 | 0 | 0 | 0 | Z | N/A |  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32  
PERSONNEL INJURIES NUMBER DESCRIPTION  
19 | 0 | 0 | 0 | Z | N/A |  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32  
LOSS OF AIR DAMPER TO FACILITY TYPE DESCRIPTION  
20 | Z | N/A |  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32  
PUBLISHER DISCOVERY DESCRIPTION  
21 | N | N/A |  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

NAME OF PREPARED BY Warren H. Kinsey PHONE 615-842-0295

POOR ORIGINAL 8004080622

LER SUPPLEMENTAL INFORMATION

SQRO-50-327/8009 Technical Specification Involved 3.3.3.9

Reported Under Technical Specification 6.9.1.13.b

Date of Occurrence: 3/3/80 Time of Occurrence: 1200 CST Unit 1

Identification and Description of Occurrence:

Engineering personnel noted during surveillance review incorrect flow readings. Liquid radwaste effluent line flow monitor 0-FT-77-42 was declared inoperable and modified.

Conditions Prior to Occurrence:

Unit 1 initial fuel loading in progress.

Action specified in the Technical Specification Surveillance Requirements met due to inoperable equipment.

---

Flow rates were estimated once per 4 hours during discharge of liquid wastes as required by action 27 of Table 3.3-12 under LCO 3.3.3.9.

Apparent Cause of Occurrence:

Inoperable flow rate monitor.

Analysis of Occurrence:

There was no hazard to the public health or safety.

Corrective Action:

The flow instrument was modified and returned to service.

Failure Data:

N/A