



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION II
101 MARIETTA ST., N.W., SUITE 3100
ATLANTA, GEORGIA 30303

APR 4 1980

In Reply Refer To:

RII:JPO

50-518, 50-519

50-520, 50-521

50-553, 50-554

Tennessee Valley Authority
Attn: H. G. Parris
Manager of Power
500A Chestnut Street Tower II
Chattanooga, TN 37401

Gentlemen:

The enclosed Bulletin 80-07 is forwarded to you for information.
No written response is required. If you desire additional information
regarding this matter, please contact this office.

Sincerely,

★ James P. O'Reilly
Director

Enclosures:

1. IE Bulletin 80-07
2. List of IE Bulletins
Recently Issued

80041109017

APR 4 1980

Tennessee Valley Authority

-2-

cc w/encl:

R. T. Hathcote, Project Manager
Post Office Box 2000
Hartsville, Tennessee 37074

J. F. Cox
400 Commerce Street
W10C131 C-K
Knoxville, Tennessee 37902

J. E. Wills, Project Engineer
400 Chestnut Street Tower II
Chattanooga, Tennessee 37401

H. N. Culver
249-A HBB
400 Commerce Avenue
Knoxville, Tennessee 37902

UNITED STATES
NUCLEAR REGULATORY COMMISSION
OFFICE OF INSPECTION AND ENFORCEMENT
WASHINGTON, D.C. 20555

SSINS No.: 6820
Accession No.:
8002280648

IE Bulletin No. 80-07
Date: April 4, 1980
Page 1 of 4

BWR JET PUMP ASSEMBLY FAILURE

Description of Circumstances:

On February 2, 1980, Commonwealth Edison Company (CECo) reported that a jet pump failed in Dresden Unit 3 while operating at about 67 percent of full power in a coastdown mode to a refueling shutdown. Observed changes in plant parameters during the event indicated an individual jet pump failure had occurred. In accordance with T.S., an orderly plant shutdown was begun to bring the unit to cold shutdown within 24 hours.

The plant parameter changes reported by the licensee were (1) generator electrical output decreased from 539 to 511 MW electrical, (2) core thermal power decreased as indicated by decreased APRM readings and steam flow to the turbine, (3) indicated total core flow increased from 97.6 to 104.7×10^6 lb./hr., (4) core plate differential pressure decreased from 16.1 to 13.8 psid., and (5) B recirculation loop flow increased from 49 to 54×10^3 gpm while A recirculation loop flow remained at 49×10^3 gpm. These changes were readily observed by the operator in the control room and it was postulated that a jet pump had failed. Individual jet pump readings were taken, the jet pump operability surveillance was performed, and an apparent failure of jet pump No. 13 was determined.

Following vessel head removal and defueling, TV camera and visual inspections of the jet pumps and vessel annulus revealed the hold-down beam assembly of the suspect jet pump had broken across its ligament sections at the mean diameter of the bolt thread area. Failure of the beam assembly resulted in pump decoupling at the diffuser connection. Subsequent insitu ultrasonic examination of all other jet pump hold-down beams, using a special UT technique developed by General Electric (GE), revealed ultrasonic indications of cracking at the same location in 6 of the remaining 19 beams examined. Initial estimates of crack depth ranged from 6 to 20 mils. A sketch of the typical jet pump assembly is shown in Figures 1 and 2.

On March 15-16, 1980, insitu ultrasonic examination of jet pump hold-down beam assemblies at Quadra (during refueling). One beam was found to contain a crack in excess of 100 mils depth in the same location as Dresden.

On March 28, 1980, Boston Edison reported that a crack was revealed in three (3) hold-down beams in Unit 1.

DUPLICATE DOCUMENT

Entire document previously
entered into system under:

ANO 8002280648

No. of pages: 7