

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | A R A N 0 2 | 0 0 - 0 0 0 0 0 0 - 0 0 | 4 1 1 1 1 | 5

CON'T REPORT SOURCE L 0 5 0 0 0 3 6 8 | 0 3 1 6 8 0 | 0 4 1 5 8 0

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
02 | During Mode 3 operation, it was discovered that the "A" Steam Generator
03 | pressure indicator, 2 PI-1041-4N, on Channel "D" PPS failed high. The
04 | low pressure & high SG differential pressure trips were bypassed per
05 | T.S. Table 3.3-3 Action #9 for ESFAS (MSIS & EFAS). The remaining
06 | indicators remained operable. This occurrence is similar to LER
07 | 50-368/79-038. Reportable per T.S.6.9.1.9.b.

09 | SYSTEM CODE I I A | CAUSE CODE E | CAUSE SUBCODE E | COMPONENT CODE I N S T R U | COMP SUBCODE I | VALVE SUBCODE Z
17 | LER/NO REPORT NUMBER 8 | 0 | SEQUENTIAL REPORT NO. 0 1 1 7 | OCCURRENCE CODE 0 3 | REPORT TYPE L | REVISION NO. 0
18 | ACTION TAKEN A | FUTURE ACTION Z | EFFECT ON PLANT Z | SHUTDOWN METHOD Z | HOURS 0 0 0 0 | ATTACHMENT SUBMITTED N | NPRD-4 FORM SUB N | PRIME COMP SUPPLIER N | COMPONENT MANUFACTURER R 3 6 9

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
10 | The electronic output of the pressure transmitter failed high. The
11 | affected electronic cards were replaced and the transmitter recalibrated.
12 | Previous failure analysis revealed no particular failure mode. Similar
13 | instrumentation have exhibited no failures. Channel "D" PPS was declared
14 | operable after meeting T.S. requirements.

15 | FACILITY STATUS B | % POWER 0 0 0 0 | OTHER STATUS NA | METHOD OF DISCOVERY LA | DISCOVERY DESCRIPTION NA
16 | ACTIVITY CONTENT Z | RELEASED OF RELEASE Z | AMOUNT OF ACTIVITY NA | LOCATION OF RELEASE NA
17 | PERSONNEL EXPOSURES NUMBER 0 0 0 | TYPE 0 | DESCRIPTION Z | NA
18 | PERSONNEL INJURIES NUMBER 0 0 0 | DESCRIPTION NA
19 | LOSS OF OR DAMAGE TO FACILITY TYPE Z | DESCRIPTION NA
20 | PUBLICITY ISSUED N | DESCRIPTION NA

NAME OF PREPARER Chris N. Shively PHONE: 501/968-2519