

LICENSEE EVENT REPORT

CONTROL BLOCK: \_\_\_\_\_ (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 N E C P R 1 2 0 0 - 0 0 0 0 - 0 0 0 3 4 1 1 1 1 4 5  
7 8 9 14 15 25 26 30 37 38 58

CON'T  
0 1 REPORT SOURCE L 6 0 5 0 0 0 2 9 8 7 0 3 1 0 8 0 8 0 3 2 5 8 0 9  
7 8 60 61 68 69 74 75 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 During surveillance testing of the Standby Liquid Control (SLC) pumps, SLC Pump "1B"  
0 3 would pump 36.5 gpm at 1215 psig. Tech. Spec. Section 4.4.A.2.b requires the SLC  
0 4 System to provide 38.2 gpm at 1215 psig from each pump. The redundant pump, SLC Pump  
0 5 "1A", was tested for proper capacity and was operable. At the time of this occur-  
0 6 rence the SLC System was not required to be operable by the Tech. Specs. There were  
0 7 no significant occurrences as a result of this event and there were no adverse  
0 8 effects to public health and safety.  
7 8 9 80

0 9 R B 11 E 12 F 13 P U M P X X 14 E 15 Z 16  
7 8 9 10 11 12 13 14 15 16 17 18 19 20

17 LER-RO REPORT NUMBER 8 0 21 22  
EVENT YEAR 8 0 21 22  
SEQUENTIAL REPORT NO. 0 0 7 24 26  
OCCURRENCE CODE 0 3 28 29  
REPORT TYPE L 30 31  
REVISION NO. 0 32

ACTION TAKEN B 18 Z 19 Z 20 Z 21 0 0 0 0 22 ATTACHMENT SUBMITTED N 23 NPRD-4 FORM SUB. 24 PRIME COMP SUPPLIER N 25 COMPONENT MANUFACTURER U 0 5 5 26  
33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 SLC Pump "1B" is a Union Pump Type TD-60 TRIPLEX. Inspection revealed pitting and  
1 1 wear of the internal suction and discharge valves of the pump. This allowed back  
1 2 leakage through the pump suction valve thereby reducing pump capacity. The valve  
1 3 seating surfaces were machined as per pump instruction manual and reinstalled in  
1 4 the pump and the surveillance test was successfully rerun.  
7 8 9 80

1 5 FACILITY STATUS H 28 POWER 0 0 0 29 OTHER STATUS N/A 30 METHOD OF DISCOVERY B 31 DISCOVERY DESCRIPTION Surveillance Procedure 32  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

1 6 RELEASED OF RELEASE Z 33 Z 34 AMOUNT OF ACTIVITY N/A 35 LOCATION OF RELEASE N/A 36  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

1 7 PERSONNEL EXPOSURES NUMBER 0 0 0 37 TYPE Z 38 DESCRIPTION N/A 39  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

1 8 PERSONNEL INJURIES NUMBER 0 0 0 40 DESCRIPTION N/A 41  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

1 9 LOSS OF OIL DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION N/A 43  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

2 0 PUBLICITY ISSUED N 44 DESCRIPTION N/A 45  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50