

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 N E C P R 1 0 0 - 0 0 0 0 - 0 0 0 4 1 1 1 1 4 5
7 8 9 14 15 25 26 30 37 CAT 38

CON'T
0 1 REPORT SOURCE L 6 0 5 0 0 0 2 9 8 7 0 3 1 0 8 0 8 0 3 2 5 8 0 9
7 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

0 2 During surveillance testing of the Standby Liquid Control (SLC) pumps, SLC Pump "1B"
0 3 would pump 36.5 gpm at 1215 psig. Tech. Spec. Section 4.4.A.2.b requires the SLC
0 4 System to provide 38.2 gpm at 1215 psig from each pump. The redundant pump, SLC Pump
0 5 "1A", was tested for proper capacity and was operable. At the time of this occur-
0 6 rence the SLC System was not required to be operable by the Tech. Specs. There were
0 7 no significant occurrences as a result of this event and there were no adverse
0 8 affects to public health and safety.
7 8 9 80

0 9 SYSTEM CODE R B 11 CAUSE CODE E 12 CAUSE SUBCODE F 13 COMPONENT CODE P U M P X X 14 COMP SUBCODE E 15 VALVE SUBCODE Z 16
7 8 9 10 11 12 13 14 15 16 17 18 19 20

17 LER-RO REPORT NUMBER 8 0 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47
ACTION FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

1 0 SLC Pump "1B" is a Union Pump Type TD-60 TRIPLEX. Inspection revealed pitting and
1 1 wear of the internal suction and discharge valves of the pump. This allowed back
1 2 leakage through the pump suction valve thereby reducing pump capacity. The valve
1 3 seating surfaces were machined as per pump instruction manual and reinstalled in
1 4 the pump and the surveillance test was successfully rerun.
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

1 5 FACILITY STATUS H 28 POWER 0 0 0 29 OTHER STATUS N/A 30 METHOD OF DISCOVERY B 31 DISCOVERY DESCRIPTION Surveillance Procedure 32
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

1 6 RELEASED OF RELEASE Z 33 34 AMOUNT OF ACTIVITY N/A 35 LOCATION OF RELEASE N/A 36
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

1 7 PERSONNEL EXPOSURES NUMBER 0 37 TYPE Z 38 DESCRIPTION N/A 39
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

1 8 PERSONNEL INJURIES NUMBER 0 40 DESCRIPTION N/A 41
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

1 9 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION N/A 43
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

2 0 PUBLICITY ISSUED N 44 DESCRIPTION N/A 45
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

NRC USE ONLY
68 69 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

NAME OF PREPARER P. L. BallingerPHONE 402-825-38118004280579