8004290447 UNIE: UPDALE REPURT: PKEVIUUS KEPUKI UJ-U/-0U (7.77) LICENSEE EVENT REPORT (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)  $(\mathbf{1})$ CONTROL BLOCK: 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 1 5 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 M D C C N 12 0 1 LICENSEE CODE CON'T L 6 [0] 5 ] 0 ] 0 ] 3 ] 1 ] 7 0 [0] 2 ] 0 ] 8 ] 8 ] 0 8 [0] 4 ] 2 ] 5 ] 8 ] 0 9REPORT 0 1 SOURCE DOCKET NUMBER EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10) At 2040 with the reactor coolant system at 130 degrees and 250 psia 0 2 shutdown cooling (SDC) suction header relief (SI-468-RV setpoint 315 psig) 0 3 | lifted and failed to reset (T.S. 6.9.1.9.d). Shutdown cooling was stopped 4 0 and isolated from the RCS at 2042. #11B and #'2B reactor coolant pumps 0 5 (RCP) and both steam generators remained operational during the event 0 15 #11B RCP was run for 30 seconds at 2139 per T.S. 3.4.1. The valve was shut 0 7 and SDC restarted at 2215. This is not a repetitive occurrence. 0 8 COMP CODE CAUSE CAUSE SUBCODE COMPONENT CODE SUBCODE P (15 IV IE X BI (16 D 1 (12) Z 13 I FIGI A 0.9 REVISION OCCURRENCE REPORT SEQUENTIAL REPORT NO. LER RO EVENT YEAR CODE TYPE NO. XI 13 1 8 1111 0 (17 10 0 31 NUMBER 32 30 COMPONENT SUBMITTED PRIME COMP. NPRD-4 SHUTDOWN EFFECT TAKEN ACTION HOURS 22 FORM SUB. SUPPLIER Y 24 17 11 10 OL 23 Z (25 Y (18) G 21 0 0 0 E (19) CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27 the improper relief pressure following a 11-SI-468-RV was left set at 1 0 surveillance test due to a procedural error. This resulted in the valve llifting and not reseating during the pump venting. The valve has been 1 2 reset, and setpoint control procedures have been revised to prevent recurrence of this kind of problem. 4 80 METHOD OF FACILITY DISCOVERY DESCRIPTION (32) (30) OTHER STATUS % POWER (31) Operator Observat 0 0 29 A D (28) 5 30 4.4 ACTIVITY CONTENT LOCATION OF RELEASE (36) (35 AMOUNT OF ACTIVITY OF RELEASE RELEASED Z 33 Z 34 NA NA 6 80 45 PERSONNEL EXPOSURES DESCRIPTION (39) NUMBER TYPE 0101037Z38 NA 80 PERSONNEL INJURIES DESCRIPTION (41) NUMBER 0 0 0 0 NA 12 80 LOSS OF OR DAMAGE TO FACILITY (43 DESCRIPTION Z (42) NA 9 80 NRC USE ONLY PUBLICITY DESCRIPTION (45) N 44 111 11111 NA 2 | 0 69 80.5 68 PHONE (301)269-4742/4816 S. M. Davis/D. E. Huseby NAME OF PREPARER -

FULLOW-UP	
LER NO.	80-11
DOCKET NO.	50-317
EVENT DATE	02/08/80
REPORT DATE	04/25/80
ATTACHMENT	

## EVENT DESCRIPTION AND PROBABLE CONSEQUENCES:

At 2040 with shutdown cooling in operation while conducting reactor coolant pump venting operations (#11B and #12B reactor coolant pumps were vented and operational) shutdown cooling suction header relief valve (SI-468-RV, setpoint 315 + 8 psig) lifted and failed to fully reseat (T.S. 6.9.1.9.d). The reactor coolant system was at 1300F and 250 psia with a bubble in the pressurizer. When the relief valve opened pressurizer level decreased from 140 to 90 inches (approximately 1200 gallons of reactor coolant). The reactor coolant was discharged to the five foot elevation of the Auxiliary Building. The Auxiliary Building was immediately vacated as a precautionary measure. Airborne activity did not increase. The shutdown cooling system was stopped and isolated from the reactor coolant system at 2042. While the shutdown cooling system was isolated, #11B reactor coolant pump was run for 30 seconds at 2138 to satisfy T.S. 3.4.1. The relief valve was shut by installing a gagging device. The shutdown cooling system was returned to service at 2215. Access was restored to all areas of the Auxiliary Building at 0015 on 2/9/80. This is not a repetitive occurrence.

## CAUSE DESCRIPTION AND CORRECTIVE ACTIONS:

The setpoint of this relief valve was changed from 285 psig to 315 psig on 1/24/78. Subsequently, this valve was tested on 3/20/79 using a procedure which had not been changed to reflect the new setpoint. The valve was left set at 285 psig following this testing. The pump venting on 2/8/80 caused pressure spike which caused the relief valve to open. The valve was not able to reseat since system pressure did not decrease below its blowdown setting. This valve was gagged and later was removed, reset to 315 psig, and returned to service. The test procedure referred to above was revised on 10/10/79 to reflect the 315 psig setpoint for RV-468. The setpoint control procedure has been revised to ensure that a copy of all setpoint changes are routed to the surveillance test coordinators so the test procedures can be updated in a timely manner.