

482

CONTROL BLOCK:

--	--	--	--	--	--

 (1)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	N	Y	J	A	F	I	2	0	0	-	0	0	0	0	-	0	0	0	3	4							4			5		
7	8	9						14						25						30						57						68	
		LICENSEE CODE						LICENSE NUMBER						LICENSE TYPE						CAT													

CON'T

REPORT SOURCE L 6 0 5 0 0 0 3 3 3 7 0 3 2 7 8 0 8 0 4 2 5 8 0 9

60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0	2	Visual inspection of more than 6000 electrical fire seals required by TS
---	---	--

03 | 4.12.F revealed 350 seals missing or requiring resealing. No significant

04 | hazard existed. See attachment for details.

05 _____

0	6
---	---

0	7	
---	---	--

02 _____

7 8 9

0 9

SYSTEM CODE

A B (11)

CAUSE CODE

A (12)

CAUSE SUBCODE

E (13)

COMPONENT CODE

Z Z Z Z Z Z (14)

COMP SUBCODE

Z (15)

VALVE SUBCODE

Z (16)

LER NO REPORT NUMBER		EVENT YEAR		REPORT NO.		CODE		TYPE		NO.	
17		80		030		03		L		0	
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED	
X		Z		Z		Z		0000		Y	
18		19		20		21		22		23	
23		24		25		26		27		28	
29		30		31		32		33		34	
35		36		37		38		39		40	
41		42		43		44		45		46	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10	Initial installation missing in most cases. Fire watch was stationed until
----	--

11 | new seals were installed. No additional action required. See attachment

1 2 | for details.

1	3
---	---

1	4	
---	---	--

7 8 9
FACILITY STATUS % POWER OTHER STATUS (30) METHOD OF DISCOVERY DISCOVERY DESCRIPTION (32)

1 5 E (28) 0 7 9 (29) NA B (31) Surveillance Test

2 3 4 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

ACTIVITY CONTENT
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)

1 6 2 9 3 34 10 11 NA 44 45 NA 46

PERSONNEL EXPOSURES

NUMBER		TYPE	DESCRIPTION
1	7	000	(37) Z (38) NA (39)

PERSONNEL INJURIES	
NUMBER	DESCRIPTION
00040	NA

1 9		Z		42		43	
TYPE		DESCRIPTION					
				NA			

2 0 N 44 NA

NRC USE ONLY

POWER AUTHORITY OF THE STATE OF NEW YORK
JAMES A. FITZPATRICK NUCLEAR POWER PLANT

DOCKET NO. 50-333

ATTACHMENT TO LER 80-030/03L-0

Page 1 of 1

During normal operation while conducting operations surveillance test F-ST-76L, titled "Electrical Fire Barrier Penetration Seals Visual Inspection," to satisfy the requirements of Technical Specifications Paragraph 4.12.F, 350 fire barrier penetration seals were found to be either missing or requiring resealing. The actual inspection of the more than 6000 penetrations and corrective action extended over a period of several weeks. In each case, as the need for resealing of a penetration was identified, the personnel performing the inspection acted as the fire watch required by Technical Specifications, until the corrective action was complete. The event did not represent a significant hazard to the public health and safety.

A review of documentation related to the requirements for sealing of electrical penetrations indicates that sealing was not required by the NRC at the time the operating license was issued. Subsequent to the issue of the operating license, and following the 1975 fire at the Browns Ferry Plant, a procedure for sealing penetrations was developed and implemented. It is believed that during this post-construction installation, the above noted missing seals were not properly installed. In most cases the missing seals were not located directly at the fire barrier (wall or floor) but were located a number of feet from the penetration at the end of an electrical conduit which penetrates the fire barrier and travels some distance beyond to a termination adjacent to a cable tray. This physical separation probably resulted in the installation error. Since the inspection is now complete and the seals installed, no additional corrective action is required.