

LICENSEE EVENT REPORT

8004290 288 EXHIBIT A

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | 25 | 26 | 27 | 28 | 29 | 30 | 31 | 32 | 33 | 34 | 35 | 36 | 37 | 38 | 39 | 40 | 41 | 42 | 43 | 44 | 45 | 46 | 47 | 48 | 49 | 50 | 51 | 52 | 53 | 54 | 55 | 56 | 57 | 58 | 59 | 60 | 61 | 62 | 63 | 64 | 65 | 66 | 67 | 68 | 69 | 70 | 71 | 72 | 73 | 74 | 75 | 76 | 77 | 78 | 79 | 80 | 81 | 82 | 83 | 84 | 85 | 86 | 87 | 88 | 89 | 90 | 91 | 92 | 93 | 94 | 95 | 96 | 97 | 98 | 99 | 100

01 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | 25 | 26 | 27 | 28 | 29 | 30 | 31 | 32 | 33 | 34 | 35 | 36 | 37 | 38 | 39 | 40 | 41 | 42 | 43 | 44 | 45 | 46 | 47 | 48 | 49 | 50 | 51 | 52 | 53 | 54 | 55 | 56 | 57 | 58 | 59 | 60 | 61 | 62 | 63 | 64 | 65 | 66 | 67 | 68 | 69 | 70 | 71 | 72 | 73 | 74 | 75 | 76 | 77 | 78 | 79 | 80 | 81 | 82 | 83 | 84 | 85 | 86 | 87 | 88 | 89 | 90 | 91 | 92 | 93 | 94 | 95 | 96 | 97 | 98 | 99 | 100

012 | At 1145 it was discovered that an inadvertent actuation of the Fire Service De-luge System resulted in damage to Auxiliary Building Ventilation Exhaust Filter AHFL-2A in excess of two-thousand (\$2,000) dollars. This created an event reportable under 10 CFR 20.403.b(4). No risk to the health or safety of plant or public. Auxiliary Building ventilation was shifted to AHFL-2B at 1300. This is the first occurrence of this type reported.

019 | SYSTEM CODE: A A | CAUSE CODE: A | CAUSE SUBCODE: A | COMPONENT CODE: X X X X X X | COMP SUBCODE: Z | VALVE SUBCODE: Z

17 | LER NO REPORT NUMBER: 80 | EVENT YEAR: 80 | SEQUENTIAL REPORT NO.: 016 | OCCURRENCE CODE: 01 | REPORT TYPE: T | REVISION NO.: 0

ACTION TAKEN: C | FUTURE ACTION: H | EFFECT ON PLANT: Z | SHUTDOWN METHOD: Z | HOURS: 0000 | ATTACHMENT SUBMITTED: Y | NRC-4 FORM 503: N | PRIME COMP SUPPLIER: A | COMPONENT MANUFACTURER: N 2 3 10

110 | The cause of this event is attributed to personnel error. The inadvertent actua-tion occurred while attempting to reset a fire service panel alarm. AHFL-2A media was replaced on 2 April 1980. Post replacement testing is scheduled and will be completed prior to returning AHFL-2A to service.

115 | FACILITY STATUS: G | POWER: 000 | OTHER STATUS: NA | METHOD OF DISCOVERY: A | DISCOVERY DESCRIPTION: Operator observation

116 | ACTIVITY CONTENT RELEASED OR RELEASE: Z | AMOUNT OF ACTIVITY: NA | LOCATION OF RELEASE: NA

117 | PERSONNEL EXPOSURES NUMBER: 0 | TYPE: 0 | DESCRIPTION: Z | NA

118 | PERSONNEL INJURIES NUMBER: 0 | DESCRIPTION: d | NA

119 | LOSS OF OR DAMAGE TO FACILITY TYPE: Z | DESCRIPTION: NA

120 | PUBLICITY: N | NA

Name of preparer: K. F. Lancaster PHONE (904) 795-6486

SUPPLEMENTARY INFORMATION

Report No.: 50-302/80-016/01T-0
Facility: Crystal River Unit #3
Report Date: 8 April 1980
Occurrence Date: 1 April 1980
Identification of Occurrence:

Damage to Auxiliary Building Ventilation Exhaust Filter in excess of two-thousand (\$2,000) dollars. This event is reportable under 10 CFR 20.403.b(4).

Conditions Prior to Occurrence:

Mode 5, cold shutdown.

Description of Occurrence:

At 1145 it was discovered that damage to Auxiliary Building Ventilation Exhaust Filter AHFL-2A had occurred as a result of an actuation of the Fire Service Deluge System. Estimated cost of filter replacement is two-thousand seven hundred fifty dollars (\$2,750). Further investigation revealed that the deluge trip mechanism was actuated as a result of a water hammer in the system caused by the inadvertent initiation of the Fire Service Water Curtain System while attempting to reset a fire service panel alarm.

Designation of Apparent Cause:

The cause of this event is attributed to personnel error.

Analysis of Occurrence:

No threat to the health and safety of the plant staff or public. Auxiliary Building exhaust ventilation was shifted to AHFL-2B at 1300. Samples of water washed through the filters into the Auxiliary Building drain system revealed concentrations of activity less than the limits imposed by 10 CFR 20.

Corrective Action:

A review of this event has been conducted with the responsible section to prevent recurrence. In addition, protective covers will be installed over the Fire Service System actuation push-buttons on the Fire Service System alarm panel.

Failure Data:

This is the first occurrence of this type reported.

/rc