

## LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: 1 1 1 1 1 1 1 ①

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1	T	N	S	N	P	1	0 0	-	0	0 0	0	0	-	0	0	③	4	1	1	1	1	④	1	⑤
-----	---	---	---	---	---	---	-----	---	---	-----	---	---	---	---	---	---	---	---	---	---	---	---	---	---

7 8 9      14 15      19 20      24 25      29 30      34 35      39 40      44 45      49 50

LICENEE CODE      LICENCE NUMBER      LICENSE TYPE      CAT 19

CONT

0 1	REPORT SOURCE	L	G	0 5	1	0	0	3	2	1	7	0	3	3	1	1	8	0	②	0 1	4	2	5	8	0	③
-----	---------------	---	---	-----	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	-----	---	---	---	---	---	---

7 8      60      61      62      63      64      65      66      67      68      69      70      71      72      73      74      75      76      77      78      79      80      81      82      83

REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES ⑩  
Flow switches on radiation monitors ORM-90-212 (turbine bldg. sump)

0 3      effluent) - and RM-90-122 (rad waste liq. effluent) were found inoperable  
0 4      when a preventive maintenance check was performed. The switches provide  
0 5      low flow alarm to the operator. LCO 3.3.3.9 is applicable. There was no  
0 6      danger to the health and safety of the public.

0 7      [REDACTED]

0 8      [REDACTED]

7 8 9	SYSTEM CODE	CAUSE CODE	CAUSE SUBCODE	COMPONENT CODE	COPM. SUBCODE	VALVE SUBCODE	REVISION NO.
0 9	M C ⑪	B ⑫	A ⑬	I N S T R U ⑭	S ⑮	⑯	⑰
7 8	9 10	11	12	13	14	15	16
17	LER PO REPORT NUMBER	EVENT YEAR	SEQUENTIAL REPORTING NO.	OCCURRENCE CODE	REPORT TYPE	VALVE SUBCODE	REVISION NO.
	21	8 0	0 2 4	0 1 3	L	⑯	⑰
	22	23	24	25	26	27	28
	29	30	31	32	33	34	35
	36	37	38	39	40	41	42
	43	44	45	46	47	48	49
	49	50	51	52	53	54	55
	56	57	58	59	60	61	62
	63	64	65	66	67	68	69
	70	71	72	73	74	75	76
	77	78	79	80	81	82	83
	84	85	86	87	88	89	90
	91	92	93	94	95	96	97
	98	99	100	101	102	103	104

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS ②

1 0      The flow switches became inoperable when small particulate matter is in  
1 1      the liquid being monitored. A design change request has been initiated.  
1 2      A preventive maintenance program on a weekly schedule has been initiated  
1 3      to verify cleanliness and operability.

7 8 9	FACILITY STATUS	% POWER	OTHER STATUS	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION
1 5	H ⑪	0 1 0 1 0 ⑫	N/A	B ⑬	Switch failed when flow removed
7 8	9 10	10 11	12 13	44 45	46 47
16	Z ⑭	Z ⑮	Z ⑯	N/A	LOCATION OF RELEASE
7 8 9	10 11	12 13	14 15	44 45	46 47
17	0 1 0 1 0 ⑪	Z ⑫	Z ⑬	N/A	N/A
7 8 9	10 11	12 13	14 15	44 45	46 47
18	0 1 0 1 0 ⑪	Z ⑫	Z ⑬	N/A	N/A
7 8 9	10 11	12 13	14 15	44 45	46 47
19	Z ⑪	Z ⑫	Z ⑬	N/A	N/A
7 8 9	10 11	12 13	14 15	44 45	46 47
20	N ⑪	N ⑫	N ⑬	N/A	N/A
7 8 9	10 11	12 13	14 15	44 45	46 47

7 8 9	ACTIVITY CONTENT	RELEASED. OF RELEASE	AMOUNT OF ACTIVITY	DISCOVERY DESCRIPTION
16	Z ⑭	Z ⑮	Z ⑯	N/A
7 8 9	10 11	12 13	14 15	44 45
17	0 1 0 1 0 ⑪	Z ⑫	Z ⑬	N/A
7 8 9	10 11	12 13	14 15	44 45

7 8 9	PERSONNEL EXPOSURES NUMBER	TYPE	DESCRIPTION
17	0 1 0 1 0 ⑪	Z ⑫	Z ⑬
7 8 9	10 11	12 13	14 15
18	0 1 0 1 0 ⑪	Z ⑫	Z ⑬
7 8 9	10 11	12 13	14 15

7 8 9	PERSONNEL INJURIES NUMBER	DESCRIPTION
17	0 1 0 1 0 ⑪	Z ⑫
7 8 9	10 11	12 13
18	0 1 0 1 0 ⑪	Z ⑫
7 8 9	10 11	12 13

7 8 9	LOSS OF OR DAMAGE TO FACILITY TYPE	DESCRIPTION
17	Z ⑪	Z ⑫
7 8 9	10 11	12 13
18	Z ⑪	Z ⑫
7 8 9	10 11	12 13

7 8 9	PUBLICITY ISSUE DESCRIPTION
20	N ⑪
7 8 9	10 11

NRC USE ONLY

NAME OF PREPARED James M. McGriffPHONE: 615-842-0295