

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ] (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

[01] [T] [N] [S] [N] [P] [1] [2] [0] [0] [0] [0] [0] [0] [0] [0] [0] [0] [0] [0] [0] [0] [3] [4] [1] [1] [1] [1] [4] [ ] [ ] [ ] [ ] [ ] [ ] (5)  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34  
LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT

CONT [01] [L] [C] [0] [5] [0] [0] [0] [3] [2] [7] [7] [0] [4] [1] [5] [8] [0] [8] [0] [4] [2] [8] [8] [0] [9]  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34  
REPORT SOURCE SOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

[02] During final inspection, prior to entering Mode 4, of the Containment  
 [03] Barrier Seal, holes in the flexible material were found. This affects  
 [04] the Containment Barrier Seal to perform its intended function (T.S.  
 [05] LCO 3.6.5.9). Two areas along the wall were missing clamps. Many  
 [06] clamps had loose nuts holding them in place. Some caulking was damaged  
 [07] and leaking. Previous occurrences - none.

[09] [S] [B] [11] [B] [12] [C] [13] [X] [X] [X] [X] [X] [14] [Z] [15] [Z] [16]  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34  
SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP SUBCODE VALVE SUBCODE

[17] [8] [0] [0] [2] [9] [0] [1] [T] [0]  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34  
LER NO REPORT NUMBER EVENT YEAR SEQUENTIAL REPORT NO OCCURRENCE CODE REPORT TYPE REVISION NO

[A] [A] [C] [Z] [0] [0] [0] [0] [Y] [N] [L] [P] [3] [7] [0]  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34  
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NRC-4 FORM SUB PRIME COMP SUPPLIER COMPONENT MANUFACTURER

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

[10] Holes were apparently made with a sharp tool. Unknown cause for missing  
 [11] clamps and loose nuts. Deterioration is not due to aging. All damaged  
 [12] areas will be replaced and new seal spliced at the ends. Missing clamps  
 [13] will be replaced. All nuts will be torqued to specifications. Caulking  
 [14] will be repaired as needed.

[15] [G] [0] [0] [0] [N/A] [B] [31] [During surveillance testing]  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34  
FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION

[16] [Z] [Z] [N/A] [N/A]  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34  
ACTIVITY CONTENT RELEASER OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE

[17] [0] [0] [0] [Z] [N/A]  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34  
PERSONNEL EXPOSURE NUMBER TYPE DESCRIPTION

[18] [0] [0] [0] [N/A]  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34  
TEST FAILURE NUMBER TYPE DESCRIPTION

[19] [Z] [N/A]  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34  
LOG OF OPERATIVE TO FACILITY TYPE DESCRIPTION

[20] [N] [N/A]  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34  
PUBLICITY POWER DESCRIPTION

NAME OF PREPARED: Ronald W. Fortenberry PHONE: 615-842-0295

Tennessee Valley Authority  
Sequoyah Nuclear Plant

LER SUPPLEMENTAL INFORMATION

SQRO-50-327/ 8029      Technical Specification Involved 3.6.5.9

Reported Under Technical Specification 6.9.1.12.i

Date of Occurrence 4/15/80      Time of Occurrence 11:30 EST      Unit 1

Identification and Description of Occurrence:

During final inspection, prior to entering Mode 4, of the Containment Barrier Seal, holes in the flexible material were found which affect the ability of the seal to perform its intended function. Two areas along the wall were missing clamps. Many clamps had loose nuts holding them in place. Some caulking was damaged and leaking.

Conditions Prior to Occurrence:

Unit 1 in Mode 5.

Action specified in the Technical Specification Surveillance Requirements met due to inoperable equipment.

---

N/A

Apparent Cause of Occurrence:

Apparently holes were made with a sharp tool. Unknown cause for missing clamps and loose nuts.

Analysis of Occurrence:

Deterioration is not due to aging.

Corrective Action:

All damaged areas will be replaced and new seal spliced at the ends. Missing clamps will be replaced. All nuts will be torqued to specifications. Caulking will be repaired as needed.

Failure Data:

None