

LICENSEE EVENT REPORT

8005020 325

CONTROL BLOCK: \_\_\_\_\_ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 N E C P R 1 0 0 - 0 0 0 0 - 0 0 0 4 1 1 1 1 5  
7 8 9 14 15 25 26 30 57 CAT 58

CON'T  
0 1 REPORT SOURCE L 0 5 0 0 0 2 9 8 0 2 2 2 8 0 0 3 2 0 8 0 9  
7 8 60 61 68 69 74 75 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 During normal operation, while hydrotesting the recently installed fire sprinkler  
0 3 system in the reactor building, a gasket in a flow switch in a water line failed and  
0 4 water sprayed into the 125 VDC starter racks for RCIC and RHR. One of the auxiliary  
0 5 contacts on the starter for RCIC-MO-131 shorted and the valve automatically opened.  
0 6 The RCIC system was declared inoperable to repair the shorted contact. The redundant  
0 7 emergency core cooling systems were operable, thus this event presented no adverse  
0 8 consequences from the standpoint of public health and safety. 80

0 9 SYSTEM CODE C E 11 CAUSE CODE A 12 CAUSE SUBCODE F 13 COMPONENT CODE C K T B R K 14 COMP. SUBCODE B 15 VALVE SUBCODE Z 16  
7 8 9 10 11 12 13 14 15 16 17 18 19 20  
17 LER/RO REPORT NUMBER 8 0 21 EVENT YEAR 8 0 22 SEQUENTIAL REPORT NO. 0 0 6 24 OCCURRENCE CODE 0 3 28 REPORT TYPE L 30 REVISION NO. 0 32  
ACTION TAKEN B 18 FUTURE ACTION Z 19 EFFECT ON PLANT Z 20 SHUTDOWN METHOD Z 21 HOURS 0 0 0 0 22 ATTACHMENT SUBMITTED N 23 NPRD-4 FORM SUB. 24 PRIME COMP. SUPPLIER A 25 COMPONENT MANUFACTURER G 0 8 0 26  
33 34 35 36 37 38 39 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 A Viking Model C-1 flow indicator gasket failed due to misalignment when the fire  
1 1 sprinklers were hydrotested. As a result, a contact shorted in RCIC starter rack.  
1 2 The gasket and flow switch were reinstalled. The starter racks were cleaned and  
1 3 dried. The contact was replaced and correct operation of RCIC-MO-131 verified. Water-  
1 4 proofing of affected electrical equipment is being investigated. 80

1 5 FACILITY STATUS E 28 % POWER 0 9 3 29 OTHER STATUS NA 30 METHOD OF DISCOVERY B 31 DISCOVERY DESCRIPTION Observation during hydrotest 32  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

1 6 RELEASED OF RELEASE Z 33 AMOUNT OF ACTIVITY NA 35 LOCATION OF RELEASE NA 36  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

1 7 PERSONNEL EXPOSURES NUMBER 0 0 0 37 TYPE Z 38 DESCRIPTION NA 39  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

1 8 PERSONNEL INJURIES NUMBER 0 0 0 40 DESCRIPTION NA 41  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

1 9 LOSS OF OR DAMAGE TO FACILITY TYPE Z 47 DESCRIPTION NA 43  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

2 0 PUBLICITY ISSUED N 44 DESCRIPTION NA 45  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

NAME OF PREPARER Ladislav F. Bednar PHONE: 402-825-3811