

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | A | R | A | N | 0 | 1 | 0 | 0 | - | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | 5

CON'T 01 | REPORT SOURCE | L | 0 | 5 | 0 | 0 | 0 | 3 | 1 | 3 | 7 | 0 | 4 | 0 | 1 | 8 | 0 | 8 | 0 | 4 | 2 | 8 | 8 | 0 | 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
02 | Based on System Reviews per I. E. Bulletin 79-14, the attached list of
03 | hangers were declared inoperable. Immediate actions were to modify and
04 | restore hanger operability within the time frame required by tech. spec.
05 | LER 50-313/79-010 and LER50-313/80-010 were similar occurrences.
06 | Reportable per T.S. 6.12.3.2(b).

09 | SYSTEM CODE | CAUSE CODE | CAUSE SUBCODE | COMPONENT COUF | COMP. SUBCODE | VALVE SUBCODE
X | X | B | A | S | U | I | P | O | I | R | I | T | X | Z
17 | LER-NO REPORT NUMBER | EVENT YEAR | SEQUENTIAL REPORT NO. | OCCURRENCE CODE | REPORT TYPE | REVISION NO.
8 | 10 | 1 | 1 | 1 | 1 | 3 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
10 | The affected hangers were repaired or modified within the time interval
11 | set forth per Tech. Spec. Modification was made through DCP 80-D-10070.
12 | Affected system was service water and main steam.

15 | FACILITY STATUS | % POWER | OTHER STATUS | METHOD OF DISCOVERY | DISCOVERY DESCRIPTION
E | 10 | 0 | 0 | 0 | Z | NOTIFICATION FROM ARCHITECT ENGR.
16 | ACTIVITY CONTENT | AMOUNT OF ACTIVITY | LOCATION OF RELEASE
Z | Z | NA | NA

17 | PERSONNEL EXPOSURES | NUMBER | TYPE | DESCRIPTION
0 | 0 | 0 | Z | NA

18 | PERSONNEL INJURIES | NUMBER | DESCRIPTION
0 | 0 | 0 | NA

19 | LOSS OF OR DAMAGE TO FACILITY | TYPE | DESCRIPTION
Z | NA

20 | PUBLICITY | ISSUED | DESCRIPTION
N | NA

NAME OF PREPARER: Lindsley S. Bramlett PHONE: 501/968-2519