

LICENSEE EVENT REPORT

8 005060 276

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 M D C C N 11 2 0 0 0 - 0 0 0 0 0 - 0 0 0 3 4 1 1 1 1 1 4 5

CON'T REPORT SOURCE L 6 0 5 0 0 0 3 1 1 7 7 0 4 0 1 8 0 8 0 4 3 0 8 0 9

02 At 1030 on April 1, 1980, number 11 control room air conditioning unit was
03 taken out of operation for maintenance. With repairs to the pneumatic control
04 system complete the unit was returned to service at 1515 on April 1, 1980. The
05 redundant air conditioning unit was operable throughout this event. (T.S. 3.7.6.1)
06 This is not a repetitive event.

08

09 SYSTEM CODE SIG 11 CAUSE CODE E 12 CAUSE SUBCODE E 13 COMPONENT CODE INSTRU 14 COMP. SUBCODE T 15 VALVE SUBCODE Z 16

17 LER/RO REPORT NUMBER 8 0 21 22 23 24 26 27 28 29 30 31 32 33 34 35 36 37 40 41 42 43 44 47

10 The required maintenance was calibration of number 11 air conditioning unit's
11 outside air temperature transmitter O-TT-5350. This pneumatic instrument (Johnson
12 Controls, Inc. Model T-5210) had been found to have no gradual output signal change.
13 resulting in the makeup air damper losing its modulating capability. The transmitter
14 was calibrated and placed back in service.

15 FACILITY STATUS E 28 % POWER 1 0 0 0 29 OTHER STATUS NA 30 METHOD OF DISCOVERY A 31 DISCOVERY DESCRIPTION OPERATOR OBSERVATION 32

16 ACTIVITY CONTENT Z 33 RELEASED OF RELEASE Z 34 AMOUNT OF ACTIVITY NA 35 LOCATION OF RELEASE NA 36

17 PERSONNEL EXPOSURES NUMBER 0 0 0 37 TYPE Z 38 DESCRIPTION NA 39

18 PERSONNEL INJURIES NUMBER 0 0 0 40 DESCRIPTION NA 41

19 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION NA 43

20 PUBLICITY ISSUED N 44 DESCRIPTION NA 45

LER NO. 80-18/3L
DOCKET NO. 50-317
EVENT DATE 04/01/80
REPORT DATE 04/30/80
ATTACHMENT

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS: (CONTINUED)

This instrument is presently calibrated under the Preventive Maintenance Program on an annual basis. No further preventive action is deemed necessary at this time.