

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	A	L	B	R	F	1	1	2	0	0	-	0	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4	5
LICENSEE CODE							LICENSE NUMBER															LICENSE TYPE					57 CAT 58		

0	1	L	6	0	5	0	0	0	2	5	9	7	0	4	0	3	8	0	8	0	5	0	1	8	0	9
REPORT SOURCE		DOCKET NUMBER										EVENT DATE					REPORT DATE									

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

During data reduction of scram timing data taken while performing procedure RTI-5, and after exceeding 40% power, it was discovered that the reactor pressure during scram timing tests had been 950 PSIA rather than the required 950 PSIG. There was no danger to health and safety of the public. There are no redundant systems. No previous occurrences. Reference T. S. 4.3.C.1

0	9	R	B	11	A	12	B	13	Z	Z	Z	Z	Z	Z	Z	14	Z	15	Z	16	Z	Z	Z	Z	17	8	0	18	0	2	8	19	0	3	20	L	21	-	22	0	23	-	24	0	2	8	25	-	26	0	3	27	-	28	0	3	29	-	30	-	31	0	32	E	18	G	19	B	20	A	21	0	0	3	0	22	Y	23	N	24	Z	25	Z	9	9	9	26	9	9	9
SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE						COMP SUBCODE		VALVE SUBCODE		SEQUENTIA REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.		ACTION TAKEN		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPR 4 FORM SUB		PRIME COMP SUPPLIER		COMPONENT MANUFACTURER																																																				

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

Personnel failed to properly implement procedural requirements for scram time testing. Immediate action was to reduce load to below 40%, and to repeat scram timing tests for all 185 CRD's. A procedure revision will be made to more clearly delineate requirements and prevent recurrence.

1	5	C	28	0	5	4	29	NA	30	A	31	Test Data Reduction	32
FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION					
ACTIVITY CONTENT		RELEASED OF RELEASE		AMOUNT OF ACTIVITY		LOCATION OF RELEASE							

1	7	0	0	0	37	Z	38	NA	39	0	0	0	40	NA	41
PERSONNEL EXPOSURES		PERSONNEL INJURIES		LOSS OF OR DAMAGE TO FACILITY		PULL CITY									

1	3	Z	42	NA	43	N	44	NA	45	80	81	82	83	84	85	86	87	88	89	90
LOSS OF OR DAMAGE TO FACILITY		PULL CITY		NAME OF PREPARED		ISSUED		NRC USE ONLY												

POOR ORIGINAL

LER SUPPLEMENTAL INFORMATION

BFRO-50- 259 / 8028 Technical Specification Involved 4.3.C.1

Reported Under Technical Specification 6.7.2.b(3)

Date of Occurrence 4/3/80 Time of Occurrence 1300 Unit 1

Identification and Description of Occurrence: During data reduction of scram timing test. Data, taken while performing procedure RTI-5, and after exceeding 40% power it was discovered that the reactor pressure during scram timing tests had been 950 PSIA rather than the required 950 PSIG.

Conditions Prior to Occurrence:

Unit 1 - @~54%
Unit 2 - @~100%
Unit 3 - @~100%

Action specified in the Technical Specification Surveillance Requirements met due to inoperable equipment. Describe.

NA


Apparent Cause of Occurrence: Personnel coordinating scram testing failed to assure that the prerequisite for reactor pressure was met. This led to exceeding 40% PWR without valid scram test data.

Analysis of Occurrence: There was no danger to plant equipment. There was no activity release, no personnel exposure or injury and no danger to health or safety of the public.

Corrective Action: Reduced load and re-performed scram timing test

Failure Data: NA

*Retention: Period - Lifetime; Responsibility - Administrative Supervisor

*Revision: 

POOR ORIGINAL