



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION IV
611 RYAN PLAZA DRIVE, SUITE 1000
ARLINGTON, TEXAS 76012

April 17, 1980

In Reply Refer To:

RIV


Docket No. STN 50-482/IE Bulletin No. 80-09

Kansas Gas & Electric Co.
Attn: Mr. Glenn L. Koester
Vice President-Operations
Post Office Box 208
Wichita, Kansas 67201

Gentlemen:

The enclosed IE Bulletin 80-09 is forwarded to you for action. A written response is required. If you require additional information regarding this matter, please contact this office.

Sincerely,


Karl V. Seyfrid
Director

Enclosures:

1. IE Bulletin No. 80-09
2. List of IE Bulletins
Recently Issued

cc: w/enclosures

Messrs. Nicholas A. Petrick, SNUPPS

D. T. McPhee, Kansas City Power and Light Company
Gerald Charnoff, Shaw, Pittman, Potts & Trowbridge
E. W. Creel, Kansas Gas and Electric Company

UNITED STATES
NUCLEAR REGULATORY COMMISSION
OFFICE OF INSPECTION AND ENFORCEMENT
WASHINGTON, D.C. 20555

SSINS No. 6820
Accession No.:
8002280659

Dupe

IE Bulletin No. 80-09
Date: April 17, 1980
Page 1 of 2

HYDRAMOTOR ACTUATOR DEFICIENCIES

ITT General Controls (ITT-GC) reported to the NRC two (2) problem areas pertaining to their Models AH-90 and NH-90 Series Hydramotor Actuators. The NH 90 designators depicts nuclear class 1E design. Either of the problems reported could affect the operation of safety-related equipment installed in nuclear power facilities:

- A. On December 7, 1979, ITT-GC reported the use of springs having incorrect material installed in Models AH-90 and NH-90 Series Hydramotor Actuators. Instead of 5160 steel, type 1060-1070 steel was used for the No. 1 springs in the actuators. The incorrect spring material does not meet the design strength and upon actuation of greater than 3 inches stroke, a permanent set occurs resulting in a decreased force output of up to 160 lbs., depending on spring combinations used and specific adjustments made to the actuators. About 368 defective springs were used between September 1975 and January 1978.
- B. On February 5, 1980, ITT-GC reported that the ITT-GC "Selection Nomograph" for AH-90 and NH-90 series hydramotor actuators represent the actual spring or hydraulic forces only and do not include the effects of friction or residual hydraulic forces. It has been determined that the actuators can have about 100 lbs. of friction and an additional 40 lbs. of residual hydraulic pressure. Use of these nomographs may result in selection of actuators undersized for the use intended.
- C. Action to be taken by licensees and construction permit holders
 1. Each licensee and each holder of a construction permit should determine whether any safety-related system or component in the facility uses an AH-90 or NH-90 series Hydramotor Actuator manufactured by ITT General Controls. (Note: To assist in this determination a listing of customers that have purchased said actuators and the number of actuators purchased is appended hereto as Attachment No. 1. Since some of the Original Equipment Manufacturers (OEM's) may delete the identity of components used in their product, it may be necessary to consult with the OEM to make the required determination.)
 2. Operating facilities using said actuators in safety-related systems should:

- a. Review system functional testing to determine that equipment using the subject actuators are periodically tested.
 - b. Examine test records to determine whether the functional test results conform to system requirements.
 - c. Verify that ample margin exists with respect to thrust delivered to the load for long term operation considering improper spring material and methods used to select the actuator for a particular application.
 - d. Take any corrective actions required by the results of items a. b. and c. above.
3. Facilities with construction permits using said actuators in safety-related systems should:
- a. Re-evaluate actuator size selection in light of the possibility of using actuators with defective springs or which were sized by the "Selection Nomograph" without accounting for internal friction and hydraulic resistance. Said re-evaluation should assure that the actuators will perform their intended function.
 - b. Modify equipment qualification, preoperational and startup test programs, as necessary, to demonstrate the functional adequacy of the Hydramotor Actuator in light of the aforementioned concerns. Particular attention should be given to the possibility of defective springs taking a permanent set.

Note: ITT General Controls is presently performing actuator testing on units supplied by one of their customers (American Warming & Ventilating Co., Inc.) and revising the methods used to select actuator application.

Each licensee or holder of a construction permit should report to the NRC within 60 days of the results of actions taken, any corrective actions required, and the date when corrective actions were or will be completed. The report should be addressed to:

U. S. Nuclear Regulatory Commission
Director of Reactor Construction Inspection, O.I.E.
Washington, D.C. 20555

A copy should also be furnished to the Regional Office.

Approved by GAO, B180225 (R0072); clearance expires 7/31/80. Approval was given under a blanket clearance specifically for identified generic problems.

Attachment No. 1

<u>Customers</u>	<u>Quantities</u>
ACDC Inc, Cincinnati, OH	27
American Warming & Ventilating Co., Inc. Maumee, OH	145
Copes Vulcan, Inc. Lake City, PA	2
Fisher Controls Co., Inc. Marshalltown, IA	38
Fisher Controls Co., Inc. Corapolis, PA	4
General Signal Corporation West Warwick, RI	2
ITT Hammel-Dahl Warwick, RI	4
Joy Manufacturing New Philadelphia, OH	18
Masoneilan International, Inc. Norwood, MA	10
Pacific Air Products Santa Ana, CA	16
Posi Seal International, Inc. No. Stonington, CT	14
Powers Regulator Co. Portland, OR	1
Powers Regulator Co. Skokie, IL	74
Ruskin Manufacturing Co. Grandview, MO	4
Valtek, Inc. Springville, UT	9
TOTAL	368

RECENTLY ISSUED IE BULLETINS

Bulletin No.	Subject	Date Issued	Issued To
79-01B	Environmental Qualification of Class IE Equipment	2/29/80	All power reactor facilities with an Operating License (OL)
80-05	Vacuum Condition Resulting In Damage To Chemical Volume Control System (CVCS) Holdup Tanks	3/10/80	All PWR power reactor facilities holding Operating Licenses (OLs) and to those with a Construction Permit (CP)
80-06	Engineered Safety Feature (ESF) Reset Controls	3/13/80	All power reactor facilities with an Operating License (OL)
79-03A	Longitudinal Weld Defects In ASME SA-312 Type 304 Stainless Steel Pipe	4/4/80	All power reactor facilities with an Operating License (OL) or Construction Permit (CP)
80-07	BWR Jet Pump Assembly Failure	4/4/80	All GE BWR-3 and BWR-4 facilities with an Operating License (OL)
80-08	Examination of Containment Liner Penetration Welds	4/7/80	All power reactors with a Construction Permit and/or Operating License (OL) no later than 4/7/80

Enclosure