

LICENSEE EVENT REPORT

8005090364₅

CONTROL BLOCK: 1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 G A E I H 2 00 - 000000 - 00 34 11 11 11 4 5
7 8 9 14 15 25 26 30 37 CAT 58
 LICENSEE CODE LICENSE NUMBER LICENSE TYPE

REPORT SOURCE L 05 00 03 66 7 04 15 81 08 04 29 80 9
60 61 68 69 74 75 80
 DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

02 With the reactor in cold shutdown, while checking the wiring changes made
03 during the Emergency Bus Alternate Supply Breaker Modification, the cur-
04 rent transformer terminal block in Junction Box 2JESB02 was found to be
05 burned at the terminal points for the Overcurrent and Differential Relay
06 Circuits that monitor the normal and alternate supplies for Emergency
07 Bus "2F". Neither public health and safety nor continued safe plant
08 operation were effected by this occurrence. 80

SYSTEM CODE E A 11 CAUSE CODE E 12 CAUSE SUBCODE A 13 COMPONENT CODE E L E C T R O N 14 COMP. SUBCODE Z 15 VALVE SUBCODE Z 16
9 10 11 12 13 18 19 20
 LER/RO REPORT NUMBER 80 04 8 03 L 0
21 22 23 24 26 27 28 29 30 31
 EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.
 ACTION TAKEN F 18 FUTURE ACTION Z 19 EFFECT ON PLANT Z 20 SHUTDOWN METHOD Z 21 HOURS 0000 22 ATTACHMENT SUBMITTED Y 23 NPD-4 FORM SUB. N 24 PRIME COMP. SUPPLIER A 25 COMPONENT MANUFACTURER G080 47
33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

10 The overheating was caused by a loose connection in the Overcurrent Relay
11 Circuit at Terminal Block-3. The affected circuits were removed from term-
12 inal block-3 and spliced to prevent a possible failure. Current trans-
13 former terminations in Junction Boxes 2JESB02 and 2JESB10 were then in-
14 spected to ascertain that this was a singular incident. 80

FACILITY STATUS G 28 % POWER 000 29 OTHER STATUS NA 30 METHOD OF DISCOVERY A 31 DISCOVERY DESCRIPTION Maintenance Personnel Observation 32
7 8 9 10 11 12 13 44 45 46

ACTIVITY CONTENT RELEASED Z 33 Z 34 AMOUNT OF ACTIVITY NA 35 LOCATION OF RELEASE NA 36
7 8 9 10 11 44 45 46

PERSONNEL EXPOSURES NUMBER 000 37 TYPE Z 38 DESCRIPTION NA 39
7 8 9 11 12 13

PERSONNEL INJURIES NUMBER 000 40 DESCRIPTION NA 41
7 8 9 11 12 13

LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION NA 43
7 8 9 11 12

PUBLICITY ISSUED N 44 DESCRIPTION NA 45
7 8 9 11 12

NAME OF PREPARER R. T. Nix PHONE: 912-367-7781
7 8 9 10 68 69 80

NAME OF PREPARER R. T. Nix

PHONE: 912-367-7781

NARRATIVE REPORT

Georgia Power Company
Plant E. I. Hatch
Baxley, Georgia 31513

Reportable Occurrence Report No. 50-366/1980-048.

With the reactor in cold shutdown on April 15, 1980, while making a verification of the wiring changes that were made for the Emergency Bus Alternate Supply Breaker Modification, terminal block-3 in Junction Box 2JESB02 was found burned at the termination points for the Overcurrent Relay Circuit, which monitors the normal supply for Emergency Bus "2F" from the 2D Start-up Transformer. Although there was heat damage to this circuit and some heat damage caused to the Differential Relay Circuit, which monitors the alternate supply for Emergency Bus "2F" from the 2C Start-up Transformer, there were no failures as continuity still existed across the terminal block.

The overheating was apparently caused by a loose connection in the Overcurrent Relay Circuit at terminal block-3. The two affected circuits were removed from terminal block-3 and spliced to prevent the possibility of a future failure. An inspection was then made of the current transformer connections in Junction Boxes 2JESB02 and 2JESB10 to ascertain that this was a singular incident.

Neither public health and safety nor continued safe plant operation was affected by this occurrence.