

LICENSEE EVENT REPORT

80050904395

CONTROL BLOCK: _____ 1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | G | A | E | I | H | 2 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | 5
7 8 9 14 15 25 26 57 58
LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT 58

01 | L | 6 | 0 | 5 | 0 | 0 | 0 | 3 | 6 | 6 | 7 | 0 | 4 | 0 | 5 | 8 | 0 | 8 | 0 | 4 | 2 | 9 | 8 | 0 | 9
7 8 60 61 58 59 74 75 80
REPORT SOURCE DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

02 | While performing surveillance procedure HNP-2-3184, Remote Shutdown Panel
03 | Instrument Checks, the torus water level instrument, 2T48-R070, was found
04 | downscale. Investigations revealed that transmitter, 2T48-N070, was in-
05 | advertently installed backwards following calibration on March 11, 1980.
06 | The reactor was in cold shutdown the entire time the transmitter was re-
07 | versed. The instrument is not required in cold shutdown. There was no
08 | effect on public health and safety. This is a non-repetitive event.
7 8 9

09 | SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE
I D 11 A 12 Z 13 Z Z Z Z Z Z 14 Z 15 Z 16
9 10 11 12 13 18 19 20
17 | LER/RO REPORT NUMBER EVENT YEAR SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED PRIME COMP. SUPPLIER COMPONENT MANUFACTURER
8 0 21 22 Z 20 Z 21 0 0 0 0 22 Y 23 Y 24 Z 25 Z 9 9 9 9 26
18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

10 | The cause of the event was attributed to personnel error. The technician
11 | failed to verify the markings of the transmitter with the proper tubing.
12 | The technician was made aware of this mistake and instructed as to the
13 | importance of verifying the proper installation. No generic problems
14 | were revealed during the investigations.
7 8 9

15 | FACILITY STATUS % POWER OTHER STATUS 30 METHOD OF DISCOVERY 32 DISCOVERY DESCRIPTION 32
G 28 0 0 0 0 29 NA B 31 Operator observation
7 8 9 10 12 13 44 45 46 80

16 | ACTIVITY CONTENT RELEASED OF RELEASE 33 AMOUNT OF ACTIVITY 35 LOCATION OF RELEASE 36
Z 33 Z 34 NA NA
7 8 9 10 11 44 45 80

17 | PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39
0 0 0 37 Z 38 NA
7 8 9 10 11 12 13 80

18 | PERSONNEL INJURIES NUMBER DESCRIPTION 41
0 0 0 40 NA
7 8 9 10 11 12 80

19 | LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION 43
Z 42 NA
7 8 9 10 80

20 | PUBLICITY ISSUED DESCRIPTION 45
N 44 NA
7 8 9 10 80

NAME OF PREPARER R. T. Nix

PHONE: 912-367-7781

NARRATIVE REPORT

Georgia Power Company
Plant E. I. Hatch
Baxley, Georgia 31513

Reportable Occurrence Report No. 50-366/1980-047.

On April 5, 1980, while performing routine surveillance procedure HNP-2-3184, Remote Shutdown Panel Instrument Checks, the torus water level indicator, 2T48-R070, was found to be downscale. Investigations revealed the associated transmitter, 2T48-N070, had been installed backwards following calibration on March 11, 1980. The instrument is a Rosemount Model 1151DP transmitter and is constructed to allow the body to be installed either of two ways. The body is plainly marked high side and low side to avoid the type error made here. The instrument installation was corrected and the instrument returned to service. The technician was made aware of his mistake and reminded of the importance of verifying the correct installation.

During the time the transmitter was installed backwards, the reactor remained in cold shutdown, Condition 4. This instrument loop is not required to be operable during Conditions 4 and 5, but it is being reported because it is required operable, therefore reportable, in conditions 1, 2 and 3. The generic review revealed no inherent problems associated with the event. There was no effect on public health and safety. This is a non-repetitive event.