LICENSEE EVENT REPORT 8 0052 00 702

CONTROL BLOCK:             (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
N   C   B   E   P   1   2   0   0   -   0   0   0   0   -   0   0
CON'T SOURCE L 6 0 5 0 - 10 3 2 5 7 0 4 1 7 8 0 8 0 5 1 5 8 0 9
EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)  During normal plant operations the containment atmosphere analyzer 1-CAC-AT-1263
would not remain running after starting. When the start button was released the
analyzer motor stopped. In no way was the health and safety of the public affected
0 5 by this event.
07
Technical Specification 3.3.5.3, 6.9.1.9b
SYSTEM CODE CAUSE CAUSE COMPONENT CODE SUBCODE
17 REPORT   8 0
ACTION FUTURE ON PLANT SHUTDOWN HOURS 22 ATTACHMENT FORM SUB. SUPPLIER MANUFACTURER  E 18 Z 19 Z 20 Z 2
The analyzer motor stop switch was open due to a disconnected wire which de-energized
the motor run relay. The wire connector had a loose retainer screw. The loose wire
was reconnected to the stop switch and the analyzer restarted satisfactorily. Other
connections on this monitor as well as other monitors were checked with all connections
1 4 found satisfactory.
POWER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32  The status 30 METHOD OF DISCOVERY DESCRIPTION 32  A power N/A A A A A A A A A A A A A A A A A A A
ACTIVITY CONTENT RELEASED OF RELEASE  AMOUNT OF ACTIVITY 35  N/A  N/A  N/A  N/A  80
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39  N/A  PERSONNEL INJURIES  N/A  80
NUMBER DESCRIPTION (4) N/A
LOSS OF OR DAMAGE TO FACILITY 43
N/A  N/A  NRC USE ONLY
2 0 N/A DESCRIPTION 43
7 8 9 10 68 69 87.5 NAME OF PREPARER A. C. Tollison, Jr. PHONE: 919-457-9521