



LER SUPPLEMENTAL INFORMATION

BFRO-50- 259 / 8042 Technical Specification Involved 3.5.D.1 & 2

Reported Under Technical Specification 6.7.2.b (2)

Date of Occurrence 5/12/80 Time of Occurrence 1300 Unit 1

Identification and Description of Occurrence:

Core spray system I room cooler failed SI 3.2.4. There was no indication of flow from the south EECW header.

Conditions Prior to Occurrence:

Unit 1 @ 96% steady state power

Unit 2 @ 100% steady state power

Unit 3 @ 100% steady state power

Action specified in the Technical Specification Surveillance Requirements met due to inoperable equipment. Describe.

Ran SI's 4.5.A.1.b & c, 4.5.B.1.b & c, and 4.9.A.1

Apparent Cause of Occurrence:

There was no indication of flow through the check valves on the south EECW header.

Analysis of Occurrence:

There was no danger to the health or safety of the public, no damage to plant or equipment, no release of activity, and no resulting chain of events.

Corrective Action:

The check valves from the south EECW headers were disassembled, inspected, reassembled, and SI 3.2.4 satisfactorily completed.

Failure Data:

NA

\*Retention: Period - Lifetime; Responsibility - Administrative Supervisor

\*Revision: 