

## LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: 1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 ELQR P3 000-000000-00 41111 - - 0  
7 8 9 14 15 25 28 37 40 43 46 49 52

CON'T  
01 L 050-0302 050680 052380  
7 8 9 14 15 25 28 37 40 43 46 49 52

REPORT SOURCE L 050-0302 050680 052380  
92 91 90 89 88 87 86 85 84 83 82 81 80 79 78 77 76 75 74 73 72 71 70 69 68 67 66 65 64 63 62 61 60 59 58 57 56 55 54 53 52 51 50 49 48 47 46 45 44 43 42 41 40 39 38 37 36 35 34 33 32 31 30 29 28 27 26 25 24 23 22 21 20 19 18 17 16 15 14 13 12 11 10 9 8 7 6 5 4 3 2 1

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 13  
02 At 1630 during an inspection of "A" OTSG feedwater swing-disc check valve FWV-45,  
03 it was discovered that the valve hinge pin was missing. The loss of the hinge  
04 pin prevented the valve from closing. This created an event contrary to  
05 Technical Specification 3.6.3.1. There was no effect upon the plant or general  
06 public as a result of this event. This is the second occurrence of this type  
07 reported. (Reference LER 80-17)  
08  
09

09 S D 11 B 12 B 13 V A L V E X 14 C 15 A 16  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

17 80 1 0121 013 L 0  
21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

ACTION TAKEN F 18 Z 19 2 20 Z 21 0000 22 Y 23 N 24 A 25 C 26 Z 27 5 6  
32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27  
10 The cause of this event is attributed to a deficiency occurring during the initial  
11 assembly of the valve by the manufacturer. FWV-45 is being repaired under Modific  
12 tion 80-5-65. In addition, other valves of similar design, supplied by the manu-  
13 facturer will be inspected and repaired as necessary prior to plant startup.  
14  
15 H 23 000 24 NA C 25 Maintenance inspection 26  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

16 Z 33 Z 34 NA 1 NA 29  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

17 000 37 28 NA  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

18 000 40 NA  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

19 Z 42 NA  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

20 N 44 NA  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

Name of preparer: K. F. Lancaster PHONE (904) 795-6486

(SEE ATTACHED SUPPLEMENTARY INFORMATION SHEET)

8006030500

SUPPLEMENTARY INFORMATION

Report No.: 50-302/80-21/03L-0

Facility: Crystal River Unit #3

Report Date: 23 May 1980

Occurrence Date: 5 May 1980

Identification of Occurrence:

Containment isolation valve FWV-45 inoperable contrary to Technical Specification 3.6.3.1.

Conditions Prior to Occurrence:

Mode 6 refueling.

Description of Occurrence:

At 1630 during an inspection of "A" OTSG feedwater swing-disc check valve FWV-45, it was discovered that the valve hinge pin was missing. The loss of the hinge pin prevented the valve from closing. Repair actions were initiated.

Designation of Apparent Cause:

The cause of the event is attributed to a deficiency occurring during the initial assembly of the valve by the manufacturer. It was determined that the set screw that locks the hinge pin in place, was not fully inserted.

Analysis of Occurrence:

There was no effect upon the plant or general public as a result of this event.

Corrective Action:

FWV-45 is being repaired under Modification 80-5-65. In addition, other valves, (of similar design), supplied by the manufacturer will be inspected and repaired as necessary. Those valves which are safety-related and/or non-accessible during power operation will be inspected and repaired if necessary prior to plant startup.

Failure Data:

This is the second occurrence of this type reported. Reference LER 80-17.

/rc