	U. S. NUCLEAR REGULATORY COMMISSION
FORM	LICENSEE EVENT REPORT
;	TROL BLOCK:
1 9	G A E I H 1 200 0 - 10 0 0 - 0 0 3 4 1 1 1 1 1 0 57 CAT 58 5 LICENSEE CODE 14 15 LICENSE NUMBER 57 CAT 58 5
4'T 1 8 E	HEPORT L G 0 5 0 0 0 13 2 1 0 0 5 0 9 8 0 8 0 5 2 9 8 0 0 SOURCE 60 ET DOCKET NUMBER 60 69 EVENT DATE 74 75 REPORT DATE 80
2	During steady state power operation while performing the month of the
[3] L	Pump Operability Test on Plant Service Water Pump 18, 11 was found that
14 1	the maximum attainable flow was 3600 gpm. The pump was declared inoper-
[6] [ative and a limiting condition for operation was established per Tech Specs
1611	3.5.J.2b. There were no effects upon public health and safety. This is
171	a repetitive event as last reported on Reportable Occurrence Report
	No. 50-321/1980-026
10 10 8	SYSTEM CODE SUBCODE CAUSE CODE SUBCODE CAUSE SUBCODE CAUSE SUBCODE COMPONENT CODE SUBCODE COMP. SUBCODE VALVE SUBCODE W A 9 10 IE 12 13 INSTIRUTION 13 11 10 12 13 Image: Street subcode Image: Subcode Image: Street subcode Image: Subcode Image: Street subcode Image: Subcode Image: Street subcode Image: Subcode Image: Subcode Image: Subcode Image: Subcode Image: Subcode Image: Street subcode Image: Subcode Image: Street subcode Image: Subcode Image: Subcode Image: Subcode Image: Subcode Image: Subcode Image: Subcode Image: Subcode Image: Subcode Image: Subcode Image: Subcode Image: Subcode Image: Subcode <td< td=""></td<>
10	$\begin{array}{c ccccccccccccccccccccccccccccccccccc$
11	due to a faulty pressure indicator on the pump discharge. The pump flow
1151	had been throttled to produce the correct head pressure on the faulty
13	gauge. The gauge was repaired and the pump was re-tested with no problems.
1 4 8	9 9 0 Method of Discovery Description (32) 80 9 Status 30 Method of Discovery Description (32) 80 1 E [08] [0] 9 [02] NA B [31] Surveillance 80
	0 10 12 11 44 45 46 ACTIVITY CONTENT 12 11 44 45 46 Inclusted Location of Release AMOUNT OF ACTIVITY 35 Location of Release 36 Inclusted Inclusted NA 44 45 46
1 7 6	PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39) 0 0 0 7 38 NA 9 PERSONNEL INJUNES 10 10 0 0 0 0 7 38 NA 10 NA
1 8	
8	9 11 12 LOSS OF ON DAMAGE TO FACILITY (43) TYPE DESCRIPTION (43)
1 9	A NA BO NRC USE ONLY
2 0	63 63

NARRATIVE REPORT

Georgia Power Comapny Plant E. I. Hatch Baxley, Georgia 31513

Reportable Occurrence Report No. 50-321/1980-048.

During steady state power operation while performing the A.S.M.E. Inservice Pump Operability Test on Plant Service Water Pump 1B, it was found that the maximum attainable flow was 3600 gpm. The pump was declared inoperative and a limiting condition for operation was established per Tech Specs 3.5,J.2b. There were no effects upon public health and safety. This is a repetitive event as last reported on Reportable Occurrence Report No. 50-321/1980-026.

An investigation revealed that the cause of the low flow indication was due to a faulty pressure indicator on the pump discharge. The pump flow had been throttled to produce the correct head pressure on the faulty gauge. The gauge was repaired and the pump was re-tested with no problems.

Nuring the course of this investigation the flowmeter calibration was checked and found acceptable. Also since the flow was unstable during testing the pump was fully disassembled and inspected for wear and foreign objects. This inspection revealed that the pump was in like new condition. The pump was re-assembled and re-tested. During the re-test the defective gauge was found. The in-ability of Plant Service Water Pumps to pass the A.S.M.W. Inservice Inspection Testing is repetitive as last reported on LER 50-321/1980-026. The primary cause of the past failures has been normal pump wear. A program is under way to extend the normal service life of the pumps. This failure was due to a defective pressure gauge on the pump discharge which is located locally. It is only used for proving pump operability and inservice testing. Although pressure gauges fail occasionally, there is no reason to believe this failure is generic.