

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK:

| | | | | | |
|---|---|---|---|---|---|
| 1 | 2 | 3 | 4 | 5 | 6 |
|---|---|---|---|---|---|

 (1)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

| | | | | | | | | | | | | |
|-----|---------------|----|----|----------------|----|----|--------------|----|----|-----|----|---|
| 0 1 | LICENSEE CODE | 14 | 15 | LICENSE NUMBER | 25 | 26 | LICENSE TYPE | 30 | 57 | CAT | 58 | 5 |
|-----|---------------|----|----|----------------|----|----|--------------|----|----|-----|----|---|

CONT

| | | | | | | | | | | | | | |
|-----|---------------|----|----|----|----|----|----|----|----|----|----|----|----|
| 0 1 | REPORT SOURCE | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | 25 |
|-----|---------------|----|----|----|----|----|----|----|----|----|----|----|----|

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 RIA-47, RB particulate and RIA-48 RF iodine monitors signaled a high alarm
 0 3 and the RB normal sump level rate-of-change monitor indicated a 2.8 gpm
 0 4 leak. Unit was shut down and after cooling, it was determined that the
 0 5 packing of 1RC-2 pressurizer spray bypass valve was blown causing the leak
 0 6 which required shutdown within 24 hrs. (T.S. 3.1.6.2). The leak was sub-
 0 7 stantially less than the capacity of 1 HPI pump and was contained by the
 0 8 RB without detrimental effects to public health and safety.

| | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
|---|---|---|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|
| 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | 25 | 26 | 27 | 28 | 29 | 30 | 31 | 32 | 33 | 34 | 35 | 36 | 37 | 38 | 39 | 40 | 41 | 42 | 43 | 44 | 45 | 46 | 47 |
|---|---|---|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|

| | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
|-----|-------------|----|------------|----|---------------|----|----------------|----|---------------|----|---------------|----|--------------|----|----------------------|----|------------|----|-----------------------|----|-----------------|----|-------------|----|----------------------|----|------------------------|----|
| 0 9 | SYSTEM CODE | 11 | CAUSE CODE | 12 | CAUSE SUBCODE | 13 | COMPONENT CODE | 14 | COMP. SUBCODE | 15 | VALVE SUBCODE | 16 | REVISION NO. | 17 | LER/RO REPORT NUMBER | 18 | EVENT YEAR | 19 | SEQUENTIAL REPORT NO. | 20 | OCCURRENCE CODE | 21 | REPORT TYPE | 22 | PRIME COMP. SUPPLIER | 23 | COMPONENT MANUFACTURER | 24 |
|-----|-------------|----|------------|----|---------------|----|----------------|----|---------------|----|---------------|----|--------------|----|----------------------|----|------------|----|-----------------------|----|-----------------|----|-------------|----|----------------------|----|------------------------|----|

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 Valve packing failed releasing RC to the RB atmosphere. The valve was
 1 1 repacked and tested using PT/1/600/10 RCS leakage which yielded an
 1 2 acceptable leak rate.

| | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
|-----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|
| 1 3 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | 25 | 26 | 27 | 28 | 29 | 30 | 31 | 32 | 33 | 34 | 35 | 36 | 37 | 38 | 39 | 40 | 41 | 42 | 43 | 44 | 45 | 46 | 47 |
|-----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|

| | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
|-----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|
| 1 4 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | 25 | 26 | 27 | 28 | 29 | 30 | 31 | 32 | 33 | 34 | 35 | 36 | 37 | 38 | 39 | 40 | 41 | 42 | 43 | 44 | 45 | 46 | 47 |
|-----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|

| | | | | | | | | | | | | | | | | | |
|-----|-----------------|----|---------|---|----|---|----|----|--------------|----|---------------------|----|-----------------------|----|----------------------|----|----|
| 1 5 | FACILITY STATUS | 28 | % POWER | 1 | 10 | 0 | 29 | NA | OTHER STATUS | 30 | METHOD OF DISCOVERY | 31 | DISCOVERY DESCRIPTION | 32 | OPERATOR OBSERVATION | 33 | 80 |
|-----|-----------------|----|---------|---|----|---|----|----|--------------|----|---------------------|----|-----------------------|----|----------------------|----|----|

| | | | | | | | | | | | | | | | | | |
|-----|------------------|----|---------------------|----|---|----|---|----|--------------------|----|----|----|----|----|---------------------|----|----|
| 1 6 | ACTIVITY CONTENT | 30 | RELEASED OR RELEASE | 31 | Z | 32 | Z | 33 | AMOUNT OF ACTIVITY | 34 | 44 | 45 | 46 | 47 | LOCATION OF RELEASE | 35 | 80 |
|-----|------------------|----|---------------------|----|---|----|---|----|--------------------|----|----|----|----|----|---------------------|----|----|

| | | | | | | | | | | | | | | |
|-----|---------------------|----|--------|----|------|----|-------------|----|----|----|----|----|----|----|
| 1 7 | PERSONNEL EXPOSURES | 35 | NUMBER | 36 | TYPE | 37 | DESCRIPTION | 38 | NA | 44 | 45 | 46 | 47 | 80 |
|-----|---------------------|----|--------|----|------|----|-------------|----|----|----|----|----|----|----|

| | | | | | | | | | | | | | | |
|-----|--------------------|----|--------|----|-------------|----|----|----|----|----|----|----|----|----|
| 1 8 | PERSONNEL INJURIES | 39 | NUMBER | 40 | DESCRIPTION | 41 | NA | 42 | 43 | 44 | 45 | 46 | 47 | 80 |
|-----|--------------------|----|--------|----|-------------|----|----|----|----|----|----|----|----|----|

| | | | | | | | | | | | | | |
|-----|-------------------------------|----|------|----|-------------|----|----|----|----|----|----|----|----|
| 1 9 | LOSS OF OR DAMAGE TO FACILITY | 40 | TYPE | 41 | DESCRIPTION | 42 | NA | 43 | 44 | 45 | 46 | 47 | 80 |
|-----|-------------------------------|----|------|----|-------------|----|----|----|----|----|----|----|----|

| | | | | | | | | | | | |
|-----|------------------|----|-------------|----|------------------------------------|----|--------------|----|----|----|----|
| 2 0 | PUBLICITY ISSUED | 44 | DESCRIPTION | 45 | ANNOUNCEMENT OF UNSCHEDULED OUTAGE | 46 | NRC USE ONLY | 47 | 68 | 69 | 80 |
|-----|------------------|----|-------------|----|------------------------------------|----|--------------|----|----|----|----|

NAME OF PREPARED K. R. Wilson

PHONE: (704) 373-8197

7912110 820