



UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
REGION IV  
611 RYAN PLAZA DRIVE, SUITE 1000  
ARLINGTON, TEXAS 76012

PDR  
LPDR  
TIC ✓  
NSIC  
CENTRAL FILES

May 13, 1980

In Reply Refer To:

RIV

Docket Nos. 50-458/IE Circular No. 80-11  
50-459/IE Circular No. 80-11

Gulf States Utilities

Attn: Dr. J. G. Weigand, Vice President  
Operations and Technical Systems

Post Office Box 2951  
Beaumont, Texas 77704

Gentlemen:

The enclosed IE Circular No. 80-11 is forwarded to you for information. No written response is required. Should you have any questions related to your understanding of the recommendations on this matter, please contact this office.

Sincerely,

Karl V. Seyfrit  
Director

Enclosures:

1. IE Circular No. 80-11
2. List of Recently Issued  
IE Circulars

8005280 046 Q

UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
OFFICE OF INSPECTION AND ENFORCEMENT  
WASHINGTON, D.C. 20555

SSINS No.: 6830  
Accession No.:  
8002280662

DUPLICATE

IE Circular No. 80-11  
Date: May 13, 1980  
Page 1 of 1

EMERGENCY DIESEL GENERATOR LUBE OIL COOLER FAILURES

Description of Circumstances:

Within a two week period (August 27 to September 11, 1979), the tube sheets failed in the lube oil coolers of both emergency diesel generators for Arkansas Nuclear One (ANO) Unit No. 1. The introduction of water into the diesel lube oil system resulted in trips of both diesels during surveillance testing. The diesels were not considered capable of sustained operation. These events were previously identified to all operating license and construction permit holders by Information Notice 79-23, Emergency Diesel Generator Lube Oil Cooler on September 25, 1979. The emergency diesel generators involved were manufactured by the Electro-Motive Division (EMD) of the General Motors Corporation and the failures occurred on engines 71-A1-1117 and 71-A1-1130. The failed lube oil coolers were manufactured by the Young Radiator Company.

An analysis of the failed coolers performed by EMD resulted in the conclusion that the failures were caused by severe corrosion of the solder which sealed the tubes to the tube sheets. The corrosion inhibitor in use at ANO was Calgon CS, a borate-nitrite type inhibitor. The manufacturer of this type of inhibitor has recommended the use of hard solder in CS treated systems. EMD does not recommend the use of Calgon CS since the puddle solder used in EMD radiators and oil coolers is considered to be soft solder of a lead-tin composition.

Recommended Action for Licensees' Consideration:

Based on the above, it is recommended that licensees:

1. Verify that the corrosion inhibitor used in cooling water systems of the emergency diesel generators is compatible with all materials wetted by the cooling water and the engine manufacturer's specific recommendations. Also, by means of the engine maintenance history, verify that the system corrosion inhibitor has been properly monitored and maintained at the recommended concentration.
2. If item 1 cannot be successfully performed, the affected components should be inspected in accordance with the manufacturer's recommendations.

No written response to this Circular is required.

If you desire additional information regarding this matter, contact the Director of the appropriate NRC Regional Office.

IE Circular No. 80-11  
May 13, 1980

RECENTLY ISSUED  
IE CIRCULARS

| Circular No. | Subject   | Date Issued | Issued To  |
|--------------|---|-------------|--|
| 80-04        | Securing of Threaded Locking Devices on Safety-Related Equipment      | 3/14/80     | All holders of a power reactor Operating License (OL) or Construction Permit (CP)  |
| 80-05        | Emergency Diesel-Generator Lubricating Oil Addition and Onsite Supply | 4/1/80      | All holders of a power reactor Operating License (OL) or Construction Permit (CP)  |
| 80-06        | Control and Accountability Systems for Implant Therapy Sources        | 4/14/80     | Medical licensees in Categories G and G1   |
| 80-07        | Problems with HPCI Turbine  | 4/3/80      | All holders of a power Reactor Operating Licenses (OL) or Construction Permit (CP) |
| 80-08        | BWR Technical Specification Inconsistency - RPS Response Time         | 4/18/80     | All General Electric BWR's holding a power reactor Operating License (OL)          |
| 80-09        | Problems With Plant Internal Communications Systems                   | 4/28/80     | All holders of a power reactor Operating License (OL) or Construction Permit (CP)  |
| 80-10        | Failure to Maintain Environmental Qualification of Equipment          | 4/29/80     | All holders of Reactor Operating Licenses (OLs) and Construction Permits (CPs)     |

Enclosure