U. S. NUCLEAR REGULATORY COMMISSION NAC FORM 366 (7.77) EXHIB!T A LICENSEE EVENT REPOR PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION (1 CONTA 010101010 01-1 0 F 0 1 CON'T 3|0|2001111171800012 0 21 718 -101 01 REPORT L(6) 0 5 0 1 SOURCE REPORT OATS 000421 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10) it was discovered that the breaker for HPI During normal mode 1 operations, 0 2 isolation valve MUV-25 was inadvertently opened and "red tagged" out of 03 This caused a plant condition contrary to Tech Spec 3.6.3.1. No service. 0 4 safety hazard as redundant HPI subsystem was available and operable. Upon 0 5 discovery, the breaker was immediately closed restoring operability of MUV-0 6 First occurrence of this event. 0 7 08 CO*** CODE CAUSE SUSCODT SUACODE CAUSE COMPONENT CODE SUSCOR B (13) ALIVIEIXICA D | (15 1D 1 (16) II BI V A (12 0 9 REVISION GCC. 335. SEQUENTIAL PORT NO CODE NQ. 13 01 10 16 10 (17) 942091 12 COMPONENT MANUFACTURES SUPPLIER SHUTDER (22) H 10101 a N (24) N WIOI 301 10 Y H Z (25 Z 1 CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) This occurrence was caused by the inadvertent opening of the breaker for 10 A clearance order for clearing DOP-2B had been issued. The breaker MUV-25. 111 cubicle for DOP-2B was adjacent to the breaker cubicle of MUV-25 and the 117 The Clearance Procedure was reviewed with conwrong breaker was cleared. 1 3 Plant personnel have been instructed as to the safety cerned personnel. aspects of this event. 4 ACILIT OT-ERSTATUS (JC) DISCOVERY SCOVERY DESCRIPTION (32) 110 10 (3 Operator observation NA Control Z G 1 1 5 20 13 ACTIVITY CONTENT LOCATION OF RELEASE (15) איזטידבר זר אבדונודא (35 ELEASED NA NA Z 1 6 (33) 80 PERSONNEL E APOSLASS DESCRIPTION (39) NUVBER Z NA 01 aies PERSONNE DISCRIPTION (41 0 NA 60 ST TO FACILITY ONS OF C (1) 11. Z NA 1 1 4 (4.) PLE. 13194 NAC USE ONLY DES:= +1 05 (45 EC N Ga Ŧ NA : 10 904) 795-6486 Cooper AAVE OF PREPARE PHONE (SEE ATTACHED SUPPLEMENTARY INFORMATION SHEET) 8002280 873

.

SUPPLEMENTARY INFORMATION

| 1. sport No.: | | 50 '78-006/03L-0 |
|---------------|------------------|-----------------------|
| 2. | Facility: | Crystal River Unit #1 |
| 3. | Report Date: | 2 February 1978 |
| 4. | Occurrence Date: | 11 January 1978 |

5. Identification of Occurrence:

High pressure injection isolation valve MUV-25 inoperable contrary to Technical Specification 3.6.3.1.

6. Conditions Prior to Occurrence:

Mode 1 operation.

7. Description of Occurrence:



At 2145, it was discovered that Control Center position indication for the HP injection isolation valve MUV-25 was inoperable. An immediate investigation revealed that the breaker for valve MUV-25 was open and the breaker was "red tagged". Further investigation revealed that a clearance had been issued for the domestic water pump, DOP-2B. The breaker cubicle for DOP-2B was adjacent to the breaker cubicle for MUV-25 was mistakenly opened and "red tagged" in lieu of the breaker for DOP-2B. Upon confirmation of the clearance error the breaker for MUV-25 was closed, restoring its operability.

8. Designation of Apparent Cause:

The cause of this event was personnel error, in that the wrong breaker was opened and "red tagged".

9. Analysis of Occurrence:

There were no safety implications as either HPI subsystem in conjunction with the core flooding system would maintain temperatures within prescribed limits in the event of accident conditions.

10. Corrective Action:

All shift supervisors have been instructed to inform and discuss the safety aspects of proper clearance and tagging with personnel on their shifts. A plant safety meeting was held and the Clearance Procedure was reviewed for all attendees.

11. Failure Data:

This is the first occurrence of an event due to improper clearance of equipment out of service.

