

U. S. ATOMIC ENERGY COMMISSION
REGION II
DIVISION OF COMPLIANCE

VENDOR INSPECTION REPORT

Tendons for Post-Tensional Concrete Containment Building

Vendor: The Prescon Corporation
Plant 5
Simpsonville, ^{1/} South Carolina

Report No: Prescoa 70/1

Components Inspected For: Duke Power Company
Oconee Units 1, 2, and 3

Date of Inspection: February 18, 1970

Inspector: W. C. Saidle Jr. 3/18/70
W. D. Kelley, Reactor Inspector - Construction Date
(In Charge)

C. E. Murphy 3/18/70
C. E. Murphy, Reactor Inspector Date

Lic peace Representatives: G. L. Hunnicutt, Field Engineer (Civil), DPC
R. W. Simmons, Inspector, DPC

Other Persons Contacted: G. T. Johnson, Reactor Engineering Manager
Prescon Corporation, Corpus Christi Office
D. Hyatt, Quality Control Inspector, Prescon
Corporation, Plant 5, Simpsonville,
South Carolina

Report Reviewed By: W. C. Saidle 3/18/70
W. C. Saidle, Senior Reactor Inspector Date

G. W. Refnsmith 3/18/70
G. W. Refnsmith, Reactor Inspector Date
(Program Standards)

Proprietary Information: Entire Report

SCOPE

A special announced visit was made to the Prescon Corporation, Plant 5,
Simpsonville, South Carolina, on February 18, 1970.

1/ Located near Greenville, South Carolina.

7911280714

2. The quality control manual did not define a tendon wire bend or kink and it does not place a limit on their acceptance. Johnson stated a limit would be specified.
3. During fabrication of a tendon for Oconee Unit 1, the Region II inspector observed a tendon wire which had been bent. Johnson placed the tendon in quarantine pending the establishment of an acceptance criterion.
4. Prescon was inspecting button heads on the basis set forth in their quality control manual which permitted splits $0.060^{\frac{1}{2}} \times 0.25^{\frac{1}{2}}$ maximum. The PSAR has a limit of two splits of 1/64 inch. Rummel had previously stated that the 1/64-inch limit was a typographical error and that the PSAR was in the process of being corrected to read 0.069 inch. This correction was confirmed by G. C. Baill, the licensee's principal civil engineer, the following day.

DETAILS

A. Description of Prescon Corporation

Prescon has been in the post-tensioning field since its incorporation in April 1956. It operates fabricating plants in various parts of the United States and has sales representatives in major cities. For the specialized work involved in post-tensioning for nuclear applications, Prescon has established modern production facilities for anchorage manufacture (washers, spacers, and trumpets) in Corpus Christi, Texas, and tendon assembly in Simpsonville, South Carolina. In addition, it has organized a field services group and an engineering group in Corpus Christi, Texas, to handle the technical phases of product design, detail drawings, testing, equipment development, and jobsite technical assistance. A company organization chart for the manufacture of tendons for nuclear applications is shown in Exhibit A, and a list of personnel locations and functions for nuclear applications may be found in Exhibit B.

B. Description of Prescon Corporation Plant 5

Prescon has erected a 40,000 square foot office, laboratory, and tendon assembly area for post-tension applications. The plant has been identified by Prescon as Plant 5. The tendons for Oconee Unit 1 are the first tendons for nuclear application to be produced at this facility.

The plant is TEE shaped with the cross bay being 500 feet long and 50 feet wide and served by two overhead cranes. The leg is 250 feet long and 50 feet wide and is used to uncoil, cut, and assemble the tendon. The building is layed out for once-through production with material being received at one end of the 500-foot bay and finished tendons being shipped from the opposite end.

ORGANIZATION CHART




FIG.1

PRESCON JOCKEY'S
REACTOR TENDONS

<u>FUNCTIONS</u>	<u>ADDRESS</u>
President	THE PRESCON CORPORATION
Reactor Department Manager	502 C. C. State Nat'l. Bank Building
Finance	Corpus Christi, Texas 78401
(512) 882-8791	
Field Service	THE PRESCON CORPORATION
Engineering	905 Cantwell Drive
Testing	P. O. Box 4087
Quality Control	Corpus Christi, Texas 78408
Manufacturing Plant #1 (Anchorage Fabrication)	(512) 882-6571
Assembly Plant #5 (Tendon Assembly)	THE PRESCON CORPORATION
Quality Control Inspector	P. O. Box 277 Mauldin, South Carolina 29662
	Old Stage Road Directly behind American Monorail Simponville, South Carolina (803) 963-8881

FIG. 2




FIG. 3

PCW TO+PRO CHK.
COIL NO. NO. BENDS

PCW MATERIAL NUMBER RECORD (WIRE)

3.4-5

Exhibit F
Page 1 of 1

三三 道の筋の行方

QC CHECK LIST FOR TENDON FABRICATION

卷之三

卷之三