

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 0 H D B S 1 2 0 0 - 0 0 N P F - 0 3 3 4 1 1 1 1 1 4 5

CONT: 0 1

REPORT SOURCE: L 6 0 5 0 - 0 3 4 6 7 0 6 0 2 7 8 3 0 6 2 3 7 8 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | On 6/2/78 at 1910 hours, Channel 2 Borated Water Storage Tank (BWST) level indication

0 3 | on Safety Features Actuation System (SFAS) Channel 2 failed high. At 1930 hours on

0 4 | the same day, SFAS Channel 2 was placed in the tripped condition. Technical Specifi-

0 5 | cation 3.3.2.1 requires BWST level indication in Modes 1, 2 and 3 only. There was no

0 6 | danger to the health and safety of the public or unit personnel. Three other BWST

0 7 | level indicators (on SFAS Channels 1, 3 and 4) were operable. The unit was in Mode 6

0 8 | at the time of the occurrence. (NP-33-78-73)

0 9

SYSTEM CODE: I B 11

CAUSE CODE: E 12

CAUSE SUBCODE: E 13

COMPONENT CODE: I N S T R U 14

COMP SUBCODE: T 15

VALVE SUBCODE: Z 16

LEVER NO. REPORT NUMBER: 7 8

SEQUENTIAL REPORT NO.: 0 5 9

OCCURRENCE CODE: 0 3

REPORT TYPE: L

REVISION NO.: 0

ACTION TAKEN: A 18

FUTURE ACTION: Z 19

EFFECT ON PLANT: Z 20

SHUTDOWN METHOD: Z 21

HOURS: 0 0 0 22

ATTACHMENT SUBMITTED: Y 23

NPRO-4 FORM SUB.: Y 24

PRIME COMP. SUPPLIER: A 25

COMPONENT MANUFACTURER: F 1 8 0 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | The cause of the occurrence was a component failure of the amplifier assembly and lever

1 1 | assembly of the level transmitter. The defective parts were replaced, the transmitter

1 2 | calibrated and a string check performed. After performance of two surveillance tests,

1 3 | "BWST Level Inputs to SFAS Channel Calibration" and "SFAS Monthly", BWST level indica-

1 4 | tion for SFAS Channel 2 was declared operable at 1550 hours on 6/4/78.

1 5

FACILITY STATUS: G 28

POWER: 0 0 0 29

OTHER STATUS: NA 30

METHOD OF DISCOVERY: A 31

DISCOVERY DESCRIPTION: NA 32

1 6

ACTIVITY CONTENT: Z 33

RELEASED OF RELEASE: Z 34

AMOUNT OF ACTIVITY: NA 35

LOCATION OF RELEASE: NA 36

1 7

PERSONNEL EXPOSURES: 0 0 0 17

TYPE: Z 38

DESCRIPTION: NA 39

1 8

PERSONNEL INJURIES: 0 0 0 40

DESCRIPTION: NA 41

1 9

LOSS OF OR DAMAGE TO FACILITY: Z 42

TYPE: NA 43

DESCRIPTION: NA 44

2 0

PUBLICITY: N 45

DESCRIPTION: NA 46

8001270089

TOLEDO EDISON COMPANY
DAVIS-BESSE UNIT ONE NUCLEAR POWER STATION
SUPPLEMENTAL INFORMATION FOR LER NP-33-78-73

DATE OF EVENT: June 2, 1978

FACILITY: Davis-Besse Unit 1

IDENTIFICATION OF OCCURRENCE: Borated Water Storage Tank (BWST) level indication on Safety Features Actuation System (SFAS) Channel 2 failed high

Conditions Prior to Occurrence: The unit was in Mode 6 with Power (MWT) = 0 and Load (MWE) = 0.

Description of Occurrence: On June 2, 1978 at 1910 hours, Channel 2 BWST level indication on SFAS Channel 2 failed high. At 1930 hours on the same date, SFAS Channel 2 was placed in the tripped condition.

Technical Specification 3.3.2.1 requires BWST level indication in Modes 1, 2 and 3 only. Since the unit was in Mode 6 at the time of the occurrence, Action Statement 9 was not applicable. This incident is being reported as a component failure.

Designation of Apparent Cause of Occurrence: The cause of the occurrence was a component failure of the amplifier assembly and lever assembly of the level transmitter. These were replaced, and the top mechanical section of the transmitter aligned.

Analysis of Occurrence: There was no danger to the health and safety of the public or to unit personnel. Three other BWST level indicators (on SFAS Channels 1, 3 and 4) were operable. The unit was in Mode 6 at the time of the occurrence.

Corrective Action: The defective parts were replaced, the transmitter calibrated, and a string check performed under Maintenance Work Order IC-357-78. Two Surveillance Tests, ST 5031.05 "BWST Level Inputs to SFAS Channel Calibration" and ST 5031.01 "SFAS Monthly" were performed. BWST level indication for SFAS Channel 2 was declared operable at 1550 hours on June 4, 1978.

Failure Data: BWST level indication was previously reported to have been inoperable in Licensee Event Reports NP-33-77-107 and NP-33-78-01 due to frozen sensing lines.

LER #78-059