

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: \_\_\_\_\_ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | F | L | Q | R | P | 3 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 4 | 1 | 1 | 1 | 1 | - | - | 5

01 | L | 5 | 0 | 5 | 0 | - | 0 | 3 | 0 | 2 | 0 | 4 | 2 | 5 | 7 | 8 | 0 | 5 | 0 | 3 | 7 | 8 | 9

02 | At 2200 on 25 April 1978 it was observed that a low flow condition  
03 | existed on Decay Heat Removal Pump 1-A (DHP-1A). Upon dis-  
04 | assembly of DHP-1A it was discovered that the pump shaft had  
05 | sheared. No hazard to the health and safety of plant or public  
06 | as plant is in a defueled condition and DHP-1B is operable.

09 | C | F | E | X | P | U | M | P | X | X | B | Z | 7 | 8 | 0 | 2 | 0 | 0 | 1 | T | 0 | X | X | Z | Z | 0 | 0 | 0 | 0 | Y | Y | N | W | 3 | 1 | 5

10 | The cause of this event is presently being evaluated, and correct-  
11 | ive actions formulated. Upon completion, a revision to this  
12 | report will be submitted.

15 | X | 0 | 0 | 0 | Defueled | A | Operator observation

16 | Z | 2 | NA | NA

17 | 0 | 0 | 0 | NA

18 | 0 | 0 | 0 | NA

19 | Z | NA

20 | N | NA

NAME OF PREPARER: J. Cooper PHONE: (904) 795-6486

(SEE ATTACHED SUPPLEMENTARY INFORMATION SHEET)

POOR ORIGINAL

8008040 862

SUPPLEMENTARY INFORMATION

1. Report No.: 50-302/78-020/01T-0

2. Facility: Crystal River Unit #3

3. Report Date: 3 May 1978

4. Occurrence Date: 25 April 1978

5. Identification of Occurrence:

Decay Heat Removal Pump 1-A inoperable creating a condition contrary to Technical Specification 6.9.1.8.1.

6. Conditions Prior to Occurrence:

Mode 6 refueling.

7. Description of Occurrence:

At 2200 on 25 April 1978 it was observed that low flow condition existed on Decay Heat Removal Pump 1-A (DHP 1-A). Upon disassembly of DHP 1-A it was discovered that the pump shaft had sheared at the impeller end. The pump manufacturer and supplier representatives have been on site and pump shaft breakage evaluations are now in progress.

8. Designation of Apparent Cause:

The cause of this event is presently being evaluated. Upon determination of cause a revision to this report will be submitted.

9. Analysis of Occurrence:

No hazard to the health and safety of the plant or general public as plant was defueled.

10. Corrective Action:

Corrective actions are presently being formulated by the pump manufacturer and supplier.

11. Failure Data:

This is the second occurrence of an event of this type.