

LICENSEE EVENT REPORT

CONTROL BLOCK: [] [] [] [] [] [] [] []

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME: 01 ARAKI 14 LICENSE NUMBER: 00-000000-00 25 LICENSE TYPE: 41111 30 EVENT TYPE: 03 32

CONT: 01 57 CATEGORY: 58 REPORT TYPE: L 59 REPORT SOURCE: L 60 DOCKET NUMBER: 050-0313 68 EVENT DATE: 120176 69 REPORT DATE: 123076 80

EVENT DESCRIPTION

02 DURING STEADY-STATE POWER (99% FP), LEAKAGE WAS DISCOVERED ON A WELD DOWNSTREAM 80
03 OF VALVE SF-10. A DYE-PENETRANT TEST REVEALED NO PENETRATING CRACKS. A DYE- 80
04 PENETRANT TEST OF THE VALVE ABOVE SF-10, VALVE SF-11, REVEALED A CRACK IN THE HEAT 80
05 AFFECTED ZONE. NO REDUNDANT SYSTEMS ARE AVAILABLE. VALVE SF-11 WILL BE 80
06 REPLACED. (50-313/76-34) 80

07 FIC 10 B 11 VALVE EX 17 A 43 A395 47 N 48

CAUSE DESCRIPTION

08 NA 80
09 VALVE SF-11 WILL BE REPLACED. 80

11 E 9 09 10 NA 13 b 44 NA 46

12 Z 9 Z 10 NA 11 NA 44 NA 45

PERSONNEL EXPOSURES

13 000 11 Z 12 NA 13

PERSONNEL INJURIES

14 000 11 NA 12

OFFSITE CONSEQUENCES

15 NA 80

LOSS OR DAMAGE TO FACILITY

16 Z 9 NA 10

PUBLICITY

17 NA 80

ADDITIONAL FACTORS

8004110 JOY
18 NA 80

19 80

NAME: DAVID G. WARDLE PHONE: (501) 371-4496

1. Reportable Occurrence Report No. 50-313/76-34
2. Report Date: 12/30/76 3. Occurrence Date: 12/1/76
4. Facility: Arkansas Nuclear One-Unit 1
Russellville, Arkansas
5. Identification of Occurrence:
Water leakage from valve in spent fuel cooling system.

6. Conditions Prior to Occurrence:

Steady-State Power	<u> X </u>	Reactor Power	<u> 2542 </u>	MWth
Hot Standby	<u> </u>	Net Output	<u> 829 </u>	MWe
Cold Shutdown	<u> </u>	Percent of Full Power	<u> 99 </u>	%
Refueling Shutdown	<u> </u>	Load Changes During Routine Power Operation	<u> </u>	
Routine Startup Operation	<u> </u>			
Routine Shutdown Operation	<u> </u>			
Other (specify)				

7. Description of Occurrence:

At 1715 hours on December 1, 1976, leakage was discovered on a weld downstream of Valve SF-10 between the valve and a T-section. Cause of the leakage appeared to be a small crack in the weld. A dye-penetrant test of the T-section area revealed no penetrating cracks. It was then thought that the leakage may have come from above on Valve SF-11. A dye-penetrant test revealed a crack in the heat affected zone of Valve SF-11.

8. Designation of Apparent Cause of Occurrence:

Design	_____	Procedure	_____
Manufacture	_____	Unusual Service Condition Including Environmental	_____
Installation/ Construction	_____	Component Failure (See Failure Data)	_____
Operator	_____		
Other (specify)	X		
Unknown			

9. Analysis of Occurrence:

Since the leakage was only a minute amount and was contained in a controlled area, there was no hazard to the health and safety of the public.

10. Corrective Action:

After a dye-penetrant test was performed on the T-section area of Valve SF-10 and no penetrating cracks were found, a dye-penetrant test revealed a crack in the body of Valve SF-11. Valve SF-11 will be replaced.

11. Failure Data:

NONE