

# LICENSEE EVENT REPORT

CONTROL BLOCK: \_\_\_\_\_ ①

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | A | L | B | R | F | 1 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | 5

LICENSEE CODE

LICENSE NUMBER

LICENSE TYPE

CAT

CONT

0 1 | L | 6 | 0 | 5 | 0 | 0 | 0 | 0 | 2 | 5 | 9 | 7 | 0 | 6 | 0 | 4 | 8 | 0 | 5 | 0 | 7 | 0 | 1 | 8 | 0 | 9

REPORT SOURCE

DOCKET NUMBER

EVENT DATE

REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES ⑩

0 2 | With Unit 1 at 81 percent steady state power SI 4.2.E.2 was being performed on the  
0 3 | drywell air sampling system when the vacuum pump associated with RM-1-90-256 was  
0 4 | found to be pulling an inadequate vacuum. The Chem Lab was notified to obtain  
0 5 | grab samples. There was no danger to the health or safety of the public, and no  
0 6 | significant resulting chain of events. A previous similar occurrence was reported  
0 7 | on LER BFRO-50-259-79036. See Tech Spec 3.6.C.2.

0 8 | \_\_\_\_\_

0 9 | B | B | 11 | E | 12 | F | 13 | P | U | M | P | X | X | 14 | G | 15 | Z | 16

SYSTEM CODE

CAUSE CODE

CAUSE SUBCODE

COMPONENT CODE

COMP. SURCODE

VALVE SURCODE

17 | LER NO REPORT NUMBER

EVENT YEAR

SEQUENTIAL REPORT NO

OCCURRENCE CODE

REPORT TYPE

REVISION NO

ACTION TAKEN

FUTURE ACTION

EFFECT ON PLANT

SHUTDOWN METHOD

HOURS

ATTACHMENT SUBMITTED

NPRD-4 FORM SUB

PRIME COMP. SUPPLIER

COMPONENT MANUFACTURER

A | 18 | Z | 19 | Z | 20 | Z | 21 | 0 | 0 | 0 | 0 | Y | 23 | Y | 24 | L | 25 | S | 0 | 9 | 3

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS ⑳

1 0 | The pump failed to perform adequately due to normal wear from operation. It was  
1 1 | replaced. Schwitzer, Series 325. No additional recurrence control is planned.

1 2 | \_\_\_\_\_

1 3 | \_\_\_\_\_

1 4 | \_\_\_\_\_

FACILITY STATUS

POWER

OTHER STATUS

METHOD OF DISCOVERY

DISCOVERY DESCRIPTION

1 5 | E | 28 | 0 | 8 | 1 | 29 | NA | B | 31 | Routine testing

ACTIVITY CONTENT

AMOUNT OF ACTIVITY

LOCATION OF RELEASE

1 6 | Z | 33 | Z | 34 | NA | NA

PERSONNEL EXPOSURES

DESCRIPTION

1 7 | 0 | 0 | 0 | 37 | Z | 38 | NA

PERSONNEL INJURIES

DESCRIPTION

1 8 | 0 | 0 | 0 | 40 | NA

LOSS OF OR DAMAGE TO FACILITY

TYPE

DESCRIPTION

1 9 | Z | 42 | NA

PUBLICITY ISSUED

DESCRIPTION

NRC USE ONLY

2 0 | N | 44 | NA | 8007080333

NAME OF PREPARER

PHONE

LER SUPPLEMENTAL INFORMATION

BFRO-50- 259 / 8047 Technical Specification Involved 3.6.C.2  
Reported Under Technical Specification 6.7.2.b(2)  
Date of Occurrence 6/4/80 Time of Occurrence 0801 Unit 1

Identification and Description of Occurrence:

While performing SI 4.2.E.2 it was found that vacuum pump on RM-1-90-256 on continuous air monitoring system to drywell was pulling inadequate vacuum.

Conditions Prior to Occurrence:

Unit 1 - 81% steady state power  
Unit 2 - 96% steady state power  
Unit 3 - 100% steady state power

Action specified in the Technical Specification Surveillance Requirements as due to inoperable equipment. Describe.

Chem Lab was asked to obtain grab samples

Apparent Cause of Occurrence:

Normal wear on pump from operation.

Analysis of Occurrence:

There was no danger to health or safety of the public, no release of activity, no damage to plant or equipment, and no resulting significant chain of events.

Corrective Action:

Pump was replaced.

Failure Data:

LER BFRO-50-259-79036

\*Retention: Period - Lifetime; Responsibility - Administrative Supervisor

\*Revision: 