## LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1 0 R T N P 1 2 0 0 - 0 0 0 0 0 0 0 0 3 4 1 1 1 1 1 4 5 5 CAT 58
CON'T
EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)  O 12   NO. 80-10: FOLLOWING REFUELING THE RCS BORON CONCENTRATION DROPPED BELOW
THE REQUIRED 2000 PPM TO 1902 PPM. THERE WAS NO EFFECT ON SAFETY BECAUSE
O 14   CORE ALTERATIONS HA BEEN COMPLETED.
<b>TIS</b> [
0 6
07
7 8 9 SYSTEM CAUSE CAUSE COMP. VALVE
CODE   SUBCODE   SUBCODE
TO REPORT NUMBER 21 22 23 24 26 27 28 29 30 31 31 31
ACTION PUTURE EFFECT SHUTDOWN HOURS (22) ATTACHMENT NPRD-4 PRIME COMP. COMPONENT MANUFACTURER
G (8) Z (9) Z (20) Z (21) O O O O O Y (23) N (24) Z (25) Z (9   9   9   9   9   9   9   9   9   9
THIS EVENT WAS CAUSED BY PERSONNEL ERROR. A MISCALCULATION RESULTED IN
INSUFFICIENT BORIC ACID TO BE ADDED TO THE RCS PRIOR TO HIGH PRESSURE
WASHING OF THE STEAM GENERATOR TUBE SHEETS. UPON DISCOVERY, MORE BORIC
113   ACID WAS ADDED.
FACILITY SPOWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32  1 5 H 28 0 0 0 29 NA A 31 CHEMISTRY SAMPLE
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY 35 NA NA NA NA NA NA NA NA NA
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39)
1 7 8 9 PERSONNEL INJURIES 13 80
NA NAMBER OF
LOSS OF OR DAMAGE TO FACILITY 43  TYPE DESCRIPTION NA NA
1 0 0 10
PUBLICITY ISSUED DESCRIPTION 45  NA  NA  NA