

SURVEILLANCE TEST PROGRAM

APPROVED FOR

ENRICO FERMI
UNIT #2FOR BII-01-A
251" BOILING WATER REACTOR VESSEL

DOCUMENT CONTROL
<u>-001 - SG-008</u>
SEP 04 1973
FERMI 2 STATUS A
CO. 121
LTR. NO. T-100

ENRICO FERMI 2
MPL #BII-A001GENERAL ELECTRIC CO.
APED - SAN JOSE

VPP#

1976-100-4

CONTRACT 2667

G.E. CO. P.O. 205-H-399

REVISION 3

GENERAL ELECTRIC	
ATOMIC POWER EQUIPMENT DEPT.	
SAN JOSE, CALIFORNIA	
<input type="checkbox"/>	Not Approved. Revise and re-submit for approval.
<input checked="" type="checkbox"/>	Approved. No further action required.
<input type="checkbox"/>	Approved With / Without comments Revise, proceed with fabrication and submit final copies.
<input type="checkbox"/>	Refer to EDS # _____
_____ <u>GR Schmidt</u> <small>Date:</small>	
 <small>Approval is in regard to general design and controlling dimensions. This does not constitute acceptance of any designs, materials or equipment which will not fulfill the functional or performance requirements established by the purchase contract.</small>	
<small>18 Mar 70</small>	

FEBRUARY 1970

8007160 709

SURVEILLANCE TEST PROGRAM
FOR
DETROIT EDISON REACTOR VESSEL

All base metal specimens shall be taken from two plates (Code G-3705) which are "trim offs" of two plates used in lower intermediate shell section of the reactor vessel. All weld specimens and heat affected zone specimens shall be taken from one test plate prepared from these two plate "trim offs."

1.0 Base Material

- 1.1 The base metal shall be taken from the two test plates "C" (Code G-3705), Reference Drawing E-232-899. The plates designated as Test "C₁", Test "C₂", Test "C₃" and Test "D" as shown in Fig. 1 shall be removed from these two plates and used for base material specimens.
- 1.2 The test plates (C₁, C₂, C₃, and D) shall be given a simulated stress relief for forty (40) hours at 1150° ± 25°F to insure that they represent the metallurgical condition of the lower intermediate shell plates of the reactor vessel after final fabrication.

2.0 Cutting of Base Material

- 2.1 Furnished are four test plates, C₁, C₂, C₃ and D, cut as shown in Figure 1 from Code G-3705.
- 2.2 The test plates shall be stenciled with paint as shown in Figures 2 and 5.
- 2.3 The dimensions as shown in Figures 2 and 5 are finished dimensions for each section obtained by machining or sawing off flame cut edges all around approximately 1" back from the edge.
- 2.4 The material must be used cautiously since there is very little extra material available.

3.0 General Instructions

- 3.1 All final cutting shall be done by machine.
- 3.2 Stencil all unused material with applicable Code Number and direction of rolling, with paint, and return to storage.
- 3.3 Specimen marking and mark orientation are of the utmost importance. Marking instructions must be followed. In case of a mistake, or if uncertain about the marking on a blank, do not use it for a finished specimen.

4.0 Base Metal Charpy Specimens

4.1 Specimen Requirements

- 4.1.1 Prepare the base metal charpy specimens in accordance with Figure 3 and Figure 14 from the plate test "D" (Code G-3705-2).
- 4.1.2 The specimens shall be taken from 1/4 thickness positions in the plate. The long axes of the specimens shall be parallel to the plate rolling direction. The specimen notches shall be perpendicular to the original plate surface and shall be controlled by the orientation of the end markings on the specimen blanks (see Figure 3 and Paragraph 15).

4.2 Specimen Preparation

- 4.2.1 Power hack saw two (2) blocks (Test "D₁" and "D₂") 2-1/4" x 7-3/8" x 11-1/2" from the test plate "D" (see Figure 2).
- 4.2.2 Stencil each sub-slab location with the proper marks before dividing the blocks into slabs and sub-slabs. The 1/4 T specimens near one surface shall be marked with F.A.B. Code in the series A¹M through A¹S and those near the other surface shall be marked with the series A²S through A²C and D¹B through D¹C. The top of the code symbols are on a line perpendicular to the plate surface. The notch shall be on the side adjacent to the top of the Code symbols on the specimen as shown in Figure 3 (see Paragraph 15).
- 4.2.3 Power hack saw each 2-1/4" x 7-3/8" x 11-1/2" block into two (2) 1/2" x 2-1/4" x 11-1/2" slabs at 1/4 T thickness levels, as shown in Figure 3.
- 4.2.4 Surface grind both 2-1/4" x 11-1/2" surfaces of each slab to a thickness of .405", as shown in Figure 3.
- 4.2.5 Cut off the unmarked edge of each of the slabs to the required finished specimen length (see Fig. 14).
- 4.2.6 Machine each of the four (4) slabs into fifteen (15) .405" x 2.165" x 1/2" sub-slabs each as shown in Figure 3, for a total of sixty (60) pieces. Allow sufficient stock for finish grinding.
- 4.2.7 Finish each specimen as shown in Figure 14, and place each in respective F.A.B. Code marked individual envelopes.

- 4.2.8 Remark one end of each finished specimen with its F.A.B. Code serial number if the original mark has been destroyed. Maintain original orientation of marking per paragraph 4.2.2. Start with the lowest mark and proceed serially.
- 4.2.9 Inspect, clean and dip each finished specimen in "Dip Seal Plastic" DS 300 Clear for prevention of rust and mechanical damage.
- 4.2.10 Fifty-three (53) specimens shall be packed in a vacuum sealed weld carton. The specimens shall be sent to the customer to comply with Paragraph 3.4 of Specification 21A-010, Revision 0.
- 4.2.11 The remaining seven (7) specimens shall be used by CE for testing purposes.

5.0 Base Metal Tensile Specimens

5.1 Specimen Requirements

- 5.1.1 Prepare the tensile specimens in accordance with Figure 4 and Figure 13 from the plate test "D", Code G-3705.
- 5.1.2 The specimens shall be taken from 1/4 thickness positions in the plate. The long axes of the specimens shall be parallel to the plate rolling direction.

5.2 Specimen Preparation

- 5.2.1 Power hack saw one (1) block (Test "D₁") 3-5/8" x 7-3/8" x 11-1/2" from the test plate "D" (see Figure 2).
- 5.2.2 Stencil each sub-slab location with the proper F.A.B. Code marks before dividing the block into slabs and sub-slabs. The 1/4 T specimens near one surface shall be marked with F.A.B. Code in the Series B51 through B5C, and those near the other surface shall be marked with the series B5D through B5L and DJ1 through DJ5 (see Paragraph 15).
- 5.2.3 Power hack saw the 3-5/8" x 7-3/8" x 11-1/2" block into ten (10) 3-5/8" x 7-3/8" x 1/2" slabs as shown in Figure 4.
- 5.2.4 Power hack saw each 3-5/8" x 7-3/8" x 1/2" slab into two (2) 1/2" x 3-5/8" x 1/2" sub-slabs at the 1/4 T thickness levels, as shown in Figure 4, for a total of twenty (20) pieces.

- 5.2.5 Place the sub-slabs in respective F.A.B. Code marked individual envelopes for further processing (see Figure 4 and Paragraph 15).
- 5.2.6 Finish each specimen, as shown in Figure 13, and return to its individual envelope.
- 5.2.7 Remark one end of each finished specimen with its corresponding envelope F.A.B. Code number if the original mark has been destroyed. Start with the lowest mark and proceed serially.
- 5.2.8 Inspect, clean and dip each finished specimen in "Dip Seal Plastic" DS 300 Clear for prevention of rust and mechanical damage.
- 5.2.9 Fourteen (14) specimens shall be packed in a vacuum sealed weld carton. The specimens shall be sent to the customer to comply with Paragraph 3.5 of Specification 21A1010, Revision 0.
- 5.2.10 The remaining six (6) specimens shall be used by CE for testing purposes.

6.0 Test Plate Test "C₁", "C₂", and "C₃" (Figure 1 and 5)

- 6.1 The test plates, "C₁", "C₂" and "C₃", taken from the test plates Code G-3705-1 and G-3705-2 (Figure 1), shall be finished to 7-3/8" x 10" x 12" as shown in Figure 5 by machining off at least 1" of stock from all flame cut edges. Identifying marks as shown on Figure 5 shall be metal stamped on each plate with symbols at least 1/4" high. The rolling direction shall also be distinctly marked.
- 6.2 The finished plates, along with documents showing source, chemistry and all heat treatments, shall be sent to the customer to comply with Paragraphs 3.1.1 and 3.1.4 of Specification 21A1010, Revision 0.

7.0 Weld and Heat Affected Zone Material

- 7.1 The weld and heat affected zone material shall be taken from two (2) plate "trim offs" from the lower intermediate shell of the reactor vessel (Code G-3705-1 and G-3705-2) plate pieces "E" and "F" cut as shown in Fig. 1. Each piece is approximately 33" x 19-3/8" x 7-3/8" thick after the quenched end has been removed. The two (2) plates shall then be joined with a continuous central weld which is identical to the reactor vessel longitudinal weld. Note that the quenched edges of the plates must be the outer edges of the test plate after welding (see Figure 6 and 7).

7.2 The welded test plate (Figure 6) shall be given a simulated stress relief for forty (40) hours at 1150°F ± 25°F to insure that it, and the weld, represent the metallurgical condition of a vessel weld, as fabricated, in the reactor core region. X-rays of the weld shall be sent to the customer to comply with Paragraph 3.2.3 of Specification 21A1010, Revision 0. Do not repair the weld if defects are present.

8.0 Cutting of Weld and Heat Affected Zone Material

8.1 Furnished is a 7-3/8" x 38-3/4" x 88" plate with a central weld (see Figures 6 and 7).

8.2 The welded plate shall be flame cut into two (2) sections (7-3/8" x 38-3/4" x 59") and (7-3/8" x 38-3/4" x 28) as shown in Figure 7. Use the 7-3/8" x 38-3/4" x 59" section for the following; send the other to the customer as directed in Paragraph 14.1.

8.3 One plate shall be flame cut to 7-3/8" x 10" x 59" with the weld center as the centerline of the 10" side (see Figure 7). Stencil the cut-off material, using paint, with the appropriate code numbers and quenched edge identification and return to storage.

8.4 Power hack saw test "U" (7" x 10" x 7-3/8"), "V" (11-1/4" x 10" x 7-3/8"), "W" (10" x 7" x 7-3/8"), and "X" (10" x 2" x 7-3/8") plates from the 7-3/8" x 10" x 59" as shown on Figure 7.

8.5 The material must be used cautiously since there is very little other material available.

9.0 General Instructions

9.1 All final cutting shall be done by machine. No flame cutting will be allowed.

9.2 Specimen marking and mark orientation are of the utmost importance. Marking instructions must be followed. In case of a mistake, or if uncertain about the marking on a blank, do not use it for a finished specimen.

10.0 Weld Charpy Specimens

10.1 Specimen Requirements

10.1.1 Prepare the weld charpy specimens in accordance with Figure 8 and Figure 14 from the weld deposit material of the furnished plate test "U".

10.1.2 The long axis of the specimen shall be perpendicular to the weld direction and parallel to the plate surface with the middle of the specimen at the mid-plane of the weld, as shown in Figure 8. The specimen location in the stock material shall be recorded, approximately, by the numbering system (see Figure 8 and Paragraphs 10.2.2 and 15). The V-notch shall be perpendicular to the plate surface.

10.2 Specimen Preparation

10.2.1 Power hack saw the central weld section, 2-1/4" x 7-3/8" x 7", out of the test "U" plate with the weld center of the block as shown in Fig. 8.

10.2.2 Stencil each sub-slab location with the proper marking before dividing the block into slabs and sub-slabs. Ten (10) sub-slabs shall be taken at each of six (6) elevations. The first or top elevation shall be marked with F.A.B. Code in the series AÜD through AÜY. The second elevation shall be marked with the F.A.B. Code in the series AÝ1 through AÝC. The third elevation shall be marked with F.A.B. Code in the series AÝD through AÝF. The fourth elevation shall be marked with F.A.B. Code in the series BÝ1 through BÝC. The fifth elevation shall be marked with F.A.B. Code in the series BÝD through BÝY. The sixth elevation shall be marked with F.A.B. Code in the series BÝ1 through BÝ5 and DÝD through DÝL (see Paragraph 15).

The top of the code symbols are on a line perpendicular to the plate surface. The notch shall be on the side adjacent to the top of the code symbols on the specimens as shown in Figure 8.

10.2.3 Power hack saw the 2-1/4" x 7-3/8" x 7" weld block into six (6) 1/2" x 7" x 2-1/4" slabs (see Figure 8).

10.2.4 Surface grind both 7" x 2-1/4" surfaces of each slab to a thickness of .405 inches, as shown in Figure 8.

10.2.5 Cut the unmarked edge of each slab to the required finished specimen length (see Figure 14).

10.2.6 Machine ten (10) .405" x 2.165" x 1/2" sub-slabs out of each slab as shown in Figure 8 for a total of sixty (60) pieces. Allow sufficient stock for finish grinding.

- 10.2.7 Finish each specimen as shown in Figure 14 and place each in respective F.A.B. Code marked individual envelopes.
- 10.2.8 Re-mark one end of each specimen with its corresponding F.A.B. Code serial number as noted on the envelope if the original mark has been destroyed. Maintain original orientation of marking per Paragraph 10.2.2. Start with the envelope with the lowest mark and proceed serially.
- 10.2.9 Inspect, clean and dip each finished specimen in "Dip Seal Plastic" DS 300 Clear for prevention of rust and mechanical damage.
- 10.2.10 Fifty-three (53) specimens shall be packed in a vacuum sealed weld carton. The specimens will be sent to the customer to comply with Paragraph 3.6 of Specification 21A1010, Revision 0.
- 10.2.11 The remaining seven (7) specimens shall be used by CE for testing purposes.

11.0 Weld Tensile Specimens

11.1 Specimen Requirements

Prepare the weld tensile specimens, in accordance with Figure 9 and Figure 13, from the weld deposit material of the furnished plate test "V", as shown in Figure 7. The long axes of the specimens shall be parallel to the length of the weld and parallel to the top surface of the plate (see Figure 9). The gauge length of the specimens shall be of weld deposit material only. The threaded ends of the specimens may include heat affected zone or base metal. The approximate location of the specimens in the stock material shall be recorded by the marking system (see Fig. 9 and Paragraphs 11.2.3 and 15).

11.2 Specimen Preparation

- 11.2.1 Power hack saw the center of the weld 1" x 7-3/8" x 11-1/4" out of the test "V" plate with the weld center at the center of the block as shown in Figure 9. Stencil the outside sections, using paint, with the appropriate code numbers and return to storage.
- 11.2.2 Power hack saw the 1" x 7-3/8" x 11-1/4" block into three (3) 1" x 7-3/8" x 3-5/8" slabs, as shown in Figure 9. Stencil each slab 1, 2, and 3 before dividing the block (see Figure 9).

- 11.2.3 Stencil each sub-slab location with the proper marks after dividing the block into slabs. Three (3) sub-slabs shall be taken at each of six (6) elevations. The first or top elevation shall be marked with F.A.B. Code designations B6M, B6P, and B6T. The second elevation shall be marked with F.A.B. Code designations B6U, B6Y, and B6I. The third elevation shall be marked with F.A.B. Code designations B62, B63, and B64. The fourth elevation shall be marked with F.A.B. Code designations B65, B66, and B67. The fifth elevation shall be marked with F.A.B. Code designations B6A, B6B, and B6C. The sixth elevation shall be marked with F.A.B. Code designations D66, D67, and D6A.
- 11.2.4 Power hack saw each slab into six (6) 1/2" x 3-5/8" sub-slabs, as shown in Figure 9, for a total of eighteen (18) pieces. Place the sub-slabs in serially marked individual envelopes for further processing.
- 11.2.5 Finish and inspect the specimens, as shown in Figure 13. Replace specimens in their respective envelopes.
- 11.2.6 Re-mark specimens on one end, serially, as shown in Figure 9 and Paragraph 15 if the original marks have been destroyed. Start with the envelope with the lowest mark and proceed serially.
- 11.2.7 Clean and dip each finished specimen in "Dip Seal Plastic" DS 300 Clear for prevention of rust and mechanical damage.
- 11.2.8 Thirteen (13) specimens shall be packed in a vacuum sealed weld carton. The specimens shall be sent to the customer to comply with Paragraph 3.7 of Specification 21A1010, Revision 0.
- 11.2.9 The remaining five (5) specimens shall be used by CE for testing purposes.

12.0 Heat Affected Zone Charpy Specimens

12.1 Specimen Requirements

- 12.1.1 Prepare the heat affected zone charpy specimens, in accordance with Figure 10 and Figure 14, from the welded material of the plate test "N" (see Fig. 7).

12.1.2 The long axes of the specimens shall be perpendicular to the length of the weld and parallel to the top surfaces of the plate (see Figure 10). The radius of the V-notch of the specimens shall be at the edge of the weld. The axis of the V-notch orientation shall be controlled by the marking orientation. The location of the specimen in the stock material shall be recorded, approximately, by the marking system (see Fig. 10 and Paragraphs 12.2.2 and 15).

12.2 Specimen Preparation

12.2.1 Power hack saw the central section, 7" x 7-3/8" x 4-1/2" out of the plate test "W" with the weld center at the center of the block, as shown in Figure 10.

12.2.2 Stencil each sub-slab location with the proper mark before dividing the block into slabs and sub-slabs. Ten (10) sub-slabs shall be taken at each of six (6) elevations, for a total of sixty (60) pieces. The first or top elevation shall be marked with F.A.B. Code in the series B26 through B2L. The second elevation shall be marked with F.A.B. Code in the series B3M to B3S. The third elevation shall be marked with F.A.B. Code in the series B3G through B3L. The fourth elevation shall be marked with F.A.B. Code in the series B3M through B4G. The fifth elevation shall be marked with F.A.B. Code in the series B4G through B4L. The sixth elevation shall be marked with F.A.B. Code in the series B4M through B4Y and DDM through DDY.

The top of the code symbols are on a line perpendicular to the plate surface. The notch shall be on the side adjacent to the top of the code symbols on the specimens as shown in Figure 10.

12.2.3 Power hack saw six (6) 1/2" x 7" x 4-1/2" slabs from 7" x 6-1/2" x 4-1/2" block (see Figure 10).

12.2.4 Surface grind both 7" x 4-1/2" surfaces of each slab to reduce the total thickness of the slab to .405". One of the faces is to have a 63 micro-inch finish for etching. Leave sufficient stock for etching and for finish grinding to specimen dimension.

12.2.5 Machine each slab into ten (10) .405" x 1/2" x 4-1/2" sub-slabs (see Figure 10) for a total of sixty (60) pieces.

- 12.2.6 Surface grind the remaining two (2) .405" x 4-1/2" sides of each sub-slab to .405" thickness. Leave sufficient stock for finish grinding to specimen dimension.
- 12.2.7 Lightly acid etch the side of each sub-slab which is adjacent to the first or last character of the F.A.B. Code symbol (whichever has the 63 micro-inch finish provided in Para. 12.2.4) to show the weld.
- 12.2.8 Scribe a line on the etched side of each sub-slab .080" below the surface which is adjacent to the top of the F.A.B. Code symbols and cut off the unmarked end 1.082" ± .010" from the intersection of this line and the edge of the weld as shown in Figures 11 and 14. DO NOT CUT OFF THE MARKED END.
- 12.2.9 Surface grind each sub-slab to remove the etch and to obtain the required finished specimen cross section (see Figure 14). Do not cut to length until later (Para. 12.2.12).
- 12.2.10 Locate, from the unmarked end, and machine the V-notch in accordance with Figure 14. See Notes 1 and 2, Figure 11.
- 12.2.11 Identify the unmarked end of each specimen with a single round nose punch mark or vibro tool mark. Do not upset the metal. Place the specimens in individual envelopes marked with the respective F.A.B. Code symbols for further processing.
- 12.2.12 Cut off the F.A.B. Code marked end to finished specimen length (see Figure 14) and immediately return the specimens to their respective F.A.B. Code marked envelopes.
- 12.2.13 Re-mark the same end of each specimen with its F.A.B. Code symbol. The proper end to re-mark is the one opposite to that identified in Paragraph 12.2.11. The original mark and its orientation as shown in Figure 14 and Paragraphs 12.2.2 and 15 must be maintained. Start with the lowest marked envelope and proceed serially.
- 12.2.14 Inspect, clean and dip each finished specimen in "Dip Seal Plastic" DS 300 Clear for prevention of rust and mechanical damage.

12.2.15 Fifty-three (53) specimens shall be packed in a vacuum sealed weld carton. The specimens shall be sent to the customer to comply with Paragraph 3.9 of Specification 21A1010, Revision 0.

12.2.16 The remaining seven (7) specimens shall be used by CE for testing purposes.

13.0 Heat Affected Zone Tensile Specimens

13.1 Specimen Requirements

Prepare the heat affected zone tensile specimens, in accordance with Figure 12 and Figure 13, from the welded material of the plate test "X" (Figure 7). The long axes of the specimens shall be perpendicular to the length of the weld and parallel to the top surface of the plate. The center of the specimen shall be in the heat affected zone adjacent to the edge of the weld metal. The approximate location of the specimens, in the stock material, shall be recorded by the marking system (see Figure 12 and Paragraphs 13.2.1 and 15).

13.2 Specimen Preparation

13.2.1 Stencil each sub-slab location before dividing the furnished block into slabs and sub-slabs. Three (3) sub-slabs shall be taken at each of six (6) elevations, for a total of eighteen (18) pieces. The first or top elevation shall be marked with F.A.B. Code B6D, B6E and B6J. The second elevation shall be marked with F.A.B. Codes B6K, B6L and B6M. The third elevation shall be marked with F.A.B. Codes B6P, B6T, and B6U. The fourth elevation shall be marked with F.A.B. Codes B6Y, B7I, and B72. The fifth elevation shall be marked with F.A.B. Codes B73, B74 and B75. The sixth elevation shall be marked with F.A.B. Codes D6D, D6E, and D6J.

13.2.2 Power hack saw three (3) 1/2" x 7-3/8" x 10" slabs from the 2" x 7-3/8" x 10" furnished blocks as shown in Figure 12.

13.2.3 Lightly acid etch each slab to reveal the weld. Place each slab in an individually marked envelope.

13.2.4 Lay out the location of the specimen blanks with the heat affected zone in their centers as shown in Figure 12.

13.2.5 Power hack saw six (6) 1/2" x 1/2" x 10" sub-slabs from each slab, for a total of eighteen (18) pieces. Cut one end 1-1/2" from one edge of the weld as shown in Figure 12. Then cut the other

end 3-5/8" from the first cut with the weld edge between the two cuts (abrasive wheel cut off permissible). Place the sub-slabs in serially marked individual envelopes for further processing.

13.2.6 Re-mark each specimen blank on one end with its F.A.B. Code designation. Start with the envelope with the lowest mark and proceed serially.

13.2.7 The 1/2" dimension which is a part of the 3-5/8" length dimension is added for machining purposes. See Figure No. 12.

13.2.8 Machine specimens as shown in Figure 13. Return Specimens to their respective envelopes.

13.2.9 Re-mark one end of each specimen with its F.A.B. Code number as shown in Figure 13 and Paragraphs 13.2.1 and 15 if the original mark has been destroyed. Start with the envelope with the lowest mark and proceed serially.

13.2.10 Inspect, clean and dip each finished specimen in "Dip Seal Plastic" DS 300 Clear for prevention of rust and mechanical damage.

13.2.11 Thirteen (13) specimens shall be packed in a vacuum sealed weld carton. The specimens shall be sent to the customer to comply with Paragraph 3.8 of Specification 21A1010, Revision 0.

13.2.11 The remaining five (5) specimens shall be used by CE for testing purposes.

14.0 Plate Pieces "E" and "F"

14.1 The remaining welded test plate fabricated from pieces "E" and "F" (see Paragraph 3.2), 38-3/4" x 28" x 7-3/8" thick, shall be sent to customer to comply with Paragraph 3.2.4 of Specification 21A1010, Revision 0. The plate shall be metal stamped "Detroit Edison Weld" and appropriate heat numbers of pieces used to fabricate as shown in Figure 7. Use symbols at least 1/4" high. Also, mark the rolling direction distinctly.

15.0 Three Digit, 20 Symbol Marking System (F.A.B. Code)

15.1 Introduction

15.1.1 CE at present is directing surveillance programs for numerous reactors. Several thousand specimens are to be handled. All of the specimens look alike, and a positive means for identification is required. The following items are to be monitored by the marking system:

(a) Reactor

(b) Type of Material - Interior Base
Exterior Base
Weld
Heat Affected Zone

(c) Location (within limits) on Stock Plate

15.1.2 The specimens must be handled remotely after irradiation, and the largest possible marking is required. The system (F.A.B. Code) uses three (3) digits and twenty (20) symbols and can accommodate 8,000 specimens. The sequence is shown in Paragraph 15.2 for the series assigned to this contract. Note that the middle digit in all cases has a double dot placed over it and shall be included as part of the marking system.

15.2 F.A.B. Code Series Numbers

15.2.1 The F.A.B. Code Series Numbers for Base Metal Charpy Specimens are:

ÄMM	ÄPP	ÄTP
ÄMP	ÄPT	ÄTT
ÄMT	ÄPU	ÄTU
ÄMU	ÄPY	ÄTY
ÄMY	ÄT1	AÜ1
ÄP1	ÄT2	AÜ2
ÄP2	ÄT3	AÜ3
ÄP3	ÄT4	AÜ4
ÄP4	ÄT5	AÜ5
ÄP5	ÄT6	AÜ6
ÄP6	ÄT7	AÜ7
ÄP7	ÄTA	AÜA
ÄPA	ÄTB	AÜB
ÄPB	ÄTC	AÜC
ÄPC	ÄTD	DB6
ÄPD	ÄTE	DB7
ÄPE	ÄTJ	DBA
ÄPJ	ÄTK	DBB
ÄPK	ÄTL	DBC
ÄPL	ÄTM	
ÄPM		

Surveillance Test Program

15.2.2 The F.A.B. Code Series Numbers for Weld Metal Charpy Specimens are:

AÜD	AÝD	BÝD
AÜE	AÝE	BÝE
AÜJ	AÝJ	BÝJ
AÜK	AÝK	BÝK
AÜL	AÝL	BÝL
AÜM	AÝM	BÝM
AÜP	AÝP	BÝP
AÜT	AÝT	BÝT
AÜU	AÝU	BÝU
AÜY	AÝY	BÝY
AÝ1	BÝ1	BÝ1
AÝ2	BÝ2	BÝ2
AÝ3	BÝ3	BÝ3
AÝ4	BÝ4	BÝ4
AÝ5	BÝ5	BÝ5
AÝ6	BÝ6	DÝD
AÝ7	BÝ7	DÝE
AÝA	BÝA	DÝJ
AÝB	BÝB	DÝK
AÝC	BÝC	DÝL

15.2.3 The F.A.B. Code Series Numbers for Heat Affected Zone Charpy Specimens are:

BÝ6	BÝ6	BÝ6
BÝ7	BÝ7	BÝ7
BÝA	BÝA	BÝA
BÝB	BÝB	BÝB
BÝC	BÝC	BÝC
BÝD	BÝD	BÝD
BÝE	BÝE	BÝE
BÝJ	BÝJ	BÝJ
BÝK	BÝK	BÝK
BÝL	BÝL	BÝL
BÝM	BÝM	BÝM
BÝP	BÝP	BÝP
BÝT	BÝT	BÝT
BÝU	BÝU	BÝU
BÝY	BÝY	BÝY
BÝ1	BÝ1	DDM
BÝ2	BÝ2	DDP
BÝ3	BÝ3	DÖT
BÝ4	BÝ4	DÖU
BÝ5	BÝ5	DÖY

15.2.4 The F.A.B. Code Series Numbers for Base Metal Tensile Specimens are:

B51	B56	B5D	DJ1
B52	B57	B5E	DJ2
B53	B5A	B5J	DJ3
B54	B5B	B5K	DJ4
B55	B5C	B5L	DJ5

15.2.5 The F.A.B. Code Series Numbers for Weld Metal Tensile Specimens are:

B5M	B61	B67	DK6
B5P	B62	B6A	DK7
B5T	B63	B6B	DKA
B5U	B64	B6C	DKB
B5Y	B65		DKC
	B66		

15.2.6 The F.A.B. Code Series Numbers for Heat Affected Zone Tensile Specimens are:

B6D	B6M	B71	DLD
B6E	B6P	B72	DLE
B6J	B6T	B73	D LJ
B6K	B6U	B74	DLK
B6L	B6Y	B75	DLL

COMBUSTION ENGINEERING, INC.
ENGINEERING DEPARTMENT, CHATTANOOGA, TENN.

CHARGE NO. COM-112-2667

DESCRIPTION TEST PLATE PROGRAM

FILE NO. _____
SHEET 16 OF 16
DATE 4-1-67 BY ACJ
CHECK DATE BY

DIRECTION OF ROLLING




FIGURE 110. 1

COMBUSTION ENGINEERING, INC.
ENGINEERING DEPT. KENT, CHATTANOOGA, TENN.
CHARGE NO. C-11714-127

DESCRIPTION: MATERIAL TEST RECORD

NUMBER _____
CHART 17 OR _____
DATE 4-1-62 NY 102
CHECK DATE _____ BY _____

TEST PLATE - TEST "D"
(EASE METAL)

DIRECTION OF ROLLING




FIGURE NO. 2

COMBUSTION ENGINEERING, INC.
ENGINEERING DEPT., MENT. CHATTANOOGA, TENN.

CHARGE NO. 5-3705-2

DESCRIPTION: SWIVEL-LIKE TEST ECONOMY

NO. 1000
SHEET 15 OF
DATE 4-1-69 BY D.L.
CHECK DATE BY

TEST PLATE - TEST "D₂" & "D₃"
(BASE METAL - CHARPY SPECIMENS)

DIRECTION OF ROLLING →




FIGURE 3

COMBUSTION ENGINEERING, INC.

ENGINEERING DEPT., LNT., CHATTANOOGA, TENN.

CHARGE NO. CONTRACT 6657

DESCRIPTION: INVESTIGATION TEST PLATE

NUMBER _____

SHEET 19 OF _____



DATE 4-1-62 BY 1221

CHECK DATE _____ BY _____

TEST PLATE - TEST "D,"


(AS METAL - TENSILE SPECIMENS)

DIRECTION OF ROLLING



COMBUSTION ENGINEERING, INC.
ENGINEERING DEPT., LNT, CHATTANOOGA, TENN.
CHARGE NO. CONTRACT 2687
DESCRIPTION. SURVEILLANCE TEST PROGRAM

NUMBER _____
SHEET 20 OR _____
DATE 1-1-69 BY 1001
CHECK DATE _____ BY _____



COMBUSTION ENGINEERING, INC.

ENGINEERING DEPT., MT. CHATTANOOGA, TENN.

CHARGE NO. CONTINUIT 2167

DESCRIPTION. MILWAUKEE TEST PROGRAM

NUMBER _____

CHL 1 21 or _____

DATE 4-1-67 BY 101T

CHECK DATE _____ BY _____

WELD \neq H.A.Z. YIELD

$\approx 38 \frac{3}{4}''$

FIVE CUT EDGES

ROLLING
DIRECTION

ROLLING
DIRECTION

65"

PIECE "E"
CODE G-3705-1

PIECE "F"
CODE G-3705-2

QUENCHED
EDGE

QUENCHED EDGE

WELD

TIME AS
15-303 MT RT CONTINUOUS
YIELD
(REF. DNG. E-232-902)




FIGURE No. 6

COMBUSTION ENGINEERING, INC.

ENGINEERING DEPT. CNT, CHATTANOOGA, TENN.

CHARGE NO. COLT 1445 E 2307

NUMBER _____

ON P. 22 OR _____

DATE 4-1-69 BY 105

DESCRIPTION: SURVEILLANCE TEST PROGRAM CHECK DATE _____ BY _____

WELD of H.A.E. MATERIAL


 $\approx 3\frac{3}{4}^{\prime \prime}$ 

FIGURE NO. 7

COMBUSTION ENGINEERING, INC.
ENGINEERING DEPT., P.O. BOX 1000, CHATTANOOGA, TENN.
CHARGE NO. CONVERGENT 6507
DESCRIPTION: MAINTENANCE TEST PROGRAM

NUMBER _____
SHR 23 OR _____
DATE 4-1-69 BY IQJ
CHECK DATE _____ BY _____

TEST PLATE - TEST "U"
(WELL METAL - CHARPY SPECIMENS)

DIRECTION OF ROLLING →





FIGURE No. 8

COMBUSTION ENGINEERING, INC.
ENGINEERING DEPARTMENT, N.E., CHATTANOOGA, TENN.
CHARGE NO. CONTRACT NO. 2007
DESCRIPTION: SURVEILLANCE TEST PROGRAM

NUMBER _____
FILE NO. 26 OR
DATE 1-1-62 BY L.O.T.
CHECK DATE _____ BY _____

TEST PLATE - TEST "V"
(WELD METAL - TENSILE SPECIMENS)
DIRECTION OF ROLLING





FIGURE No. 9

COMBUSTION ENGINEERING, INC.
ENGINEERING DEPT. DIVISION, CHATTANOOGA, TENN.

NUMBER _____
- LEFT 25 OR
DATE 1-1-69 BY 10:00
CHECK DATE _____ BY _____

CHARGE NO. G-3705-1 2667
DESCRIPTION TWISTED WIRE TEST PROBLEMS

TEST PLATE - TEST "W"
(HEAT AFFECTED ZONE CHARPY SPECIMENS)
DIRECTION OF ROLLING





FIGURE 110.10

COMBUSTION ENGINEERING, INC.

ENGINEERING DEP., MENT, CHATTANOOGA, TENN.

CHARGE NO. C011111112867


DESCRIPTION TANKER LAUNCH TEST FLOWERS

NUMBER _____

SET 26 OF _____

DATE 4-1-69 BY J.D.J.

CHECK DATE _____ BY _____



SUB-SLAB

NOTE: ① CUT OFF LINE & V-NOTCH MAY BE LOCATED FROM
EITHER WELD EDGE.

② BOTTOM OF NOTCH MUST INTERSECT WELD FUSION
LINE.

FIGURE No. 11

COMBUSTION ENGINEERING, INC.

ENGINEERING DEPT. ENT. CHATTANOOGA, TENN.

CHARGE NO. CONTRACT 2337

NUMBER _____

OF LT. 27 OR _____

DATE 4-1-69 BY JCJ

DESCRIPTION SURVEILLANCE TEST ELEMENT CHECK DATE BY _____

TEST PLATE - TEST "X"
(HEAT AFFECTED ZONE - TENSILE SPECIMENS)

DIRECTION OF ROLLING





FIGURE NO. 12

CONDUIT ENGINEERING, INC.
ENGINEERING DEPARTMENT, CHATTANOOGA, TENN.

CHARGE NO. 277500-2467

DESCRIPTION SURVEILLANCE TEST PROGRAM

NUMBER _____
SHIP. 23 OR
PAI. 4-1-62 BY 155
CHECK DATE _____ BY _____



NOTES:

1. $D = 250 \pm .001$ dia. at center of reduced section.
 2. $D' =$ actual 'D' dia. + .002 to .005 at ends of reduced section, tapering to 'D' at center.
 3. Use 22 gauge extensometer wire marker for pick punching gage marks.
 4. Polish reduced section and radius to 32 mm, remaining edge as turned.
 5. Each piece is to be marked as per specimen blank from which it was made.
 6. 100% dimensional inspection required.


FIG. 13

* CONGO SERVICE ENGINEERING, INC.
ENGINEERING DEPARTMENT, CHATTAHOOCHEE, TENN.

NUMBER _____
SHEET 22 or _____
DAY 2-1-62 OR WED
CHECK DATE _____ BY _____

CHARGE NO. MURKIN 3667

RECOMMENDED PRACTICE TEST Program



TYPICAL ORIENTATION OF IDENTIFICATION WHEN MACHINING NOTCH.

NOTES:

1. FINISH GRIND ALL SURFACES, EXCEPT ENDS, TO 63 MICROINCHES MAINTAINING CONTINUOUS FLOW OF COOLANT.
 2. MACHINE UNMARKED END TO MAKE IT SQUARE. DUE TO TOLERANCE, NO SPECIAL FINISH REQUIRED.
 3. MARKED END OF BLANK DOES NOT REQUIRE MACHINING. PRESERVE ORIGINAL IDENTITY MARKS ON END OF BLANKS; IF POSSIBLE. IF REMARKING IS REQUIRED, REMARK SAME END. CHARACTER, THEIR LOCATION/ORIENTATION ARE TO BE IDENTICAL TO THAT OF THE ORIGINAL MARKINGS.
 4. MILL OR BROACH "V" NOTCH ON SIDE ADJACENT TO TOP OF IDENTIFICATION MARKS. BOTTOM OF "V" NOTCH SHALL BE MACHINED SMOOTHLY WITH NO CHATTER OR TOOL MARKS. MEASURE NOTCH LOCATION WITH RESPECT TO UNMARKED END.
 5. REMOVE ALL BURRS.
 6. 100% DIMENSIONAL INSPECTION REQUIRED.

FIG. 14