

### LICENSEE EVENT REPORT

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CONTROL BLOCK:            (1)

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

0 1 | 0 | H | D | B | S | 1 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | 5

LICENSEE CODE      LICENSE NUMBER      LICENSE TYPE      CAT 58

CON'T

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40

0 1 | L | 6 | 5 | 0 | - | 0 | 3 | 4 | 6 | 7 | 0 | 6 | 1 | 4 | 8 | 0 | 8 | 0 | 7 | 1 | 1 | 8 | 0 | 9

REPORT SOURCE      DOCKET NUMBER      EVENT DATE      REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | (NP-33-80-59) On 6/14/80 at 1243 hours during the restoration of containment pressure

0 3 | inputs to Safety Features Actuation System (SFAS) cabinets, the station experienced an

0 4 | SFAS actuation. The actuation caused decay heat suction to switch from the Borated

0 5 | Water Storage Tank to the emergency sump. A loss of suction occurred and the pump

0 6 | was stopped. This caused a loss of decay heat flow and violation of T.S. 3.9.8.

0 7 | There was no danger to the public or station personnel. Flow was restore two

0 8 | minutes and no increase in core temperature was noted.

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

0 9 | C | F | 11 | D | 12 | Z | 13 | Z | Z | Z | Z | Z | Z | 14 | Z | 15 | Z | 16

SYSTEM CODE      CAUSE CODE      CAUSE SUBCODE      COMPONENT CODE      COMP. SUBCODE      VALVE SUBCODE

17 | 8 | 0 | - | 0 | 4 | 9 | / | 0 | 3 | L | - | 0

LER/RO REPORT NUMBER      EVENT YEAR      SEQUENTIAL REPORT NO.      OCCURRENCE CODE      REPORT TYPE      REVISION NO.

X | 18 | G | 19 | Z | 20 | Z | 21 | 0 | 0 | 0 | 0 | Y | 23 | N | 24 | Z | 25 | Z | 9 | 9 | 9 | 26

ACTION TAK'N      FUTURE ACTION      EFFECT ON PLANT      SHUTDOWN METHOD      HOURS      ATTACHMENT SUBMITTED      NPRD-4 FORM SUBJ.      PRIME COMP. SUPPLIER      COMPONENT MANUFACTURER

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | The cause was a deficient procedure in that ST 5061.01 Appendix F did not require the

1 1 | mechanic to go to test trip bypass while restoring a channel or to reset the channel

1 2 | after completion of restoration. At 1252 hours Decay Heat Pump 1-1 was started and

1 3 | flow re-established. A modification to ST 5061.01 will be added to provide these

1 4 | instructions.

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

1 5 | H | 28 | 0 | 0 | 0 | 29 | NA | B | 31 | Conclusion of Surveillance Test

FACILITY STATUS      % POWER      OTHER STATUS      METHOD OF DISCOVERY      DISCOVERY DESCRIPTION

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

1 6 | Z | 33 | Z | 34 | NA | NA

ACTIVITY CONTENT RELEASED OF RELEASE      AMOUNT OF ACTIVITY      LOCATION OF RELEASE

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

1 7 | 0 | 0 | 0 | 37 | Z | 38 | NA

PERSONNEL EXPOSURES NUMBER      TYPE      DESCRIPTION

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

1 8 | 0 | 0 | 0 | 40 | NA

PERSONNEL INJURIES NUMBER      DESCRIPTION

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

1 9 | Z | 42 | NA

LOSS OF OR DAMAGE TO FACILITY TYPE      DESCRIPTION

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

2 0 | N | 44 | NA

PUBLICITY ISSUED      DESCRIPTION

TOLEDO EDISON COMPANY  
DAVIS-BESSE NUCLEAR POWER STATION UNIT ONE  
SUPPLEMENTAL INFORMATION FOR LER NP-33-80-59

DATE OF EVENT: June 14, 1980

FACILITY: Davis-Besse Unit 1

IDENTIFICATION OF OCCURRENCE: Inadvertent actuation of Safety Features Actuation System (SFAS) during restoration of containment pressure inputs

Conditions Prior to Occurrence: The unit was in Mode 6, with Power (MWT) = 0 and Load (Gross MWE) = 0.

Description of Occurrence: On June 14, 1980 at 1243 hours, during the restoration of containment pressure inputs to SFAS cabinets, the station experienced an SFAS actuation of levels 1, 2, and 3. Level 1 caused some containment isolation. Level 2 caused more isolation and alignment of the Emergency Core Cooling Systems. Level 3 caused decay heat pump 1-1, which was in service, to switch suction from the Reactor Coolant System (RCS) hotleg to the Borated Water Storage Tank (BWST). This caused about 16,000 gallons of borated water to be added to the RCS and raised the level in the refueling canal. At 1248 hours, the BWST level dropped to 4.5 feet which caused a Level 5 actuation. This switches decay heat suction from the BWST to the emergency sump. DH7A and DH7B went closed isolating the BWST. This caused a loss of suction to the decay heat pump. At 1250 hours, the pump was stopped to prevent damage. This caused a loss of decay heat flow and violation of Technical Specification 3.9.8, which requires at least one decay heat loop to be in operation in Mode 6. The action statement requires a suspension of all operations involving an increase in the reactor decay heat load or a reduction in boron concentration of the RCS. The conditions were met. At 1252 hours, the suction for the decay heat pump was restored, the pump placed in service, and the flow was verified at 3000 gpm.

Designation of Apparent Cause of Occurrence: An I&C mechanic was in the process of restoring the containment pressure inputs to SFAS at the conclusion of the Integrated Leak Rate Test, ST 5061.01, Appendix F. When the mechanic touched the leads for Channel 3 to the terminals, a voltage transient caused a high containment pressure trip of that channel. He then went to Channel 4 and when the leads were attached, a high containment pressure trip was received in that channel. This meant the two out of four requirement for Levels 1, 2, and 3 trip of SFAS was received. ST 5061.01 Appendix F did not require the mechanic to go to test trip bypass while restoring a channel or to reset the channel after completion of restoration which would have prevented the trip of SFAS.

Analysis of Occurrence: There was no danger to the health and safety of the public or to station personnel. No core alterations were in progress and flow was restored within two minutes after it was lost. No increase in core temperature was noted.

LER #80-049

Corrective Action: At 1252 hours on June 14, 1980, suction from the RCS to the decay heat pump 1-1 was re-established, the pump put in service, and flow verified at 3000 gpm. At 1332 hours, the NRC was notified via the red phone. At 1345 hours, the recovery from the safety actuation was complete with the RCS at 92°F and 3000 gpm flow.

A modification, T-4774, has been added to ST 5061.01 to provide instructions on restoring containment pressure inputs to SFAS.

Failure Data: There have been no previous similar reportable occurrences in which decay heat flow was lost due to a procedural inadequacy.

LER #80-049