

SITE PROBLEM

REPORT TRANSMITTAL

THREE MILE ISLAND-1

**** CLEARED ****

TO: _____ For Information
Central Engineering Files
C. C. Plunkett - Contract Admin.
S. H. Klein - Quality Assurance
R.A. Shepherd - Task Engineer
R.A. Gavers - Project Manager

FILE: 13-5-322
CONTRACT NO: 620-00 OS
SPR 322 REV. 1
TITLE Low PRESS.
LEVEL FOLLOWING
REACTOR TRIP
DATE: 6-25-76

The attached, cleared SPR is submitted for your information.

TO: _____ E. L. Logan - FLORIDA
_____ L. C. Rogers - MET.ED. _____
_____ R. J. Baker - TOLEDO _____
_____ B. L. Day - Intl. Support _____
_____ P. E. Perrone - OFR _____
_____ J. L. Donnell - OFR _____

L.M. KOLONAY

Attached is one copy of Site Problem Report No. 322 which was processed on Contract 620-00 OS. Future contracts have been reviewed for the potential of a similar problem. This problem ~~is~~ is not considered applicable to other contracts OC.

REMARKS:

cc: G. M. Jacks - Plant Integration
This SPR has been reviewed IAW NPG-1707-01

Chris C. Lockard
NUCLEAR SERVICE SUPPORT ENGINEER

CLEARED

7910040 530

SITE PROBLEM REPORT

BARCOCK & WILCOX

CUSTOMER	MET ED	CONTRACT NO.	620-0002	SPR NO.	322	REV. NO.	1
VENDOR	EMCO	P.O. NO.		TASK NO.	21	GROUP NO.	01
SITE ENGINEER	B. P. MAINCI			REQ'D. RESOL. DATE		REQ'D. COMP. DATE	
TITLE LOW PRESSURIZER LEVEL FOLLOWING REACTOR TRIP							
DESCRIPTION OF PROBLEM SEE ATTACHED SHEET							
STATUS - ACTION TO DATE INCLUDING PERSONS CONTACTED L. M. Koleny of Engineering informed.							
FURTHER ACTION RECOMMENDED BY SITE PERSONNEL Review and implement Logic modification such that reactor trip should block calibrating integral RC 9.12, to achieve a slower cooldown rate of RC System and a more acceptable pressurizer level. This problem should be reviewed for all other sites.							
SPOKESMAN		10/4/74	SPOKESMAN SIGNATURE		10/4/74		
RESOLUTION SEE COMPLETION REPORT							
APPROVED BY			SIGNATURE	DATE			
N. S. SUPPORT ENGINEER			<i>Chris C. Lockard</i>	6-23-76			
TASK ENGINEER/NS UNIT MGR			<i>No. 2. Holonyak Jr. /initials</i>	6/23/76			
OP. PLANT MGR.			<i>John Harrington</i>	6/24/76			
PROJECT MANAGER/SERVICE MGR.			<i>R. Hovers</i>	6/23/76			
COST CATEGORY	<input type="checkbox"/> NORM	<input type="checkbox"/> C	<input type="checkbox"/> D	<input type="checkbox"/> G	<input type="checkbox"/>	<input type="checkbox"/> VENDOR CLAIM	
AUTH CHARGE NO			<input type="checkbox"/> FIELD CHANGE REQ	FC NO			
SITE COMPLETION REPORT FURTHER INVESTIGATION SHOWED THAT OPERATOR PUT FW CONTROL IN MANUAL. THE PROBLEM RESULTED FROM OPERATOR ACTION INSTEAD OF AUTOMATICICS ACTION. RECOMMEND SPR BE CLOSED <i>(R. Hovers) BNICo 423/76</i>							
DEVIATIONS	<input type="checkbox"/> NONE	<input type="checkbox"/> SEE SPR REV. NO.	<input type="checkbox"/> RECOMMENDED STDS. CHANGE				
DATE COMPLETED	SIGNED BY		FINAL DISTRIBUTION				
S O M. CONSTR. REP. APPROVAL	<i>R. Hovers</i>		PROJECT MANAGER S.O.M./CONSTR. REP. QA DOC FILE CENT. ENGR FILE 1211.2				
DATE 6/23/76							

ATTACHMENT
SPR 322 Rev. 1

DESCRIPTION OF PROBLEM:

Following a reactor trip the pressurizer level goes as low as 40 inches. SPR 322 Rev. C pointed out the main reason that pressurizer level goes as low, because the trapped steam pressure in turbine header decays slowly, resulting in turbine bypass remaining open for time longer than is necessary.

Further examination of the reactor trip data revealed that immediately following the reactor trip the feedwater demand actually reduced to 20% instead of reducing to 5% (cross limit value as neutron power following the trip is zero).

This additional feed to steam generators contributes to the excessive cooling of the RC system and hence lower pressurizer level.

See attached EMC report on the subject.

PROJ. NO.	ITEM NO.	FILE NO.	ACT. OF PROBLEM	FROM							
			9/5/74 AND 10/13/74 150L	R. S. Band							
CWD INFO ONLY			LINE NO. & NO.	LOC. NO. 51239 ACCT. NO. 779							
DX 1 ONE ONLY AND TYPE OF SYSTEM/PRODUCT			MAIL STATION PU Box 352								
TITLE: ICS IMPROVEMENT			Middletown PA 17057								
Reference: My PMS of 9/23/74			SERIAL NO. AND ORG. PART NO.								
On 9/4/74 Mat. Ed. Plant Superintendent, Jack Herbein stated that "On a Reactor Trip the pressurizer level should not drop as low as it does, (to approximately 40 inches) Analysis of the 8/13/74 Generator breaker trip test reveals the cross limits from neutron power error to feedwater flow control did not perform as expected. The neutron power error cross limit should have reduced the feedwater demand immediately after reactor trip to approximately 5%. The neutron power error cross limit actually reduced the feedwater flow demand to approximately 20%. This additional feed to the steam generators contributed to the excessive rate of cooling of the IC system and the resultant drop in pressurizer level."			X								
The reason for the above undesirable performance is as follows. On a reactor trip the CWD system transfers to manual. When the CWD is in MANUAL the neutron power error is applied to the T_{ave} calibrating integral.											
EFFECT ON SYSTEM/NORMALLY											
CUSTOMER ATTITUDE			POSSIBLE CAUSE FOR PROBLEM								
MAJOR CONCERN			<input type="checkbox"/> CONCERNED <input checked="" type="checkbox"/> INFO. ONLY								
<input type="checkbox"/> CONCERNED <input checked="" type="checkbox"/> INFO. ONLY			<input type="checkbox"/> FAULTY MATERIAL <input type="checkbox"/> FAULTY MANUFACTURING <input type="checkbox"/> SPECIFICATION ERROR <input type="checkbox"/> PERFORMANCE DEFECT ENGR. <input type="checkbox"/> FAULTY PACKAGING <input type="checkbox"/> COMPONENT FAILURE <input type="checkbox"/> DESIGN <input type="checkbox"/> WORKROUT <input type="checkbox"/> IMPROPER APPLICATION <input type="checkbox"/> OPERATING ENVIRONMENT <input type="checkbox"/> INSUFFICIENT INSTRUCTIONS (DOCUMENTATION)								
DATE SOLUTION REQUIRED			OPERATING CONDITIONS								
10/14/74			AMBIENT TEMP. <input type="checkbox"/> CLEAN <input type="checkbox"/> DIRTY								
			ATMOSPHERE: <input type="checkbox"/> CLEAN <input type="checkbox"/> DIRTY								
			HUMIDITY: <input type="checkbox"/> HI <input type="checkbox"/> LO <input type="checkbox"/> AVG.								
REPORT OF INVESTIGATION & CORRECTIVE ACTION (BY FIELD IF APPLICABLE)			TIME REQUIRED TO:								
			REPAIR <input type="checkbox"/> TROUBLESHOOT <input type="checkbox"/>								
			RECALIBRATE <input type="checkbox"/>								
			FAILURE DETAILS: <input type="checkbox"/> UNKNOWN <input type="checkbox"/> CWD CWD. PART NO. <input type="checkbox"/>								
			DESCRIBE (DIODE, CAP., TRANSISTOR, ETC.)								
			CIRCUIT SYMBOL <input type="checkbox"/> Q1, R1, Q2								
			MFG. OF PART (IF KNOWN)								
			HOW PART FAILED: <input type="checkbox"/> SHORT <input type="checkbox"/> OPEN <input type="checkbox"/> MECH. DAMAGE <input type="checkbox"/> ADJUSTMENT <input type="checkbox"/> DIRTY <input type="checkbox"/> UNKNOWN <input type="checkbox"/> OTHER (DESCRIBE)								
FOR USE ONLY:											
PROBL. TYPE	FAILURE CODE	PN. SYSTEM	OWNER/ORG.	ACTION/TAKEN BY							
CODES: QUALITY ASSURANCE XNO. LIABILITY PRO. PLANNING NFO FPO CONTRACT OPR. WARRANTY REPAIR COMPLIATION ENGR. COMP. SERVICES ORDER CENTER COMPONENT ENGR.	COPIES			<input type="checkbox"/> PRELIMINARY ANS	SIGNATURE	DATE	APPROVAL	DATE			
				<input type="checkbox"/> FINAL SOLUTION							
				FOLLOW UP/UN-CORRECTIVE ACTION					DISP. OF RM.		
									DATE F.C.D.		
									DATE RETURNED		
									HOURS SPENT SOLUTION		
									DEPT.	MAN.	HRS.
FORM 505-278											

ATTACHMENT

PROBLEM: (Cont'd)

At this time the neutron error is very large and rapidly causes the calibrating integral to travel to its limit. Reference DWG D553712 and D556175F. When the Tave calibrating integral travels to its limit the effective neutron power error to the cross limit is reduced and therefore results in inadequate reduction in feedwater flow.

a

RECOMMENDATIONS:

On DWG D556175 T1 (Calibrating Integral Operation), logic 1, i.e., should be added between RC D3.1 and RC D4.1. This logic block to read "IS REACTOR TRIPPED? (By Diamond)". If YES, Block calibrating Integral NO).14. If NO, Proceed to RC D4.1.

DESIRED ACTION:

Please contact B&W to see if they would like to implement this ICS improvement.

APPLIES TO OTHER NSS CONTRACTS: YES

ATTACHEE

DATE

CONT. ENGR
FILE 13M 2

→ NSS-5 SPR 322 Rule (P-100)

On 5-12-75 discussed this with Bob Wahr. Bob feels that this particular problem is part of an ongoing evaluation underway at IMI and to maintain the plant on line after a Turbine trip. He says he is committed to making a final recommendation for the 62 NSS which would be issued for NSS-7, 14, 6 etc once IMI completes additional testing later this year.

7/1/75 Lcd = 174 At BMCo 1st FDR/NPR

2-2-76 322 rev.0 issued this date. 322 rev.1 was generated based on current information → slow or normal during transient. Don Young will review rev.1 and 3rd issue work on it while not be taken from SIC until // be issued.

3-16-75 Talk to Stan Young to see if we looked into this -
⁽¹⁰⁶⁷⁵⁾
WAS THE PLANT OPERATIONAL? SHOULD SPR 322 BE AMENDED? (in checklist)

SITE PROBLEM REPORT

BABCOCK & WILCOX

CUSTOMER NET ED	CONTRACT NO.	620-000 SPR NO. 322	REV. NO. 1
VENDOR BMS	P.O. NO.	TASK NO. 21	GROUP NO. 51 SEQ.NO. 01
SITE ENGINEER S. P. MAINOI		REQ'D. RESOL. DATE	REQ'D. COMP. DATE
TITLE LOW PRESSURIZER LEVEL FOLLOWING REACTOR TRIP			
DESCRIPTION OF PROBLEM			
SEE ATTACHED SHEET			
STATUS - ACTION TO DATE INCLUDING PERSONS CONTACTED			
L. M. Kolony of Engineering informed.			
FURTHER ACTION RECOMMENDED BY SITE PERSONNEL			
Review and implement Logic modification such that reactor trip should block calibrating integral RC 9.12, to achieve a slower cooldown rate of RG System and a more acceptable pressurizer level.			
This problem should be reviewed for all other sites.			
RESOLVED SOLUTION	Spinniger 10/4/74	<i>[Signature]</i>	10/4/74
APPROVED BY N.S. SUPPORT ENGINEER <i>SMH/14</i>	SIGNATURE	DATE	
TASK ENGINEER			
PROJECT MANAGER			
COST CATEGORY <input type="checkbox"/> NORM <input type="checkbox"/> C <input type="checkbox"/> D <input type="checkbox"/> G <input type="checkbox"/> L <input type="checkbox"/> VENDOR CLAIM			
AUTH CHARGE NO	<input type="checkbox"/> FIELD CHANGE REQ	FC NO	
SITE COMPLETION REPORT		<input type="checkbox"/> RECOMMENDED STDS. CHANGE	
COMPLETION DEVIATIONS <input type="checkbox"/> NONE <input type="checkbox"/> SEE SPR REV. NO.		FINAL DISTRIBUTION PROJECT MANAGER S.O.M. CONST. REP. CA DOC. FILE CENT. ENGR FILE 12M.2	
DATE COMPLETED S.O.M. CONSTR. REP. APPROVAL		SIGNED BY	
		DATE	

ATTACHMENT
SPR 342 Rev. 1

DESCRIPTION OF PROBLEM.

Following a reactor trip the pressurizer level goes as low as 40 inches. SPR 342 Rev. 0 pointed out the main reason that pressurizer level goes as low, because the trapped steam pressure in turbine header decays slowly, resulting in turbine bypass remaining open for time longer than is necessary.

Further examination of the reactor trip data revealed that immediately following the reactor trip the feedwater demand actually reduced to 20% instead of reducing to 5% (cross limit value as neutron power following the trip is zero).

This additional feed to steam generators contributes to the excessive cooling of the RC system and hence lower pressurizer level.

See attached RMC report on the subject.

PROBLEM REPORT

PRODUCT SYSTEM

ITEM NO.
1000FILE NO.
1000DATE TRACED
9/18/74FROM
R. S. Rand

EXN NO.

SL239

APN NO.

779

MAIL STATION NO.

P.O. Box 352

Middletown, PA 17057

SERIAL NO. AND/OR PART NO.

X

TO PROBLEM OWNER

MAIL STA. NO. 1000

CUSTOMER & PLANT

CNC
1000 ONLY

ADDRESS MAILED

150L

CUST. ADDRESS

2906-2

SHIP TO

DATE CODE

X

X

FOR FIELD USE

DAYS SERVICE

SERVICE

EXPENSES

MATERIAL

ATTACHMENT

PROBLEM: (Cont'd)

At this time the neutron error is very large and rapidly causes the calibrating integral to travel to its limit. Reference DWG D553732 and D556175E. When the Tave calibrating integral travels to its limit the effective neutron power error to the cross limit is reduced and therefore results in inadequate reduction in feedwater flow.

RECOMMENDATIONS:

On DWG D556175 T1 (Calibrating Integral Operation), Logic block should be added between RC D3.1 and RC D4.1. This logic block to read "IS REACTOR TRIPPED? (By Diamond)". If YES, Block calibrating Integral PC9.12; If NO, Proceed to RC D4.1.

DESIRED ACTION:

Please contact B&W to see if they would like to implement this ICS improvement.

APPLIES TO OTHER NES CONTRACTS: YES

APR 16 1975

THE BABCOCK & WILCOX COMPANY
POWER GENERATION GROUP

To : L.C. A. Creasy, Project Management

From : R. W. Wink, Control Analysis, EXT 2564

RWW

BOS 663-8

Cust. : Duke Power Company

File No.
or Ref.

Subj. : A Feedwater Pump Speed "Kicker" Circuit
for Occonee Unit #1 (and #2 and #3)

Date

April 16, 1975

This letter is copy and contains no secret or confidential information.

The following information on a modified Feedwater Pump Speed Control Circuit, which has been implemented at the TMI-1 Plant, is being forwarded at this time to allow incorporation prior to any additional load rejection tests scheduled for Units 1, 2, or 3. B&W recommends this as a temporary change to your ICS which will be followed up by a field change package.

The purpose of the Pump Speed "Kicker" Circuit is to enable the feedwater flow control system to continue to deliver a high level of flow to each Steam Generator, even though the steam outlet pressure has suddenly increased approximately 130 psi. The modification originated and implemented at TMI-1 improved the overall plant performance by directly increasing feedwater pump speed more rapidly than could be accomplished by the combined action of the feedwater control valve and pump speed controllers in the ICS.

The modification to the present Unit #1 ICS is the following:

Route an additional wire from the turbine header pressure error signal (IC/B on Drawing Unit #1) to two summers which are shown on Drawing D8032313F. The particular summers are FW28.8B(6-1-3) and FW28.12B(6-2-1) and the new signal is to be connected to each summer. In the new line also install a diode and a 100 k ohm resistor in a path to ground. Refer to the attached schematic.

The turbine header pressure control error signal has the following effective range:

+ 10 Volts = 300 psi above setpoint.
+ 0.5 Volts = 15 psi above setpoint.

Any signal below 0.5 Volts will be blocked by the diode in the new line.

The gain for the turbine header pressure error signal on each summer will have to be calculated and set by Duke Power Company. The calculation used at TMI-1 is given below:

1. Assume pump discharge pressure varies with the square of pump speed when suction pressure is constant.
2. For two feedwater pump operation find the pump speed (S_1) when the plant is at 100% power.
3. This speed corresponds to a turbine header pressure of 885 psig.
For a turbine header pressure of approximately 1050 psi the required pump speed would have to be: $(S_1) = (S_0) \sqrt{1050 + 885}$. The increase in pump speed ($S_1 - S_0$) represents a fraction of the total range of feedwater pump speed (2700 rpm to 5400 rpm at TM-1) and the output voltage of each summer should be adjusted to cause an increase in feedwater pump speed to (S_1) when the turbine header pressure error signal corresponding to 1050 psig occurs on each summer.

The following numerical calculation is only an example:

Assume (S_0) is 4500 rpm at 100% power. Then (S_1) is $4500 \times 1.089 = 4900$ rpm and $(S_1 - S_0) = 400$ rpm. Assume total speed range of feedwater pumps is 2700 to 5400 rpm or the total increase in pump speed is 2700 rpm. The gain at each summer is that which will cause a pump speed of 4900 rpm when the error in turbine header pressure is 155 psig.

If you have any questions, I would be happy to discuss them with you.

RWW:lr

cc: B. A. Krasch
A. W. Brown
W. Van Scoter
E. F. Ryan
W. E. Wilson
J. T. Janis
J. J. Galan
R. S. Rand (EM Co)

Q/A The information contained in this memo has been checked for applicability and completeness.

Signature R D Randall

Date 4/16/75

FEEDWATER PUMP SPEED "KICKER"
MODIFICATION TO THE ICS

FW 28.8.B

$$\Sigma$$

14 (spare)

6-1-3

DWG. D 8032313 F

FW 28.12.B


$$\Sigma$$

14

6-2-1

NOTE:

REMOVE BIAS SIGNAL ON
PIN 14 OF 6-2-1 COMING
FROM MODULE 4-10-9
PIN 4 AND RE-CONNECT
IT THROUGH A 1 MEG
OHM RESISTOR TO PIN
21 ON MODULE 6-2-1.



I C/B DWG. D 8032317 E

TURBINE HEADER PRESSURE ERROR SIGNAL

PROBLEM:

Steam lines between the instrument connections for Turbine Header pressure and Steam Generator pressure.

Attached please find charts recorded during a generator trip test conducted 8-13-74 which resulted in a reactor trip. From these charts and table 1 it can be noted that while there was flow through the line there was a pressure drop i.e., SG pressure is 30 psi higher than THP, immediately after the trip with no pressure drop due to flow the pressures equalized. For the next 3.5 min. the SG pressure is less than THP. Also note the waves in the SG pressure recorded during the first minute are not present in the THP pressure. These conditions seem to be a good indication that the check valves did close.

The fact that the Turbine Header pressure remains higher for a time holds the Turbine Bypass Valves open longer than necessary. (AFTER The Safety Valves have closed)

It is believed that this area could be improved by having the turbine bypass valves modulate to control Steam Generator pressure when the reactor is tripped instead of turbine header pressure. Getting these valves closed sooner after a trip should keep the Steam generator pressure from dropping so low which would keep the steam generator temperature higher and therefore TAVE. This should then keep the pressurizer level from dropping so low because it would not have to make up as much volume in the RC system.

PROBLEM 2:

On August 13 the generator breaker trip from 100% power transient was tested. The Reactor tripped on high RC pressure four seconds after the generator trip. After analysis of Reactimeter data it was observed that the system came very close to NOT tripping the reactor. We had previously sustained two turbine trips from 76% power without tripping the reactor. (The reactor did trip on the second turbine trip but not until the reactor had run all the way back to 20% power and this trip was due to operator error.) The most important item to be worked on to prevent reactor trip would be to reduce the maximum steam generator pressure immediately after the generator trip. This might be achieved by lowering the popping pressure on the last two banks of safety valves. In addition, the Emergency Relief Valve control could be modified to utilize the emergency relief valves (atmospheric dump valves) as additional steam relief capability. Presently the B1U limits as specified by BIA call for immediate reduction of feedwater flow demand to approximately 60% due to the rise in steam generator pressure from 910 psig to 1070 psig on a turbine trip. The elimination or delay of the B1U limits in this situation would help to maintain the required feedwater flow which would in turn tend to prevent overheating the primary coolant and to prevent the Reactor tripping on high RC pressure.

The attached logic and schematic drawings reflect a suggested way to utilize the atmospheric relief valves to open for overpressure at any time, whether the turbine bypass valves are available or not.

It must be considered that this change will substantially increase the use of these atmospheric relief valves and might increase their maintenance requirements.

DESIRED ACTION:

Contact B&W to see if they would like to implement either of these suggestions.


APPLIES TO OTHER NSS CONTRACTS: YES (ITEM 2)

TABLE I


Steam Generator pressure and Turbine Header pressure recorded during generator trip test 8/13/74 at TMI Unit 1.

	<u>SG Press.</u>	<u>TH Press.</u>	<u>THP-SG Press.</u>
Before the trip			
peak	912 PSI	882 PSI	-30 PSI
12 sec.	1080	1080	0
24 "	1063	1074	+16 PSI
36 "	1032	1059	+27
48 "	1008	1046	+38
1 min./60 "	984	1035	+54
12 "	966	1032	+66
24 "	948	1021	+73
36 "	930	1017	+87
48 "	926	1003	+82
2 min./60 "	936	1004	+69
12 "	962	997	+35
24 "	984	994	+10
36 "	986	987	+1
48 "	1002	996	+6
3 min./60 "	1008	1005	-3
12 "	1014	1011	-3
24 "	1032	1020	-12
36 "	1032	1023	-11
48 "	1020	1020	0
4 min./60 "	1020	1020	0


OPTION 1 C.R.
TURBINE BYPASSVALVE CONTROL




ALL INFORMATION IS THE PROPERTY OF SOUTHERN CALIFORNIA
EDUCATIONAL TELEVISION DISTRICT AND IS NOT
TO BE REPRODUCED, TRANSMITTED, OR GIVEN TO OTHERS
WITHOUT THE WRITTEN APPROVAL OF SOUTHERN CALIFORNIA
EDUCATIONAL TELEVISION DISTRICT.




THE DRAWING IS THE PROPERTY OF THE BOSTON METROPOLITAN PARKS
DEPARTMENT. THE DRAWING AND ANY REPRODUCTION OF IT MAY
NOT BE MADE OR COPIED EXCEPT WITH THE WRITTEN CONSENT OF THE
BOSTON METROPOLITAN PARKS DEPARTMENT.




D 2200BG






Part of Dwg
 D.553730
 Alternative TB control
 using STM 6011, press,
 Danner BMEZER 25T




Rising stem from
pressure to
control TB
valves



Part of
DWG D 553854




15.11
0


15.10
+75






GENERATOR TOP TEST FROM 100% & 8-1





250" 44



FRSP + LANTIGUE
TO 15 JUL 1944
4-4-4. 60%



100 Densified
Glass and
Ceramic



$6 \times 10^6 \text{ t/ha}$

9-2-1 Input 1

TRIP TANTON C.
TUE 9-1-12 8A.M. '12
6-4-12 000

100% POSITIVE

250"

Cu Strip - 1/2 2000 fm
4-4-12 11A.M. 2

0% POSITION

FIV Lecania E.
4-6-12 000
(with ETU limits)

100%
positive
showing
concentrate
up

6810⁶ #/cc
FIV DENDR "A"
(with ETU limits)


c pre

150

450

6 nL dilution
100 uL sample

GENERATOR Trip TEST From 100% of 8-



-25VDC

12X1Q^{6%}

F41 Value
DifferentiaL
10-4-1 INP 2

100%

Sig. To 5% Error 3%

Differential Value
10-4-1 INP 2
100% 200% 300%

100 PSID

0 PSID

F41 Value 2
Differential Press
10-4-1 INP 2

100 PSID


0 PSID

Differential Press
10-4-1 INP 2

Generator Pressure
Time in sec

Generator Trip Test from 100% of

Generator Trip TEST for 100% of



OPEN — TIME

"B" Express Valve Demand
2-9-10 OUT

CLOSED



1200 PSL
←1000 PSL

224 PSL


"E" Express Valve Demand
2-9-10 OUT

0 PSL



OPEN

"F" Express Valve Demand
2-9-10 OUT



OPEN

"G" Express Valve Demand
2-9-10 OUT



CLOSED

"H" Express Valve Demand
2-9-10 OUT

1200 PSI

← 1040 PSI

1032 PSI

1040 PSI

10" Street Side

2-9-13 Left

100 PSI

OPEN

10" Street Side

Left

CLOSED

OPEN

10" Street Side

Left

CLOSED

10" Street Side

Left

CLOSED

1200 PSI

← 1040 PSI

1020 PSI

1024 PSI

912 PSI

10" Street Side

2-3-13 Left

0 PSI

0.00
Tire Mark

(3)

SITE PROBLEM

REPORT TRANSMITTAL

**** CLEARED ****

TO: _____ For Information
Central Engineering Files
C. C. Plunkett - Contract Admin.
S. H. Klein - Quality Assurance
B. J. SHERPERD - Task Engineer
R. A. GLOVERS - Project Manager

FILE: 12M2
CONTRACT NO: 620-00 05
SPR 322 REV. 0
TITLE ICS PERFORMANCE
FOLLOWING GENERATOR-
REACTOR TRIP
DATE: 3-12-76

The attached, cleared SPR is submitted for your information.

TO: _____ E. L. Logan - FLORIDA _____
_____ L. C. Rogers - MET.ED. _____
_____ R. J. Baker - TOLEDO _____
_____ B. L. Day - Intl. Support _____
_____ P. E. Perrone - OFR _____
_____ J. L. Donnell - OFR _____

R.W. WINKS

L.M. KOLONAY

Attached is one copy of Site Problem Report No. 322 which was processed
on Contract 620-00 05. Future contracts have been reviewed for the
potential of a similar problem. This problem is ~~not~~ considered applicable
to other contracts →14

REMARKS:

cc: G. M. Jacks - Plant Integration
This SPR has been reviewed IAW NPG-1707-01

Chris C. Lockard
NUCLEAR SERVICE SUPPORT ENGINEER

CLEARED

SITE PROBLEM REPORT

BABCOCK & WILCOX

CUSTOMER EMCo	MET ED P.O. NO.	CONTRACT NO. 620-0005 SPR NO. 322 TASK NO. 21 GROUP NO. 01 SEQ.NO. 01	REV. NO. 0
SITE ENGINEER S. P. MAINGI		REQ'D. RESOL. DATE	REQ'D. COMP. DATE

TITLE ICS PERFORMANCE FOLLOWING GENERATOR-REACTOR TRIP

DESCRIPTION OF PROBLEM

- #1 Following a Reactor Trip the pressurizer level goes as low as 40 inches.
- #2 The Reactor Trips on high RC pressure within few seconds, following a Generator/Turbine trip at 100% power.
Per customer these situations are unacceptable. See EMCo. problem report attached.

STATUS - ACTION TO DATE INCLUDING PERSONS CONTACTED

R. Winks of Control Analysis and L. H. Kolony of Engineering are made aware of the problem.

FURTHER ACTION RECOMMENDED BY SITE PERSONNEL #1 Issue field change covering Turbine bypass Valves control signals following the reactor trip should be from OTSG's.

#2 To review recommendations in EMCo problem report, specially elimination or relaxation of BTU Limits and lowering settings on last two banks of safety valves.

SPONSOR SIGNATURE	4125174	STTR REP. SIGNATURE	4/30/74
-------------------	---------	---------------------	---------

RESOLUTION 1) EC-174
2) Letter, L.C. Rogers to J.B. Herbein dated 5-27-75 (attached)

APPROVED BY	SIGNATURE	DATE
N S SUPPORT ENGINEER	Miles Vanlike	2/2/76
TASK ENGINEER / S. P. Maingi	Project - No REC	2/2/76
OPS Manager	JTB	2/19/76
PROJECT MANAGER	R. Winks	2/19/76
COST CATEGORY	<input type="checkbox"/> NORM <input type="checkbox"/> C <input type="checkbox"/> D <input type="checkbox"/> G <input type="checkbox"/> L <input type="checkbox"/> VENDOR CLAIM	
AUTH CHARGE NO	<input type="checkbox"/> FIELD CHANGE REQ	FC NO.

COMPLETION	SITE COMPLETION REPORT		<input type="checkbox"/> RECOMMENDED STDS. CHANGE
	SEE ATTACHMENT		
DEVIATIONS	<input type="checkbox"/> NONE <input type="checkbox"/> SEE SPR REV. NO.		FINAL DISTRIBUTION
DATE COMPLETED	1/19/76	SIGNED BY S. P. Maingi	PROJECT MANAGER S.O.M. CONST. REP. QA DOC. FILE CENT. ENGR FILE 13112
S.O.M. CONST. REP. APPROVAL	L. C. Rogers	DATE 1/19/76	

COC
RE
SE
E
che
a

LVER

rip

tion
f sa

11/31

125

VER

REC
STD

L DIS
ECTA
M /C
OC
T EN
125

SITE COMPLETION REPORT

1. Field change 174, changing Turbine Bypass Valve control to CTP. Pressure rather than Turbine header pressure has been implemented.
2. New relaxed BTU limits have been incorporated.
3. Relief settings on the two main safety valves have been reduced from 1092 PSIG to 1050 PSIG.

All these steps will help run the reactor back to 15% power on a Turbine/Generator Trip, so the SPR is being closed.

S.W. Wilcox

Babcock & Wilcox

Plant Engineering Group

P.O. Box 1100-1, Middletown, Pa. 17057
Telephone (717) 394-5111

May 27, 1975

REM-I-104

Mr. J. G. Herbein
Metropolitan Edison Company
Post Office Box 480
Middletown, PA 17057

Subject: Revised BTU Limits for TMI-I

Reference: REM-I-62, L. C. Rogers to J. G. Herbein dated May, 1975

Dear Mr. Herbein:

B&W Engineering has recently completed work on the revised curves for the BTU Limit circuit for TMI-I in preparation for plant operation and testing associated with the proposed turbine trip or load rejection test at rated power. Attachments include these curves and an appropriate table.

An analysis of plant operational characteristics during the January 23, 1975, power runback transient has led to a revision of the curves comprising the BTU Limit circuit. Figure 1 (attached) shows the revised curves which can be incorporated into the ICS at the first opportunity. Comparison with the curves of Figure 2 which are currently in use reveals that the steam pressure limit is significantly expanded, whereas the T hot curve is more limiting at lower temperatures and power levels. The feedwater temperature curve was changed to properly represent the effect of feedwater temperature on feedwater flow and steam superheat. Also, reactor coolant flow has been changed slightly. These revised curves are to be utilized for all plant operation from now on and are not only associated with the proposed plant runback tests.

The revised BTU Limit curves were tested on the B&W Old Forest Ford PWR simulator for several major transients and the TMI-I type plant with the new BTU Limits performed very well. When compared with the old curves, the new limits provided greater operating margin at full power.

The development of the revised curves was accomplished by using the B&W certified steam generator computer code and determining the limits for the four parameters which comprise the BTU Limits to exceed or maintain 35°F superheat. After incorporating the curves into the simulator ICS, the following operational transients were incorporated:

- (a) ramping power up and down with both 3 and 4 RC pumps operating

R. J. G. Hartain

-2-

5/27/75

(b) tripping 1 NC pump at 75% power level

(c) tripping the turbine at 100% power level

All of these transients were performed successfully without a reactor trip. In addition, transients in which the feedwater flow had to be limited were performed and the control of the feedwater flow by the new BTU Limits was excellent. Sufficient testing of the new BTU Limit curves has occurred and fewer operational problems should develop at TMI-1 since the BTU Limits are less restrictive than the curves presently in use.


The accompanying table presents the specific information which defines each of the four curves in the BTU Limit circuit.

Additional information with regard to lowering the setpoint for pressurizer electromagnetic relief valve, is included and has been reviewed by the Control Analysis Group of Babcock & Wilcox.

The effect of lowering the setpoint of the pressurizer electromagnetic relief valve from 2255 to 2205 psig has been analyzed and will flow an additional 56 lbs of steam to the Quench Tank during a very severe transient.

If you have any further questions, please contact me.

Very truly yours,



L. C. Rogers
Resident Engineer Manager

LCR/SPM/can

cc: J. J. Colitz
J. D. Pinney
K. F. Schmidt
D. B. Tulodieski
~~D. W. Winks~~
R. S. Rani

TABLE I

Revised ETU Limits for TMI-1

Steam Generator Pressure

Pressure psig	Feedwater Limit - %
Equal to and less than 1000	106
Equal to and more than 1125	50

RC Flow (Temperature compensated - each loop)

Flow Rate - 10^6 lb/hr	Feedwater Limit - %
0	0
80	120

Reactor Outlet Temperature (OTSG Inlet Temperature)


Temperature, F	Feedwater Limit - %
575	0
604	118


Feedwater Temperature

Temperature, F	Feedwater Limit - %
100	60
500	106

46.07:0

WELL HEAD PRESSURE, PSIG

C
C
C
C



(2)

SITE PROBLEM REPORT
TRANSMITTAL FOR ACTION

FEB 26 1976

TO: L Rogers For Action
For Action
For Action
TO: RW Winkler For Information
R Cokers For Information
For Information
For Information

RECEIVED

Contract: 620-00 83

SPR Number: 322 v440

Title: JCC Performance
following Item - By
trip

Date of Transmittal: 2-17-76

Reply Required By:

Action Requested: L Rogers is requested to complete
SPR 322-0 when necessary actions are completed

Reply and Return This Transmittal to:

Mike Vandiver
Nuclear Service Support Engineer

Reply: SPR was signed off 1/19/76
and returned to OPR. The agency
Closes the SPR now that the original finally
was returned to the LCR

This problem is/is not considered as applicable to other contracts: NSS-

(Signed)

cc: C. C. Plunkett - Contract Administration
S. H. Klein - NPG Quality Assurance
B. L. Day - Intl. Support
R. J. Baker - Toledo
L. C. Rogers - Met Ed
E. L. Logan - Florida
P. E. Perrone - OFR