

DUKE POWER COMPANY

POWER BUILDING

422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28201

A. C. THIES
SENIOR VICE PRESIDENT
PRODUCTION AND TRANSMISSION

P. O. Box 2178

March 15, 1974

Mr. Norman C. Moseley, Director
Directorate of Regulatory Operations
U. S. Atomic Energy Commission
Region II - Suite 818
230 Peachtree Street, Northwest
Atlanta, Georgia 30303

Re: RO:II:FJ
50-269/74-1

Dear Mr. Moseley:

Please find attached our response to Items I.A.b and I.A.c listed in
RO Inspection Report 50-269/74-1.

Duke Power Company does not consider any information contained in RO
Inspection Report 50-269/74-1 to be proprietary.

Very truly yours,


A. C. Thies

ACT:vr
Attachment

7912040555

DUKE POWER COMPANY
OCONEE UNIT 1
RESPONSE TO RO INSPECTION REPORT 50-269/74-1

I.A.b. Incomplete Power Runback Following a Failed Rod

When the runback occurred on November 20, 1973, the operator brought the power level as indicated by core delta temperature to less than 60 percent of rated power as required by Technical Specification 3.5.2.2e. The operator did not reduce the unit load to less than 55 percent full power as required by EP/O/A/1800/21, "Inoperable Control Rod."

The requirement in EP/O/A/1800/21 to reduce unit power to 55 percent when a control rod is inoperable was a self-imposed reduction of 5 percent below the power level requirements of the technical specifications. It was intended to provide margin to prevent violations of technical specifications. At the present time, the station operations group has initiated a complete review of procedures which contain operational limits more restrictive than those contained in the technical specifications. Where these operational limits exist, they will be re-identified as guides for the operator or they will be changed to limits which are more compatible with the technical specifications. In addition, the necessity of following operating and emergency procedures has been emphasized to operations supervisors at shift supervisors meetings and in a memorandum issued on January 29, 1974 by the Operating Engineer.

I.A.c. Withdrawal of Rods During an Unscheduled Power Reduction

When the power runback was initiated on November 20, 1973 because of a dropped control rod, the pressurizer spray valve opened to maintain reactor coolant system pressure. When pressure stabilized, the spray valve was given a close signal by the control system but did not respond. Consequently, reactor coolant system pressure continued to decrease. As pressure decreased, attempts were made to close the pressurizer spray valve and block valve by remote manual action to secure the pressurizer spray, but these attempts were unsuccessful.

As reactor coolant system pressure neared the low pressure trip point, the control operator momentarily withdrew control rods to halt the pressure decrease. A plot of reactor power during this period showed that power increased less than 1 percent from 55 percent full power. This change in reactor power was insignificant, and the operator and an Assistant Operating Engineer who was in the control room at the time of the power reduction had full knowledge of the event that had led to the power reduction.

In the limits and precautions section of operating procedure OP/1/A/1102/04, "Operation at Power," it is stated that in the event of an unscheduled power reduction, the power level shall not be increased until an investigation has been conducted and any necessary corrective action taken. In the incident cited in this inspection report, the operator and Assistant Operating Engineer were fully knowledgeable of the plant conditions that had led to the power

runback, and corrective action was being taken to close the pressurizer spray block valve to halt pressurizer spray and thus prevent further decrease in system pressure. The operator withdrew rods to gain more time to close the block valve.

As stated in the "Steam Production Department Administrative Policy Manual for Operational Quality Assurance of Nuclear Stations," written procedures cannot address all contingencies, and therefore, should contain a degree of flexibility appropriate to the activities for which each is applicable. The precaution in the procedure for operation at power was not intended to preclude operator action required to stabilize plant conditions, especially as in this incident, when such action was taken with full knowledge of the cause of the transient and within the flexibility permitted by procedures. Such action also precluded an unnecessary trip from low reactor coolant system pressure and unnecessary injection of borated water.

Letter to Duke Power Company from N. C. Moseley
dated APR 19 1974 50-269/74-1

Letter from Duke Power Company, A. C. Thies,
dated March 15, 1974

DISTRIBUTION:

H. D. Thornburg, RO
RO:HQ (4)
Directorate of Licensing (4)
DR Central Files

cc encl. only:

PDR
Local PDR
NSIC
DTIE, OR
State