

HARPSTER FIELD NOTES

IE Co

B & W

J. EVANS

F. FAIST

B & W

NUCLEAR
SERVICES

B. GREEN

B. BYER

D. MICHAELS ASST. ENG.

L. STAUFER

D. DIBERT

20


POOR ORIGINAL

8001160 530

initial information 9/26

- ① steam feedwater system control system logic failure apparently initiated the MSIV isolation
- ② cause of electromagnetic relief sticking open was pilot valve stuck open. K valve had been recently worked on, causing relief with integral pilot valve assembly

9/27



max cooldown rate was 35° in 7 min but did not exceed $10^{\circ}/hr$

②

was boiling in core, confirmed by source range spikes in press-temp ranges

35 x 10
(100%/hr)



close relay (seal in relay) was missing from electro relief

cyched about 2255. psig

boiled 36 dry. minor insulation is off ~ 40% around 56' 8-10' high

- ① B & W evaluating cooldown
people coming in tonight
- ② cables to degassing heaters
were wetted & some required
low - are presently
anticipate finishing insulation
Wednesday, Saturday & clean
up in a couple of days

flow indicators
and feed water
per heater

POOR ORIGINAL

2/28 critique

- no indication of start-up feed valve position at ICS station - only demand signal
- no positive indication of electronic relief valve position
- reconstruction

start-up feed valve shut
low level #2 SG

PCS press & temp increased
relief & spray cycling

~~PCS~~ ICS level \uparrow - 226"

Rx manually tripped

SFAS trip, AT injection

ICS level \uparrow

rupture disk blew

relief stuck open

was there
time when
#1 injection
shut by in
due to marking
to BUST

discrepancy between alarm loggers
& readimeter data (to be on)

sewing of RCP's

never got to any stopped alarm

ICS level \uparrow & flat at 320"

(press decreasing)

#2 SG was dry

#1 SG ?

POOR ORIGINAL

because level indication on SG is
DP cell indication flattened out
at low level

pan (uncompensated level) appeared
that to be solid - also no pipe
spikes

what observed temps 580°
 $T_c 509^{\circ}$

was put
back in
auto
later

and had temp gov problem - #3 had
to be put in manual (~40 sec later)
it was ~¹⁵⁻20 min till block valve
in series with electro relief was
closed

had any
acc with
discharge &
crosscomp
when seen
2600
was low
try blocks

cause of starting a feed who
starting in manual half
try still unknown

previous event may have
as similar problem - tub
alarm 1951 ✓

letdown for long time when
PET level up

POOR ORIGINAL

Fct written for indicating lights
on electric shelf (may split the
false indications)


asked for ~~the~~ interval on RC-11
below 2100" which would shut

asked for by trying following SFPCS try

when on start values < 80% without
block (man) open half try (2)
closes - can this logic be improved

appears one problem is operators
and unclear on SFPCS system operation

as gears
would be
rotated
single fail
attempt



note there is always this problem
at < 35% power

there also is surveillance test
where jumper is installed when
slip with jumper would
cause same transient

POOR ORIGINAL

would steam go, had gone dry if
ATP governor had worked - apparently
state was aware of governor problem
since January

BEW will provide evaluation
of press; Henry expansion

BEW is evaluating core effects

BEW is evaluating SB dry

F&E has been written to replace
air feed pump governors

also investigating shut-down
procedure for ATP - pumps will
not come up right if dry
shut down exactly right

~~check~~ (problem with hydraulic
press (critical) when
shutting down)

checking on ^{status} relay for electro relief

may have been outside limit on
containment annulus diff press.

alams may not seal in on shell
trip of computer may not pick up
if it comes & goes

POOR ORIGINAL

9/30 Meeting

relief block valve closed at 20 min
cont press reached 4 psia

SFRCS

SFRCS $\frac{1}{2}$ trip in $\frac{1}{3}$ of channel 2
(wasnt sealed in)

$\frac{1}{2}$ trip sealed in on 115. ✓

other $\frac{1}{2}$ trip on 56 low level

trip
performed
trial
35 msec

→ efforts to track down trips

all surveillance test ✓

all setpoints ✓

found 4 connections not tight (1 obvious)
(was in channel 3 & did not cause this
incident)

others were not as bad but could
have caused trip (press switch
on main steam line)

* t_1 actuated device seals in but
aban does not so it must (signal)
remain in for full sec for
computer scan to pick up

there were 2 other SFCS initiations

9/19 read

1/2 event appears to have similar
1/2 trip initiation

both 9/3 & 9/34 events gave unexplained
channel 2 1/2 trip which closed
start up control valve

to press (steam)

to level 56

SI? across valve

} all will close
50 valve & give
up 1/2 trip

== Aux feed

saw 3600 RPM

switched to manual & turbine ↑ 3600 RPM

normal shutdown procedure requires
gov to be required to be full open
torque at shutdown causes binding
of ~~the~~ linkage & gov may not
be full open

a special procedure had been
worked out in fact to try to
preclude this problem

POOR ORIGINAL

in trying to reconstitute pump was started
4 or 5 times & once loading problem
reoccurred.

- 3 potential fixes
 - put on slow speed stop at shutdown
 - put on slower motor
 - put on limit switch to stop track

Tommy Taylor
Woodward
Governor

power relief valve

2255 \uparrow open
2205 \downarrow close

close relay missing
which provides seal in

to keep valve open till 2205
this caused power relief to cycle ~ 9 times
about 2265

relay was scheme checked & in place
during prep & tested with simulated
pressures
cause of removal unknown now

stem on Crosby full valve was
bent - replaced with

Crosby man said rapid actuation
caused failure & subsequent
failure to open if relief

plan to simulate ~~to~~ signals to verify
proper operation - relay has been replaced

Pressure expansion & transient

2 times during expansion

reconstruction of data - fuel steam
formation for ~ 6 min in RCS

most likely in RCS suction (lowest ^{of steam} temp)

heat input from decay heat, metal, & RCS ^{or heating}

pump problems ~ 6 min & ~ 16 min

steam formation also likely along
heated surfaces)

seal return line was isolated putting
full system press on merger seal
(designed to handle this)

may be govern with loss of head
on hydrostatic beams

3 pumps have operated since
treatment with ~~no~~ problems

POOR ORIGINAL

Fuel

max SP across fuel clad - 300, OSID
about 6 min into transient

preliminary evaluation shows no concerns

Stresses

does not appear to have caused problems
are presently evaluating cyclic contribution
against code limitations to see if fatigue
life shortened

this transient did exceed analyses
transient 3200-800 15 min

this transient quicker

Physical damage in containment

quench tank rupture disk 18"

ventilation duct bent & lowered ~~vent~~
(repairs)

~10 stuff hanging
~20 on floor
min insulation removed ~ 1/3 way
around SG ; paint removal

39 new pieces were installed

POOR ORIGINAL

press heater cables wetted (13 or 14)
- were dried out (originally measured low)
4 cables had some physical damage
which probably occurred before the
- were returned for repair ^{or replacement}
201° meters were measured
fire detectors above 201 were damaged
by steam & replaced
1 lighting fixture dislodged

Chemistry

Chromium 51
Zinc 97
Cobalt 68
Sodium 57

core samples indicated almost
nothing & mostly corrosion products
some $\rightarrow \sim 10^{-6}$ ug/cc iodine
is normal from surface
contamination

no carbene was detected before
entry
surface contamination $\sim 40,000$ DPM
/ .20 cm²

POOR ORIGINAL

boic acid crystallization under
minor on SG - evaluated to be
no problem.

H₂O injection - no indication

48 am

2 makeup pumps were on supplying
140 GPM which prevented flow from
H₂O pumps

discharge press of makeup pumps were
higher than H₂O pumps

Aux feed w/ cross connect - performed
properly operator had blocked

thermal shock SG - within B₂W
envelope previously analyzed

(assumed temp was considerably
higher) (analyzed temp is
43°)

Contained annulus ΔT

not out of spec

POOR ORIGINAL

there are no safety related cables
affected by general tank rupture
(previously reviewed for FSAR BY PFW)

POOR ORIGINAL

10/5/77

Closet visit

SG dry - if AF₁ work properly

(1) on dbl ended steam line
break - safety analysis indicates
both SG would go dry & reflux

(2) on feed system - SG would
not go dry

on small break affected SG would
go dry

POOR ORIGINAL

relay

no work orders issued for relay
relay is held in place by 2 screws
(plug in type)

subsequent review has shown 5 other
empty sockets & 11 empty fuse
holders - are still reviewing to
determine if these are spares

relay was tested in pres. & AFT
also was scheme checked

tech spec violations
none - all action statements
were met

Day 56

BEW defines Day 56 as
(lower instrument tray) - 8" above
tube sheet 6"

POOR ORIGINAL

Immediate action letter

① actual cause of 1/3 trips not known
(loose connections)

plan to connect ~ 10 brush recorders
to various points in SFCCS system
to provide continuous monitoring of
selected parameters (temporary fix)
if nothing is found would conclude
(tightening) connections was fix

evaluating time delays for
SFCCS alarms

presently annunciators only on low
steam press trips

are planning to provide annunciator
windows for 1/3 trips

	<u>windows</u>	<u>trip</u>
	1	full SFCCS
	1	RCF's
(expts)	2	lg steam press
	2	ls level
	3	SG DP

FOR ORIGINAL

only cable calls would be within
control room - info already available
in computers with exception of
full BFRCS trips

(2) B & W has verbally confirmed these
as result of cooldown were within
acceptable limits - will follow
with hard copy

(3) same as (2) will follow in the

(4) SG was omitted because AFI did
not come up to speed (consider
definition of chf)

(5) AFI not up to speed because of
procedure for setting gov at
high speed stop

Both governors are at Woodward
in Colorado - are installing
position switch which alerts
operator if not on low speed
stop

Lowell Doe is submitting
part 21 report

WD

1/11/80
1/11/80

POOR ORIGINAL

signal to Bodine is level error
{ above setpt drives down
{ below setpt drives up

electro relief - seal in relay \rightarrow 225.7
missing \rightarrow 230.5 \downarrow

rapid cycling deformed pilot valve stem
which causes pilot to stick open

plan to test with simulated press using
position indicator switch is being
installed

SFKCS causing initial half trips

Training

Lesson plans have been prepared to
initiate training for operators on
SFKCS

starting training next Wednesday
all operators will go through
in (3-5 weeks)

probably 2-4 hour sessions
probably complete by 10/30

POOR ORIGINAL