

MANAGER, LICENSING, NPGO  
(CC: QUALITY ASSURANCE)

R.C. Janzen, Jr.

 SIGNIFICANT DEFICIENCY

LOG NO. FSC 10-734

 SUBSTANTIAL SAFETY HAZARD FILE NO. T4.4

CONTRACT NO.

LOCATION: ECCS Analysis

 MISC. REPORTABLE ITEM

PAGE 1 OF \_\_\_\_\_

WHICH AND IDENTIFY, BY PAGE NUMBER, ANY SUPPORTING INFORMATION/DOCUMENTS

WHICH AND ON WHICH PLANT WAS THE SAFETY CONCERN IDENTIFIED?

April 7, a 0.04-ft<sup>2</sup> small break analysis at pump discharge on the SMUD plant was conducted. Results show substantial core uncoverage. TO YOUR KNOWLEDGE IS CUSTOMER AWARE?  YES  NO

WHEN &amp; HOW \_\_\_\_\_

 TO YOUR KNOWLEDGE IS NRC AWARE?  YES  NO

WHEN &amp; HOW \_\_\_\_\_

## AFFECTED CONTRACTS (CUSTOMER NAME AND LOCATION)

Units 1, 2, and 3 (Duke Power Corp.), Crystal River 3 (Florida Power Corp.), TMI-1 (Ed.), TMI-2 (JCP&amp;L), ANO-1 (Arkansas P&amp;L), Midland 1 &amp; 2 (Consumer's Power)

## DESCRIPTION OF SAFETY CONCERN-IDENTIFY AFFECTED COMPONENT(S), SYSTEM(S) OR ACTIVITY/SUPPLIER, AND IMPACT ON PLANT OPERATIONS

small breaks at the pump discharge on the 177-FA Lowered Loop Plants (identified above), the HPI pumps are inadequate to control the accident to the criteria of CFR 50.46. The analysis performed for a 0.04-ft<sup>2</sup> break at the pump discharge shows core uncoverage starting at ~1700 seconds. The mixture level in the core at 0 seconds is less than 4.0 ft. This level is inadequate to maintain cladding temperatures below 2200F. Long-term cooling will not be established by the HPI until ~8200 seconds. Thus, the inadequate level at 2400 seconds is not even minimum level that will be reached during the accident.

28

POOR ORIGINAL

## BE CORRECTIVE ACTION COMPLETED/TO BE INITIATED

Fully Q/A the results.

Identify and analyze hardware fixes (it is expected that cross-connecting each HPI to all four cold legs will result in an acceptable fix). Report and document results to the NRC.

8001170 864

A

PWR UNIT ECCS Analysis, Fluid Systems Analysis, Plant Integration

DATE AND DATE

2/1/78

TSD/DR 4/4/78

BABCOCK & WILCOX COMPANY  
POWER GENERATION GROUP

DISTRIBUTION

J. H. TAYLOR - MANAGER, LICENSING (2817)

*Edward R. Knight*

EDS 663.5

File No. 205 T4.4  
or Ref. PSC 10-78

PRELIMINARY REPORT OF SAFETY CONCERN  
PSC 10-78

Date

APRIL 12, 1978

This letter is to cover one customer and one subject only.

DISTRIBUTION

R. C. Jones  
B. M. Dunn  
A. L. MacKinney  
J. P. Jones  
W. A. Cobb  
B. A. Karrasch  
B. B. Cardwell  
D. W. Berger

J. C. Deddens  
J. J. Stewart  
G. M. Olds  
D. H. Roy  
A. H. Lazar  
E. G. Ward  
L. J. Stanek  
J. D. Phinney

C. D. Russell  
R. C. Luken  
J. T. Janis  
G. T. Fairburn  
F. J. Levandoski  
E. R. Kane  
H. A. Bailey  
D. Mars  
Record Center

In accordance with procedure NPG-1707-01, "Processing of Safety Concerns," I am forwarding a reported concern relating to small breaks at the pump discharge on the 177FA Lowered Loop Plants. PSC 10-78 has been assigned as the PSC number for this case.

A preliminary indication is that this concern will be reportable to the NRC under the requirements of 10 CFR 21. Effort is now in progress on preparing an evaluation and on recommendations for possible corrective action. When my staff has completed its evaluation report, I will communicate their findings to you.

The point of contact within Licensing on this case is H. A. Bailey, Ext. 2678.

JHT:dsf  
Attachment

POOR ORIGINAL