

14 + 15

SITE PROBLEM
REPORT TRANSMITTAL

*** CLEARED ***

TO: _____ For Information
Central Engineering Files
C. C. Plunkett - Contract Admin.
S. H. Klein - Quality Assurance
R. S. SHEPHERD - Task Engineer
R. A. GIVERS - Project Manager

FILE: 13-5-322
CONTRACT NO: 620-00 05
SPR 322 REV. 1
TITLE LOW PRESS.
LEVEL FOLLOWING
REACTOR TRIP
DATE: 6-25-76

The attached, cleared SPR is submitted for your information.

TO: _____ E. L. Logan - FLORIDA _____
_____ L. C. Rogers - MET. ED. _____
_____ R. J. Baker - TOLEDO _____
_____ B. L. Day - Intl. Support _____
_____ P. E. Perrone - OFR _____
_____ J. L. Donnell - OFR _____

L.M. KOLONAY

Attached is one copy of Site Problem Report No. 322 which was processed on Contract 620-00 05. Future contracts have been reviewed for the potential of a similar problem. This problem ~~is~~ is not considered applicable to other contracts 00.

REMARKS: _____

cc: G. M. Jacks - Plant Integration
This SPR has been reviewed IAW NPG-1707-01

Chris C. Lockard
NUCLEAR SERVICE SUPPORT ENGINEER

CLEARED

POOR ORIGINAL

8001170898

A

SITE PROBLEM REPORT

BABCOCK & WILCOX

CUSTOMER	MET ED	CONTRACT NO.	620-0002	SPR NO.	322	REV. NO.	1
VENDOR	BNCO	P. O. NO.		TASK NO.	21	GROUP NO.	01
SITE ENGINEER	S. P. MAINGE	REQ'D. RESOL. DATE		REQ'D. COMP. DATE		SEQ. NO.	01
TITLE LOW PRESSURIZER LEVEL FOLLOWING REACTOR TRIP							
DESCRIPTION OF PROBLEM SEE ATTACHED SHEET							
STATUS - ACTION TO DATE INCLUDING PERSONS CONTACTED L. M. Kolony of Engineering informed.							
FURTHER ACTION RECOMMENDED BY SITE PERSONNEL Review and implement logic modification such that reactor trip should block calibrating integral RC 9.12, to achieve a slower cooldown rate of PC System and a more acceptable pressurizer level. This problem should be reviewed for all other sites.							
APPROVED BY <i>Spencer</i>		DATE 10/4/74		SIGNATURE <i>L. M. Kolony</i>		DATE 10/9/74	
RESOLUTION SEE COMPLETION REPORT							
APPROVED BY		SIGNATURE			DATE		
N. S. SUPPORT ENGINEER		<i>Chris C. Lockard</i>			6-23-76		
TASK ENGINEER/NS UNIT MGR		<i>Ho M. Kolony</i>			6/23/76		
OP. PLANT MGR.		<i>[Signature]</i>			6/24/76		
PROJECT MANAGER/SERVICE MGR.		<i>[Signature]</i>			6/23/76		
COST CATEGORY <input type="checkbox"/> NORM <input type="checkbox"/> C <input type="checkbox"/> D <input type="checkbox"/> G <input type="checkbox"/> L <input type="checkbox"/> VENDOR CLAIM							
AUTH CHARGE NO				<input type="checkbox"/> FIELD CHANGE REQ		FC NO	
SITE COMPLETION REPORT FURTHER INVESTIGATION SHOWED THAT OPERATOR PUT FW CONTROL IN MANUAL. THE PROBLEM RESULTED FROM OPERATOR ACTION INSTEAD OF AUTOMATIC ICS ACTION. RECOMMEND SPR BE CLOSED. <i>(R. S. King) BNCO det/76</i>						<input type="checkbox"/> RECOMMENDED STDS. CHANGE	
DEVIATIONS <input type="checkbox"/> NONE <input type="checkbox"/> SEE SPR REV NO. _____						FINAL DISTRIBUTION	
DATE COMPLETED						PROJECT MANAGER	
S O M CONSTR. REP. APPROVAL <i>[Signature]</i>						S O M CONSTR. REP.	
DATE 6/23/76						QA DOC FILE	
						CENT. ENGR	
						FILE 131 2	

POOR ORIGINAL

ATTACHMENT
SFR 322 Rev. 1

DESCRIPTION OF PROBLEM:

Following a reactor trip the pressurizer level goes as low as 40 inches. SFR 322 Rev. 0 pointed out the main reason that pressurizer level goes as low, because the trapped steam pressure in turbine header decays slowly, resulting in turbine bypass remaining open for time longer than is necessary.

Further examination of the reactor trip data revealed that immediately following the reactor trip the feedwater demand actually reduced to 20% instead of reducing to 5% (cross limit value as neutron power following the trip is zero).

This additional feed to steam generators contributes to the excessive cooling of the RC system and hence lower pressurizer level.

See attached HMCo report on the subject.

POOR ORIGINAL

PRODUCT SYSTEM FILE NO 1506	FILE NO 1506	DATE OF PROBLEM 9/4/74	FROM R. S. Hand
DATE OF SERVICE 1506	DATE OF SERVICE 1506	DATE OF SERVICE 1506	ACCT NO. 81239
DATE OF SERVICE 1506	DATE OF SERVICE 1506	DATE OF SERVICE 1506	ACCT NO. T79
DATE OF SERVICE 1506	DATE OF SERVICE 1506	DATE OF SERVICE 1506	MARK STRIP NO. FU Box 352
DATE OF SERVICE 1506	DATE OF SERVICE 1506	DATE OF SERVICE 1506	Middletown, PA 17057
DATE OF SERVICE 1506	DATE OF SERVICE 1506	DATE OF SERVICE 1506	SERIAL NO. AND/OR PART NO.

TABLET IMPROVEMENT

References by IR# of 9/23/74

On 9/4/74 Mat. Ed. Plant Superintendent, Jack Herbein stated that "On a Reactor Trip the pressurizer level should not drop as low as it does. (to approximately 40 inches) Analysis of the 8/13/74 Generator Breaker trip test reveals the cross limits from neutron power error to feedwater flow control did not perform as expected. The neutron power error cross limit should have reduced the feedwater demand immediately after reactor trip to approximately 5%. The neutron power error cross limit actually reduced the feedwater flow demand to approximately 20%. This additional feed to the steam generators contributed to the excessive rate of cooling of the EC system and the resultant drop in pressurizer level.

The reason for the above undesirable performance is as follows. On a reactor trip the CED system transfers to manual. When the CED is in manual the neutron power error is applied to the V_{avg} calibrating integral.

EFFECT ON SYSTEM (BRIEFLY):
Pressurizer level less than 60 inches cuts off heaters.
EC pressure can not be controlled.

CUSTOMER ATTITUDE: MAJOR CONCERN
 CONCERNED
 UNCONCERNED

DATE SOLUTION REQUIRED: 10/14/74 OR INFO. ONLY

COPY ON SEPARATE SHEET

SIGNATURE: [Signature] DATE: 9/27/74

FOR FIELD USE

DAYS SERVICE 0
SERVICE 1
EXPENSES 2
MATERIAL 3
SEC NO. P72-236

ALLOCATION
 PRODUCT
 PRODUCT APPLICATION
 SYSTEM
 SYSTEM APPLICATION
 WARRANTY
 OTHER

DEFECTIVE BY IT RETURNED
 NO
 YES ON _____ DATE _____
RM NO. _____

FAILURE OCCURRED
 ON RECEIPT
 IN SERVICE (WARRANTY)
 IN SERVICE (NON-WARRANTY)

POSSIBLE CAUSE FOR PROBLEM
80 FAULTY MATERIAL
81 FAULTY MANUFACTURING
82 FAULTY DESIGN
83 PERFORMANCE DEFICIENCY
84 FAULTY PACKAGING
85 COMPONENT FAILURE
86 WEAR/OUT
87 IMPROPER APPLICATION
88 OPERATING ENVIRONMENT
89 INSUFFICIENT INSTRUCTIONS (DOCUMENTATION)

REPORT OF INVESTIGATION & CORRECTIVE ACTION (BY FIELD IF APPLICABLE)

OPERATING CONDITIONS: **EA**

AMBIENT TEMP: _____ °C/F

ATMOSPHERE: CLEAN
 AVERAGE DIRTY

HUMIDITY: HI LO AVG.

TIME REQUIRED TO: **EA**

REPAIR: _____ TROUBLESHOOT

RECALIBRATE: _____

FAILURE DETAILS: **EA**

BMCC PART NO. _____

DESCRIBE (DIODE, CAP, TRANSISTOR, ETC.) _____

CIRCUIT SYMBOL (C, R, G) _____

MFG OF PART (IF KNOWN) _____

HOW PART FAILED:
 SHORT OPEN
 MECH. DAMAGE
 ADJUSTMENT
 DIRTY UNKNOWN
 OTHER (DESCRIBE) _____

FOR USE ONLY:

PROBLEM TYPE	FAILURE ORDER CODE	THE SYSTEM	ANALYSIS	ACTION TAKEN BY

COPIES: _____

QUALITY ASSURANCE
MFG LIABILITY
MFG PLANNING
NPO
FPO
CONTRACT OPER
WARRANTY REPAIR
COORDINATION ENGR
JOB SERVICES
ORDER CENTER
COMPONENT ENGR

PRELIMINARY ANS
 FINAL SOLUTION

SIGNATURE: _____ DATE: _____

FOLLOW UP ON CORRECTIVE ACTION

DEPT	MAN	HRS

DEPT	NAME	PART NO.	COMMENTS

POOR ORIGINAL

ATTACHMENT

PROBLEM: (Cont'd)

At this time the neutron error is very large and rapidly causes the calibrating integral to travel to its limit. Reference DWG D556175B and D556175C. When the Tave calibrating integral travels to its limit the effective neutron power error to the cross limit is reduced and therefore results in inadequate reduction in feedwater flow.

RECOMMENDATIONS:

On DWG D556175 T1 (Calibrating Integral Operation), logic block should be added between RC D3.1 and RC D4.1. This logic block to read "REACTOR TRIPPED? (By Diamond)". If YES, Block calibrating integral F00.12. If NO, Proceed to RC D4.1.

DESIRED ACTION:

Please contact B&W to see if they would like to implement this ICS improvement.

APPLIES TO OTHER NSS CONTRACTS: YES

APPROVAL

DATE

CLNT. ENGR
FILE 12M 2

POOR ORIGINAL

~~1000~~

● = NSS-5 SPR 322 Fale (P. 100)

On 5-12-75 I discussed this with Bob White. Bob

feels that this particular problem is part of an ongoing evaluation underway at TME and to maintain the plant on line after a Turbine Trip. He says he's committed to making a final rec. recommendation for the new NSS which would be issued for NSS-7, 14, 6 etc once TME completes additional testing later this year.

4/25/75 EC# - 174 At BDCo LEO KOLHAPY

2-2-76 322 rev. 0 dead this date. 322 rev. 1 was generated based on sensor information → plant in manual during transient. Don Manning will review rev. 1 and → done 1/26/76 as to whether or not he thinks the SPR would be dead. 2-15

(10045)

3-16-75 Talk to STAN MANGI to see if we looked into this - WAS THE PLANT IN MANUAL? SHOULD SPR BE RELEAS? (CALL CALLER?)

POOR ORIGINAL

SITE PROBLEM REPORT

BARCOCK & WILCOX

CUSTOMER MET ED	CONTRACT NO. 620-000	SPR NO. 322	REV. NO. 1
VENDOR BACO	P. O. NO.	TASK NO. 21	GROUP NO. 01
SITE ENGINEER S. P. MATSOI	REQ'D. RESOL. DATE	REQ'D. COMP. DATE	

TITLE LOW PRESSURIZER LEVEL FOLLOWING REACTOR TRIP

DESCRIPTION OF PROBLEM
SEE ATTACHED SHEET

STATUS - ACTION TO DATE INCLUDING PERSONS CONTACTED
L. M. Kolony of Engineering informed.

FURTHER ACTION RECOMMENDED BY SITE PERSONNEL
Review and implement Logic modification such that reactor trip should block calibrating integral RC 9.12, to achieve a slower cooldown rate of RC System and a more acceptable pressurizer level.
This problem should be reviewed for all other sites.

Spencer 10/17/74 *[Signature]* 10/17/74

RESOLUTION

APPROVED BY	SIGNATURE	DATE
N. S. SUPPORT ENGINEER <i>[Signature]</i>		
TASK ENGINEER		
PROJECT MANAGER		

COST CATEGORY NORM C D G L VENDOR CLAIM

AUTH CHARGE NO FIELD CHANGE REQ FC NO

COMPLETION	SITE COMPLETION REPORT		<input type="checkbox"/> RECOMMENDED STDS. CHANGE
	DEVIATIONS <input type="checkbox"/> NONE <input type="checkbox"/> SEE SPR REV. NO. _____		FINAL DISTRIBUTION
	DATE COMPLETED	SIGNED BY	PROJECT MANAGER
	S O M. CONSTR. REP APPROVAL	DATE	S O M. CONST. REP

QA DOC FILE
CENT. ENGR
FILE 1212

POOR ORIGINAL

ATTACHMENT
SPR 322 Rev. 1

DESCRIPTION OF PROBLEM:

Following a reactor trip the pressurizer level goes as low as 40 inches. SPR 322 Rev. 0 pointed out the main reason that pressurizer level goes as low, because the trapped steam pressure in turbine header decays slowly, resulting in turbine bypass remaining open for time longer than is necessary.

Further examination of the reactor trip data revealed that immediately following the reactor trip the feedwater demand actually reduced to 20% instead of reducing to 5% (cross limit value as neutron power following the trip is zero).

This additional feed to steam generators contributes to the excessive cooling of the RC system and hence lower pressurizer level.

See attached BMCs report on the subject.

POOR ORIGINAL

PROBLEM REPORT	PROB. SYSTEM FILE NO. (C/M)	FILE NO. (S)	DATE OF REPORT 9/4/74	BY R. S. Ward
TO: PROJECT SUPPORT	FROM: (S) ONLY	TO: (S) ONLY	WORK ORDER NO. 150L	APP. NO. 61239 179
PLANT S.A. NO. 408	PLANT	PLANT	WORK ORDER NO. 290628	MAIL STOP NO. 10 Box 352 Middleton, WI 53551
PROB. NO.	PROB. NO.	PROB. NO.	DATE CODE X X	SERIAL NO. (S) PART NO.

POSSIBLE FOR IMPROVEMENT

Referenced: My PR# of 9/23/74

On 9/4/74 Met. Ed. Plant Superintendent, Jack Herbein stated that "On a reactor trip the pressurizer level should not drop as low as it does. (to approximately 40 inches) Analysis of the 8/13/74 Generator breaker trip test reveals the cross limits from neutron power error to feedwater flow control did not perform as expected. The neutron power error cross limit should have reduced the feedwater demand immediately after reactor trip to approximately 5%. The neutron power error cross limit actually reduced the feedwater flow demand to approximately 20%. This additional feed to the steam generators contributed to the excessive rate of cooling of the RC system and the resultant drop in pressurizer level.

The reason for the above undesirable performance is as follows. On a reactor trip the CHD system transfers to manual. When the CHD is in manual the neutron power error is applied to the T_{avg} calibrating integral.

EFFECT ON SYSTEM (BRIEFLY):
Pressurizer level less than 80 inches cuts off heaters. RC pressure can not be controlled.

CUSTOMER ATTITUDE

MAJOR CONCERN

CONCERNED

UNCONCERNED

DATE SOLUTION REQUIRED: 10/15/74 OR INFO ONLY

SIGNATURE: *[Signature]* DATE: 9/27/74

FOR FIELD USE

DATE SERVICE:

SERVICE:

EXPENSES:

MA-ERR:

SER. NO. P73-236

ALLOCATION

PRODUCT

PRODUCT APPLICATION

SYSTEM

SYSTEM APPLICATION

WARRANTY

OTHER

DEFECTIVE PART RETURNED

NO

YES ON _____ DATE

MP NO.

FAILURE EXCLUDED

ON RECEIPT

IN SERVICE WARRANTY

IN SERVICE NON-WARRANTY

TEST TIME ALLOCATION

POSSIBLE CAUSE FOR PROBLEM

80 - FACTORY MATERIAL

81 - FACTORY MANUFACTURING

82 - QUALITY CONTROL

83 - PERFORMANCE DEGRADENCY

84 - FACTORY PACKAGING

85 - COMPONENT FAILURE

86 - WEAR/USE

87 - IMPROPER APPLICATION

88 - OPERATIONAL ENVIRONMENT

89 - INSUFFICIENT INSTRUCTION

90 - DOCUMENTATION

OPERATING CONDITIONS

AMBIENT TEMP: _____ OF

ATMOSPHERE: CLEAN DIRTY

AVERAGE: HIGH LOW AVE

HUMIDITY: HI LO AVE

TIME REQUIRED TO REPAIR: NA

REPAIR: TRIM/REBOOT

RECALIBRATE: _____

FAILURE DETAILS

BMOD PART NO. NA

DESCRIBE (CIRCUIT, LEAD, TRANSISTOR, ETC.)

CIRCUIT SYMBOL: _____

MP. OF PART (IF KNOWN): _____

HOW PART FAILED:

SHORT OPEN

MECH DAMAGE

ADJUSTMENT

DIRTY UNKNOWN

OTHER (DESCRIBE): _____

APPROVAL

DATE: _____

DISP. OF R/W: _____

DATE REC'D: _____

DATE RETURNED: _____

HOURS SPENT SOLUTION

DEPT	MAN	HRS

PROB. TYPE	FAILURE CAUSE CODE	PL	ITEM	ANALYSIS	ACTION TAKEN BY
COPES					
QUALITY ASSURANCE					
PROD. LIABILITY					
PROD. PLANNING					
NPD					
EPO					
CONTRACT OPER					
WARRANTY REPAIR					
CONSULTATION ENGR					
COMM SERVICES					
ORDER CENTER					
COMPONENT ENGR					

<input type="checkbox"/> PRELIMINARY ANS	SIGNATURE	DATE	
<input type="checkbox"/> FINAL SOLUTION			
FOLLOW UP ON COMPLETIVE ACTION			
CITY	NAME	PART NO.	COMMENTS

POOR ORIGINAL

ATTACHMENT

PROBLEM: (Cont'd)

At this time the neutron error is very large and rapidly causes the calibrating integral to travel to its limit. Reference DWG D553732 and D556175B. When the T_{ave} calibrating integral travels to its limit the effective neutron power error to the cross limit is reduced and therefore results in inadequate reduction in feedwater flow.

RECOMMENDATIONS:

On DW. D556175 T1 (Calibrating Integral Operation), Logic block should be added between RC D3.1 and RC D4.1. This Logic block to read "IS REACTOR TRIPPED? (By Diamond)". If YES, Block calibrating Integral SC9.12; If NO, Proceed to RC D4.1.

DESIRED ACTION:

Please contact B&W to see if they would like to implement this ICS improvement.

APPLIES TO OTHER MSS CONTRACTS: YES

POOR ORIGINAL

APR 16 1975

THE BABCOCK & WILCOX COMPANY
POWER GENERATION GROUP

To
C. A. Cready, Project Management

From
H. W. Winks, Control Analysis, EXT 2864

PWW

BOS 662-4

Cust.
Duke Power Company

File No.
or Ref.

Subj.
A Feedwater Pump Speed "Kicker" Circuit
for Oconee Unit #1 (and #2 and #3)

Date

April 16, 1975

This letter is correct as customer and our subject only

The following information on a modified Feedwater Pump Speed Control Circuit, which has been implemented at the TMI-1 Plant, is being forwarded at this time to allow incorporation prior to any additional load rejection tests scheduled for Units 1, 2, or 3. B&W recommends this as a temporary change to your ICS which will be followed up by a field change package.

The purpose of the Pump Speed "Kicker" Circuit is to enable the feedwater flow control system to continue to deliver a high level of flow to each Steam Generator, even though the steam outlet pressure has suddenly increased approximately 150 psi. The modification originated and implemented at TMI-1 improved the overall plant performance by directly increasing feedwater pump speed more rapidly than could be accomplished by the combined action of the feedwater control valve and pump speed controllers in the ICS.

The modification to the present Unit #1 ICS is the following:

Route an additional wire from the turbine header pressure error signal (IC/B on Drawing Unit #1) to two summers which are shown on Drawing D80J2311F. The particular summers are FW28.8B(6-1-3) and FW28.12B(6-2-1) and the new signal is to be connected to each summer. In the new line also install a diode and a 100 k ohm resistor in a path to ground. Refer to the attached schematic.

The turbine header pressure control error signal has the following effective range:

- + 10 Volts = 300 psi above setpoint.
- + 0.5 Volts = 15 psi above setpoint.
- Any signal below 0.5 Volts will be blocked by the diode in the new line.

The gain for the turbine header pressure error signal on each summer will have to be calculated and set by Duke Power Company. The calculation used at TMI-1 is given below:

POOR ORIGINAL

1. Assume pump discharge pressure varies with the square of pump speed when suction pressure is constant.
2. For two feedwater pump operation find the pump speed (S_0) when the plant is at 100% power.
3. This speed corresponds to a turbine header pressure of 885 psig.
4. For a turbine header pressure of approximately 1050 psig the required pump speed would have to be: $(S_1) = (S_0) \sqrt{1050 / 885}$. The increase in pump speed ($S_1 - S_0$) represents a fraction of the total range of feedwater pump speed (2700 rpm to 5400 rpm at TII-1) and the output voltage of each summer should be adjusted to cause an increase in feedwater pump speed to (S_1) when the turbine header pressure error signal corresponding to 1050 psig occurs on each summer.

The following numerical calculation is only an example:

Assume (S_0) is 4500 rpm at 100% power. Then (S_1) is $4500 \times 1.089 = 4900$ rpm and ($S_1 - S_0$) = 400 rpm. Assume total speed range of feedwater pumps is 2700 to 5400 rpm or the total increase in pump speed is 2700 rpm. The gain at each summer is that which will cause a pump speed of 4900 rpm when the error in turbine header pressure is 165 psig.

If you have any questions, I would be happy to discuss them with you.

RW:lr

cc: B. A. Karrasch
 A. W. Brown
 W. Van Sprooter
 R. F. Ryan
 W. E. Wilson
 J. T. Janis
 V. J. Galan
 R. S. Rand (EM Co)


Q/A The information contained in this memo has been checked for applicability and completeness.

Signature R. D. Randall

Date 4/16/75

POOR ORIGINAL

FEEDWATER PUMP SPEED "RICKER" MODIFICATION TO THE ICS



POOR ORIGINAL

PROBLEM:

Steam lines between the instrument connections for Turbine Header pressure and Steam Generator pressure.

Attached please find charts recorded during a generator trip test conducted 8-13-74 which resulted in a reactor trip. From these charts and table 1 it can be noted that while there was flow through the line there was a pressure drop i.e., SG pressure is 30 psi higher than THP, immediately after the trip with no pressure drop due to flow the pressures equalized. For the next 3.5 min. the SG pressure is less than THP. Also note the waves in the SG pressure recorded during the first minute are not present in the THP pressure. These conditions seem to be a good indication that the check valves did close.

The fact that the Turbine Header pressure remains higher for a time holds the Turbine Bypass Valves open longer than necessary. (AFTER The Safety Valves have closed)

It is believed that this area could be improved by having the turbine bypass valves modulate to control Steam Generator pressure when the reactor is tripped instead of turbine header pressure. Getting these valves closed sooner after a trip should keep the Steam generator pressure from dropping so low which would keep the steam generator temperature higher and therefore TAVE. This should then keep the pressurizer level from dropping so low because it would not have to make up as much volume in the RC system.

PROBLEM 2:

On August 13 the generator maker trip from 100% power transient was tested. The Reactor tripped on high RC pressure four seconds after the generator trip. After analysis of Reactimeter data it was observed that the system came very close to NOT tripping the reactor. We had previously sustained two turbine trips from 76% power without tripping the reactor. (The reactor did trip on the second turbine trip but not until the reactor had run all the way back to 20% power and this trip was due to operator error.) The most important item to be worked on to prevent reactor trip would be to reduce the maximum steam generator pressure immediately after the generator trip. This might be achieved by lowering the popping pressure on the last two banks of safety valves. In addition, the Emergency Relief Valve control could be modified to utilize the emergency relief valves (atmospheric dump valves) as additional steam relief capability. Presently the BEU limits as specified by BW call for immediate reduction of feedwater flow demand to approximately 60% due to the rise in steam generator pressure from 910 psig to 1070 psig on a turbine trip. The elimination or delay of the BEU limits in this situation would help to maintain the required feedwater flow which would in turn tend to prevent overheating the primary coolant and to prevent the Reactor tripping on high RC pressure.

POOR ORIGINAL

PAGE 3

The attached logic and schematic drawings reflect a suggested way to utilize the atmospheric relief valves to open for overpressure at any time, whether the turbine bypass valves are available or not.

It must be considered that this change will substantially increase the use of these atmospheric relief valves and might increase their maintenance requirements.

DESIRED ACTION:

Contact B&W to see if they would like to implement either of these suggestions.

APPLIES TO OTHER NSS CONTRACTS: YES (ITEM 2)

POOR ORIGINAL


TABLE 1

Steam Generator pressure and Turbine Header pressure recorded during generator trip test 8/13/74 at TMI Unit 1.

	<u>SG Press.</u>	<u>TH Press.</u>	<u>THP-SG Press.</u>
Before the trip	912 PSI	882 PSI	-30 PSI
peak	1080	1080	0
12 sec.	1068	1074	+6 PSI
24 "	1032	1059	+27
36 "	1008	1046	+38
48 "	984	1038	+54
1 min./60 "	946	1032	+66
12 "	948	1021	+73
24 "	930	1017	+87
36 "	926	1008	+82
48 "	936	1004	+68
2 min./60 "	962	997	+35
12 "	984	994	+10
24 "	966	987	+1
36 "	1002	996	+6
48 "	1008	1005	-3
3 min./60 "	1014	1011	-3
12 "	1032	1020	-12
24 "	1032	1023	-11
36 "	1020	1020	0
48 "	1020	1020	0
4 min./60 "	1020	1020	0


POOR ORIGINAL

OPTION 1
TURBINE BYPASS VALVE CONTROL




POOR ORIGINAL

POOR ORIGINAL







NOTE:
CONTROL LOGIC TO MANAGER
TRANSFER CONTROL TO MANUAL
LEAD TUNING MANUFACTURER



TRANSFER CONTROL TO
MANUAL


IS UNIT IN TRACKING
FOR MANUAL CONTROL

TRANSFER CONTROL TO
MANUAL



4
3

(UNOFFICIAL COPY) IS ORIGINAL



BARON & WILCOX
DRAWING NUMBER
620255


RELAY
2.5V DC
CONVERTER
RELAY

BAILY ACME COMPANY
MACHINE CARD

DR032704F


POOR ORIGINAL

62-21080



(PARTIAL OF) D802729F

POOR ORIGINAL



Part of Dwg
D553730

Alternate TB control
using STM Gen. PR455,
Drawn at BRW6X054257

POOR ORIGINAL

Alternate Schematic
 using Steam G-2.1,
 Press to
 Control T B valves

STEAM GEN B
 OUTLET PRESS
 DWG D554567

Part of
 DWG
 D553730

IC 16.12
 125 PSI

IC 16.11
 75 PSI

IC 16.10
 75 PSI

IC 17.13

IC 18.11
 % + I

IC 19.13
 H/A

IC 20.13
 >

IC 17.15
 S

1040 PSI

STEAM GEN A
 OUTLET PRESS
 DWG D554567

IC 19.10
 S

1040 PSI

IC 19.10
 Δ -

IC 20.10
 %

IC 17.11
 Δ +

IC 18.11
 % + I

IC 19.11
 H/A

IC 20.11
 >

IC 16.15
 S

IC 17.15
 T₁

IC 18.15
 T₂

IC 19.15
 f(x)

f(x)

f(x)

f(x)

f(x)

f(x)

f(x)


f(x)

f(x)

POOR ORIGINAL

Using Stim. Gen.,
Pressure to
Control TB
Values


Part of
DWG D553854






POOR ORIGINAL

Generator Trip Test From 100% 2-13-72



2-13-72



POOR ORIGINAL







POOR ORIGINAL



POOR ORIGINAL

GENERATOR TOP TEST FROM 100% 4 8-1



POOR ORIGINAL

PLATE 23

100% POSITION

TIME

Lead + integral
to 100% position

250"

SS. Control Level "E"
9-2-1. 100%

0% POSITION

0"

100% POSITION

Lead + integral
to 100% position

0% POSITION

250"

SS. Control Level "E"
9-2-2. 100%

0"

6x10⁶ #/hr

SS. Control Level "E"
9-2-1. 100%
(with 0% velocity)

Investigation
should be
conducted
w/

6x10⁶ #/hr

POOR ORIGINAL

9-3-1 output 1

0"

FW Demand "E"
9-4-12

100% position

0% position

250"

SCC Error - 1/2 Load "H"
9-4-12

0

6X10⁴ #/hr

FW Demand "E"
9-4-12
(with STU limits)

20%
Should not
come back
up

6X10⁴ #/hr

FW Demand "E"
(with STU limits)

0 #/hr

6X10⁴ #/hr


150"

250"

POOR ORIGINAL

41
100

CORNER INTO TRIP TEST FROM 100% of 8-



POOR ORIGINAL

-25400

12X10⁶ 1/2

FIV PAIR
FIVE PAIR
10-4-1 IMP 2

100%

Sig. To FIVE PAIR 3"

INTERNAL LOCK
INTERNAL LOCK
INTERNAL LOCK

FIV PAIR 2
INTERNAL PRESS
10-4-1 IMP 2

100 PSID

OPSID

100 PSID

INTERNAL PRESS
INTERNAL PRESS
INTERNAL PRESS
10-4-1 IMP 1

OPSID

Generator Breaker
Time 10:00

11236

27

GENCOINTO TRIP TEST FOR 100%

POOR ORIGINAL


COMMENTS TRIP TEST FOR 100% ϕ



OPEN TIME

2" BYPASS VALVE DEMAND
2-9-10 OUT

CLOSED



1200 PSI

1032 PSI


989 PSI

1060 PSI

1124 PSI

1" - 2" BYPASS VALVE DEMAND
2-9-10 OUT

0 PSI



OPEN

1" BYPASS VALVE DEMAND
2-9-10 OUT

CLOSED



OPEN

1" - 2" BYPASS VALVE DEMAND
2-9-10 OUT

CLOSED




OPEN

1" - 2" BYPASS VALVE DEMAND
2-9-10 OUT

CLOSED

POOR ORIGINAL



POOR ORIGINAL

3

Site PROBLEM
REPORT TRANSMITTAL

**** CLEARED ****

TO: _____ For Information
Central Engineering Files
C. C. Plunkett - Contract Admin.
S. H. Klein - Quality Assurance
B. J. SHEPHERD - Task Engineer
R. A. GOUERS - Project Manager

FILE: 12M2
CONTRACT NO: 620-00 05
SPR 322 REV. 0
TITLE ICS PERFORMANCE
FOLLOWING GENERATOR-
REACTOR TRIP
DATE: 3-12-76

The attached, cleared SPR is submitted for your information.

TO: _____ E. L. Logan - FLORIDA _____
_____ L. C. Rogers - MET. ED. _____
_____ R. J. Baker - TOLEDO _____
_____ B. L. Day - Intl. Support _____
_____ P. E. Perrone - OFR _____
_____ J. L. Donnell - OFR _____

R. W. WINKS
L. M. KOLONAY

Attached is one copy of Site Problem Report No. 322 which was processed on Contract 620-00 05. Future contracts have been reviewed for the potential of a similar problem. This problem is/~~is~~ considered applicable to other contracts 3-14

REMARKS: _____

cc: G. M. Jacks - Plant Integration
This SPR has been reviewed IAW NPG-1707-01

Chris C. Lockard
NUCLEAR SERVICE SUPPORT ENGINEER

CLEARED

POOR ORIGINAL

SITE PROBLEM REPORT

BABCOCK & WILCOX

CUSTOMER MET ED		CONTRACT NO. 620-0005		SPR NO. 322	REV. NO. 0
VENDOR EMCo		P.O. NO.	TASK NO. 2:	GROUP NO. 01	SEQ. NO. 01
SITE ENGINEER S. P. MAINGI			REQ'D. RESOL. DATE	REQ'D. COMP. DATE	
TITLE ICS PERFORMANCE FOLLOWING GENERATOR-REACTOR TRIP					
DESCRIPTION OF PROBLEM #1 Following a Reactor Trip the pressurizer level goes as low as 40 inches. #2 The Reactor Trips on high RC pressure within few seconds, following a Generator/Turbine trip at 100% power. Per customer these situations are unacceptable. See EMCo. problem report attached.					
STATUS - ACTION TO DATE INCLUDING PERSONS CONTACTED R. Winks of Control Analysis and L. H. Kology of Engineering are made aware of the problem.					
FURTHER ACTION RECOMMENDED BY SITE PERSONNEL #1 Issue field change covering Turbine bypass Valves control signals following the reactor trip should be from OTSC's. #2 To review recommendations in EMCo problem report, specially elimination or relaxation of STU Limits and lowering settings on last two banks of safety valves.					
APPROVED BY <i>Spencer</i>		DATE 4/25/74	SIGNATURE <i>L. H. Kology</i>		DATE 4/30/74
RESOLUTION 1) FC-174 2) Letter, L. H. Kology to J. G. Harbein dated 5-27-75 (attached)					
RESOLUTION	APPROVED BY		SIGNATURE		DATE
	N.S. SUPPORT ENGINEER <i>Spencer</i>		<i>Miles VanDike</i>		2-2-76
	TASK ENGINEER <i>Spencer</i>		<i>[Signature]</i>		4/2/76
	OPS manager		<i>[Signature]</i>		2/17/76
PROJECT MANAGER		<i>[Signature]</i>		2/5/76	
COST CATEGORY <input type="checkbox"/> NORM <input type="checkbox"/> C <input type="checkbox"/> D <input type="checkbox"/> G <input type="checkbox"/> L <input type="checkbox"/> VENDOR CLAIM					
AUTH CHARGE NO			<input type="checkbox"/> FIELD CHANGE REQ		FC NO
COMPLETION	SITE COMPLETION REPORT				<input type="checkbox"/> RECOMMENDED STDS. CHANGE
	SEE ATTACHMENT				FINAL DISTRIBUTION
	DEVIATIONS <input type="checkbox"/> NONE <input type="checkbox"/> SEE SPR REV NO. _____				PROJECT MANAGER
	DATE COMPLETED 1/19/76		SIGNED BY <i>Spencer</i>		S.O.M. CONST. REP.
S.O.M. CONSTR. REP. APPROVAL <i>[Signature]</i>			DATE 1/19/76	QA DOC. FILE	
					CENT. ENGR
					FILE 1212

POOR ORIGINAL

SITE COMPLETION REPORT:

1. Field change 174, stopping Turbine bypass Valve controls to OTTI Trippers rather than Turbine header pressure has been implemented.
2. New relaxed BTM limits have been incorporated.
3. Relief settings on the two main safety valves have been reduced from 1092 PSIG to 1050 PSIG.

All these steps will help run the reactor back to 15% power on a Turbine/Generator Trip, so the SPR is being closed.

POOR ORIGINAL

B. W. Winks

Babcock & Wilcox

Power Generation Group
P.O. Box 1399, York, Pa. 17405
Telephone (304) 384-5111

May 27, 1975

REM-I-104

Mr. J. G. Herbein
Metropolitan Edison Company
Post Office Box 430
Middletown, PA 17057

Subject: Revised BTU Limits for TMI-1
Reference: REM-I-02, I. C. Rogers to J. G. Herbein dated May, 1975

Dear Mr. Herbein:

B&W Engineering has recently completed work on the revised curves for the BTU Limit circuit for TMI-1 in preparation for plant operation and testing associated with the proposed turbine trip or load rejection test at rated power. Attachments include these curves and an appropriate table.

An analysis of plant operational characteristics during the January 23, 1975, power runback transient has led to a revision of the curves comprising the BTU Limit circuit. Figure 1 (attached) shows the revised curves which can be incorporated into the ICS at the first opportunity. Comparison with the curves of Figure 2 which are currently in use reveals that the steam pressure limit is significantly expanded, whereas the T hot curve is more limiting at lower temperatures and power levels. The feedwater temperature curve was changed to properly represent the effect of feedwater temperature on feedwater flow and steam superheat. Also, reactor coolant flow has been changed slightly. These revised curves are to be utilized for all plant operation from now on and are not only associated with the proposed plant runback tests.

The revised BTU Limit curves were tested on the B&W Old Forest Road PWR simulator for several major transients and the TMI-1 type plant with the new BTU Limits performed very well. When compared with the old curves, the new Limits provided greater operating margin at full power.

The development of the revised curves was accomplished by using the B&W certified steam generator computer code and determining the limits for the four parameters which comprise the BTU Limits to exceed or maintain 35°F superheat. After incorporating the curves into the simulator ICS, the following operational transients were incorporated:

- (a) ramping power up and down with both 3 and 4 RC pumps operating;

POOR ORIGINAL

5/21/75

- (b) tripping VRC pump at 75% power level
- (c) tripping the turbine at 100% power level

All of these transients were performed successfully without a reactor trip. In addition, transients in which the feedwater flow had to be limited were performed and the control of the feedwater flow by the new BTU Limits was excellent. Sufficient testing of the new BTU Limit curves has occurred and fewer operational problems should develop at TMI-1 since the BTU Limits are less restrictive than the curves presently in use.

The accompanying table presents the specific information which defines each of the four curves in the BTU Limit circuit.

Additional information with regard to lowering the setpoint for pressurizer electromagnetic relief valve, is included and has been reviewed by the Control Analysis Group of Babcock & Wilcox.

The effect of lowering the setpoint of the pressurizer electromagnetic relief valve from 2255 to 2205 psig has been analyzed and will flow an additional 56 lbs of steam to the Quench Tank during a very severe transient.

If you have any further questions, please contact me.

Very truly yours,



L. C. Rogers
Resident Engineer Manager

LCR/SFA/ser

cc: J. J. Colits
J. D. Phinney
K. F. Schmitt
D. B. Tulodjeski
~~W. W. Winks~~
R. S. Rani

POOR ORIGINAL