

SITE PROBLEM REPORT

BADCO 2 WILCOX

CUSTOMER Toledo Edison Company	ORIGINATOR F.R.Faist	DATE 11/2/77	DOC. NO. CONT. NO. 13 620-0014	SPR NO. 300
VENDOR Crosby	P.A. NO. 023 090 LS		PART NO./TAGG NO. 28/041/005	GROUP NO.
TITLE (MAX 30 CHARACTERS) Electromatic Relief Valve Modification			PROBLEM CONTACT J. E. Anderson	

DESCRIPTION OF PROBLEM:

See attached sheet.

PROBLEM IDENTIFICATION

STATUS-ACTION TO DATE, INCLUDING PERSONS CONTACTED: Lynb. Engineering is aware of this problem. S. A. Lamanna, Lynb., and J. A. Lauer, Proj. Mgm. know of this problem. T. D. Murray and B. R. Beyer, TECo, are also aware of the problem.

FURTHER ACTION RECOMMENDED BY SITE PERSONNEL: 1. Lynb. Engineering should review Crosby installation, operating and maintenance instructions No. I - 1115, Sect. 4.2, with the Crosby vendor to determine if these instructions will give the proper pilot valve stem adjustment when actuated. 2. Engineering to provide additional recommendation and concurrence with action taken.

RESOLUTION: *Engineering concurred with recommendations per communication with Mr. Dick Ashmaker. The instruction number section 4.2 will be revised by Crosby. A copy will be given copies of the revised pages for the I.M. Steve Lamanna.*

RESOLUTION

PREPARED BY <i>Tong Halsted</i>	DATE 11-4-77	APPROVED BY	DATE
<i>R. L. Lauer & K. Ellison</i>	DATE 11-7-77	<i>J. A. Lauer</i>	11-7-77

COST CATEGORY <input type="checkbox"/> NORM <input checked="" type="checkbox"/> OTHER	FIELD CHANGE REQ <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	F.C.A. NO. 04- N/A	SIGNIF. DEFICIENCY <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO
--	---	-----------------------	---

COMPLETION

SITE COMPLETION REPORT: SOM Letter #352, copy attached was written to TECo. Instruction manual is correct and will not be revised. Additional adjustment check provided. Eng. concurred with Crosby/TECo actions.	DEVIATIONS: <input checked="" type="checkbox"/> NONE <input type="checkbox"/> SPR REV NO. <input type="checkbox"/>
	DATE COMPLETED: 3/24/78
	COMPLETED BY F. R. Faist <i>F. R. Faist</i> DATE 3/24/78
	F. R. Faist <i>F. R. Faist</i> DATE 3/24/78

POOR ORIGINAL

Description of Problem:

On 10/13/77, the electromatic relief valve was tested after the completion of repairs as outlined in SPR #369. The valve was cycled six times successfully. On the seventh test cycle the pilot valve did not close. The ERV was isolated and permitted to cool down while waiting for Crosby representatives.

Crosby rep., Walt Conroy, arrived and the pilot valve assembly was removed from the main valve. Disassembly of the pilot valve revealed that the pilot valve stem had stuck open due to the close tolerance causing a binding condition between the O.D. of the stem and the I. D. of the pilot valve nozzle. Also, a small metal particle was found in the pilot stem/nozzle area. Subsequent cleaning of the inlet piping to the ERV revealed this same type of metal particles.

The Crosby representative furnished a detailed drawing of the pilot valve stem requiring a diameter of .374. This was changed to read .373 diameter .372.

by the Crosby rep., and the stem was modified accordingly by TECo Maintenance under the direction of the Crosby rep. This modification resulted in opening the clearance between the stem and the nozzle thus eliminating the binding. The nozzle was also reamed out with a reamer the same size, no material was removed.

All parts were cleaned and assembled. The solenoid linkage was adjusted to drop the adjustment bolt more squarely on the disc actuator. In addition, the adjustment bolt was positioned to move the pilot valve stem off the seat a maximum of .125". It had been moving off the seat some .375".

The pilot valve was tested without pressure by actuating the solenoid three times. The valve was tested again twice with 5 or 6 seconds between tests. This was followed by testing the valve five more times assuring actuation each time by a one-minute delay between tests. The valve was tested with a pressure of 1100 psig on the second and third occasion.

JEA:nlf

POOR ORIGINAL

9 of 12

ERU MODIFICATION

TITLE 0

HXKCH-8
80 SPR #326
620-0014

Suggested test
signature
from bank value closed RC11
Test electrical solenoid circuit 3 times

Open ~~RC11~~ RC11
Follow twice for 5-6 seconds if
to give ~~stroke~~ ~~stroke~~ ~~stroke~~ ~~stroke~~ ~~stroke~~
RC5 & Q.T can take it
As not go below 600 psi on RC5 if
press should be as near 1500 psi as possible
will test at 1150 because of heat transfer
limitation -

Stroke 5 times assuming retention
during each time - ~~stroke~~ ~~stroke~~ ~~stroke~~ ~~stroke~~ ~~stroke~~
in between strokes to avoid closing
~~RC5~~
Stroke 5 times again same as above

WRC wants one cycle at temp & pressure

~~858 2511 Finoff~~
~~312 682 1257 Test~~

POOR ORIGINAL 4 of 42

Long Creek Relief

10-14-77

Min clearance between guides and stem
was 0.005"

373 - 374 stem

was 0.3745 at bottom
~~0.3745 at bottom~~

375 - 376 : nozzles

~~0.3745 at bottom~~

Revised stem diameter by grinding with many cuts
approx

0.375 in nozzles

0.375 on stem - Cooley will send revised drawing

① Opened clearance between guide & plate to bottom
sufficed seats

Main valve weight OK - seats good - but not
in ~~assembly~~ disassembly - valve seat looking

② Alter solenoid to set ^{full actuator} stroke to about .130 - .140"
to get ~100 strokes on pilot valve

③ Will attempt to eliminate side force on
the pilot valve actuator stem - will send
alter face of solenoid bolt on
solenoid frame

④ Cleared line between check valve & pilot


Crosby - Bolt, Crosby
Egt Intermine

10-15-77

Accomplished things planned and
discussed on 10-14-77.

Walt will include in his
report recommendation to revise
method of adjusting selected
to get ≈ 0.100 pilot valve stroke.

Crosby ~~will~~ Engineering will
submit letter on change on
pilot valve stem diameter.


10/15/77

POOR ORIGINAL

FUNCTIONAL ACCOUNT NO.

EQUIPMENT FILE NO.

MWO NO.

58

33005

77-2120

EQUIPMENT INSTRUMENT NAME AND NO. PRZR ELECTROMAGNETIC RELIEF VALVE RC2A

MWO INITIATED BY:

MWO NO. OTHER

WRI

AIR NO.

NCR No.

DESCRIPTION OF PROBLEM/MALFUNCTION

RC2A STUCK OPEN. TROUBLESHOOT AND REPAIR AS NEEDED. WORK WITH SERVICE MAN ON REPAIRS

4. WORK CLASSIFICATION

Normal Immediate Emergency Outage
 Routine Non-Routine
 Nuclear Safety Related/ASME Non-Nuclear Safety Related

Preventive Maintenance Frequency Scheduled For

5. REP REQUIRED

Yes No

6. CLEANLINESS INSPECTION REQUIRED

Yes No

7. NPRD REQUIRED

Yes No

8. PROCEDURE/INSTRUCTION

Number REC-1 Revision

9. APPROVED BY MAINTENANCE/I&C ENGINEER

[Signature]

DATE

9/26/77

REVIEWED BY QUALITY CONTROL

DESIGNATED INSPECTOR (Name)

MIN. LEVEL

[Signature] Charles R. Section

[Signature]

SPECIAL INSTRUCTIONS

NOT TO BE OPEN TO STARTING WORK.

11. ASSIGNED RESPONSIBILITY

12. PERMISSION TO COMMENCE WORK

DATE

Wassell/MacCallister

J.C. Skiland

9/27/77

DESCRIPTION OF WORK PERFORMED

DISASSEMBLED VALVES REPLACED PARTS & GASKETS REASSEMBLED VALVES - WAS NOT ABLE TO CYCLE VALVE DUE TO X/C POWER RATED P.V.H.H. when valve was cycled with pressure pilot valve stuck again on the 5th blow.

14. TEST EQUIPMENT I.D. NO.

CALIBRATION DUE DATE

15. SPARE PARTS REQUIRED:

Yes No (List MIT or P.O. or ETC)

MAINTENANCE COMPLETED AND INSPECTED PER REQUIREMENTS OF AD 1544.00

16. DESIGNATED INSPECTOR

DATE

RESPONSIBLE FOREMAN

DATE

[Signature]

10/17/77

[Signature]

10-17-77

TESTING COMPLETED & RETURNED TO SHIFT FOREMAN FOREMAN CONTROL

17. TEST NO.

SHIFT FOREMAN FOREMAN

DATE

[Signature]

10/17/77

ACTION ITEMS/FOLLOW UP

NPRD Form Completed (if required) None Required

Initiated Followup MWO NO. 77-2-2-56 Other

Initiated AIR/DVR NO.

MWO REVIEWED AND APPROVED

DATE

10/19/77

POOR ORIGINAL


Net Weston measurement is 0.372
Diode measurement is 0.375

Valve was tested at ≈ 1100 psi 10 times and closed satisfactorily with no leakage noted.

Valve was also tested one time at 2150 psi and closed satisfactorily with no leakage noted.

Valve was also opened and closed once and had two additional ≈ 5 second blows ^{at ≈ 1100 psi} the 10 times above
B.P.S.
6/19/77

POOR ORIGINAL



POOR ORIGINAL

FIG. 1
ASSEMBLY OF PRESSURMATIC
VALVE STYLE HPV-SN

CROSBY



Jack Anderson

January 13, 1978

The Babcock & Wilcox Company
Power Generating Group
P.O. Box 1260
Lynchburg, Virginia 24505

Attention: Mr. C. D. Carmichael
Senior Buyer
Purchasing Department

Subject: TOLEDO EDISON (DAVIS BESSE NO. 1)
HPV-SN ASSEMBLY NO. N54890
ADJUSTMENT OF SOLENOID ADJUSTING BOLT

Gentlemen:

Please forward the following information to Steve Lamanna.

Para. 4.2.2.2, Crosby instruction No. I-1115 is correct as written and should be followed.

Proper adjustment of the solenoid adjusting bolt can be further checked as follows:

- Move the solenoid plunger to full stroke by pushing to the maximum position. The Disc Actuator Pilot Valve (19) will be depressed by the adjusting bolt (31) with the plunger in this position. If the adjusting bolt (31) were to be backed off a distance of approximately 5/32" (which could be accomplished by allowing the plunger to drop from its full upward position), the adjusting bolt (31) should be just beginning to make contact with the disc actuator pilot valve (19). Should the condition prevail, with the adjusting bolt (31) is making contact with, or is moving the disc pilot valve (19) below the free position, the adjustment is not correct and should be reset per instruction I-1115, Para. 4.2.2.2.

The above described method is not to be used for any reason other than information, and all settings of the adjusting bolt (31) should be per the instruction manual (I-1115).

POOR ORIGINAL

I hope the information as written is clear and as requested, but if further clarification or information is required, please do not hesitate to contact Mr. R. A. Wright, Service Manager or this writer.

Very truly yours,

CROSBY VALVE & GAGE COMPANY

R.J. Martin

R.J. Martin

Asst. Product Manager - Power Industry

RJM/lea

cc: V.L. Heine
R.A. Wright
P.F. Black
M.A. Gaffin

POOR ORIGINAL

March 24, 1978

SOM #352

620-0014

12B28

T3.3.1

01-0204-00

Mr. T. D. Murray, Station Superintendent
Davis-Besse Nuclear Power Station
5501 North State Route #2
Oak Harbor, Ohio 43449

Subject: Adjustment of Solenoid Adjusting Bolt on Pressurizer
Power Relief Valve RC2A

Reference: Crosby Style HPV-SN Solenoid Pilot Operated Relief
Valve, "Installation, Operating and Maintenance In-
struction No. I-1115", B&W #01-0204-00

Dear Terry:

The referenced instruction manual pertains to the pressurizer power relief valve RC2A. Section 4 of the manual describes the testing and adjustment procedure for the valve, while section 4.2 pertains to adjustments for proper pilot valve actuation.

A critical adjustment is that described in step 4.2.2.2, Setting of the Adjusting Bolt (F/N 31). All adjustments should be made per the instruction manual, however, proper adjustment of the solenoid adjustment bolt can be further checked as follows:

Move the solenoid plunger to full stroke by pushing to the maximum position. The Disc Actuator Pilot Valve (19) will be depressed by the adjusting bolt (31) with the plunger in this position. If the adjusting bolt (31) were to be backed off a distance of approximately $5/32$ " (which could be accomplished by allowing the plunger to drop from its full upward position), the adjusting bolt (31) should be just beginning to make contact with the disc actuator pilot valve (19). Should the condition prevail, with the adjusting bolt (31) making contact with, or is moving the disc pilot valve (19) below the free position, the adjustment is not correct and should be re-set per instruction I-1115, Para. 4.2.2.2.


POOR ORIGINAL

Installation and adjustment of the power relief valve was performed with a Crosby service representative. The valve operated properly when tested immediately after installation, and has operated properly during certain RCS transients.

It is recommended that the "further checks" on the solenoid adjustment bolt stated above be included in the appropriate maintenance procedures for the power relief valve RC2A to minimize any misadjustments that may be overlooked.

If you have any questions, please advise.

Yours truly,



Fred R. Faist
Site Operations Manager

FRF:nlf

cc: W. H. Spangler
J. A. Lauer
R. L. Pittman
R. J. Finnin
D. A. Lee

J. S. Grant, TECo
E. C. Novak, TECo
C. R. Domeck, TECo
J. G. Evans, TECo
B. R. Beyer, TECo
R. A. Brown, TECo
J. P. Hartigan, Jr., TECo
J. D. Lenardson, TECo
R. E. Blanchong, TECo

POOR ORIGINAL