

1 0 | H | D | E | S | 1 | 2 | 0 | 0 | - | 0 | 0 | N | P | F | - | 0 | 3 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | [ ] | [ ] | 5  
8 LICENSE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE JO 57 CAT 5E

1 REPORT SOURCE L | 6 | 0 | 5 | 0 | - | 0 | 3 | 4 | 6 | 7 | 0 | 6 | 1 | 2 | 7 | 8 | 8 | 0 | 6 | 2 | 3 | 7 | 8 | 9  
8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

2 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)  
On June 12, 1978, a review of the Safety Features Actuation System 18 Month Test, ST 5031.07 found that the voltage and time delay setpoints of the essential bus under-voltage trip relays were incorrect and the monthly functional test was not being performed. The provisions of Technical Specification 3.3.2.1 did not apply as the unit was in Mode 6. This event is being reported in accordance with Technical Specification 6.9.1.8f. (NP-32-78-07)

9 SYSTEM CODE [E | E | 11] CAUSE CODE [D | 12] CAUSE SUBCODE [Z | 13] COMPONENT CODE [R | E | L | A | Y | X | 14] COMP. SUBCODE [J | 15] VALVE SUBCODE [Z | 16]  
17 LER/RC REPORT NUMBER [7 | 8 | 21 | 22] SEQUENTIAL REPORT NO. [0 | 6 | 1 | 24 | 26] OCCURRENCE CODE [0 | 1 | 28 | 29] REPORT TYPE [T | 30] REVISION NO. [0 | 32]  
ACTION TAKEN [E | 18 | 33] FUTURE ACTION [Z | 19 | 34] EFFECT ON PLANT [Z | 20 | 35] SHUTDOWN METHOD [Z | 21 | 36] HOURS [0 | 0 | 0 | 0 | 37 | 40] ATTACHMENT SUBMITTED [Y | 23 | 41] NPRD-4 FORM SUB. [Y | 24 | 42] PRIME COMP. SUPPLIER [A | 25 | 43] COMPONENT MANUFACTURER [I | 2 | 0 | 2 | 44 | 47]

0 CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)  
Facility Change Request 77-430 was immediately issued for implementation to adjust the time delay and voltage setpoints. One relay was found to be defective and was replaced. The relay settings were changed to comply with Technical Specification requirements. A new surveillance test procedure will be prepared to assure the monthly functional test is completed when the unit is in the applicable modes.

5 FACILITY STATUS [G | 28 | 8 | 9] % POWER [0 | 0 | 0 | 29 | 10 | 12 | 13] OTHER STATUS [30] METHOD OF DISCOVERY [B | 31 | 44 | 45] DISCOVERY DESCRIPTION [Surveillance Test ST 5031.07 | 32 | 46]

6 ACTIVITY CONTENT RELEASED OF RELEASE [Z | 33 | 10 | 11] AMOUNT OF ACTIVITY [NA | 35 | 44] LOCATION OF RELEASE [NA | 36 | 45]

7 PERSONNEL EXPOSURES NUMBER [0 | 0 | 0 | 37 | 11] TYPE [Z | 38 | 12] DESCRIPTION [NA | 39 | 13]

8 PERSONNEL INJURIES NUMBER [0 | 0 | 0 | 40 | 11] DESCRIPTION [NA | 41 | 12]

9 LOSS OF OR DAMAGE TO FACILITY TYPE [Z | 42 | 11] DESCRIPTION [NA | 43 | 12]

0 PUBLICITY ISSUED [N | 44 | 10] DESCRIPTION [NA | 45 | 11]

8001180137  
68 69 80

TOLEDO EDISON COMPANY  
DAVIS-BESSE UNIT ONE NUCLEAR POWER STATION  
SUPPLEMENTAL INFORMATION FOR LER NP-32-78-07

DATE OF EVENT: June 12, 1978

FACILITY: Davis-Besse Unit 1

IDENTIFICATION OF OCCURRENCE: Incorrect setpoints on essential bus undervoltage relays

Conditions Prior to Occurrence: The unit was in Mode 6 with Power (MWT) = 0, and Load (MWE) = 0.

Description of Occurrence: On June 12, 1978, during the Station Review Board review of the "Safety Features Actuation System (SFAS) 18 Month Test", ST 5031.07, it was found that the time delay setpoints of the essential bus undervoltage relays were incorrect and that the monthly channel functional test was not being performed.

The initial investigation showed the Facility Change Request (FCR) 77-217 which was implemented on October 4, 1977, called for the time delay to be set at 9 seconds. FCR 77-430 was prepared on October 28, 1977, to correct the setpoints to  $7 \pm 1.5$  seconds, but had not yet been issued for implementation on June 12, 1978.

This occurrence is being reported in accordance with the provisions of Technical Specification 6.9.1.8f.

Designation of Apparent Cause of Occurrence: The cause of this occurrence is procedure inadequacy.

Analysis of Occurrence: There was no danger to the health and safety of the public or to unit personnel. The intent of the  $7 \pm 1.5$  second time delay setpoint is to ensure that a bus trip will occur in 9 seconds after the bus voltage degrades to less than 90% of the normal voltage. The average time delay setting of the relays was found to be 8.99 seconds.

Corrective Action: FCR 77-430 was immediately implemented and at that time it was also found that the voltage setpoints were incorrectly set to a maximum of 2.5% less than the technical specification minimum. One relay was found to be defective and was replaced. The time delay and voltage setpoints were adjusted to values in compliance with Table 3.3-4 of Technical Specification 3.3.2.1. A modification (T-2870) was prepared for a test to be performed in conjunction with ST 5031.07 to satisfy the monthly functional check. A new surveillance test procedure will be written to assure the monthly functional test is completed when the unit is in the applicable modes. This work was completed on June 15, 1978 under Maintenance Work Order 78-1397.

Failure Data: This is not a repetitive occurrence.

EXHIBIT 1  
page 3 of 3