## LICENSEE EVENT REPORT

CONTROL BLOCK: [ ] [ ] [ ] (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1 P A T M I 2 2 0 0 - 0 0 0 0 0 0 0 3 4 1 1 1 1 1 6 5 CAT 58 5
CON'T SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80
EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)  O [2] During disassembly of NR-P-1D as a result of high pump vibration, it was
0 3 discovered that a top lug on a split ring coupling which joins two sections
of the pump shaft had sheared. Therefore, although the shaft was still intact,
0 5 the pump's ability to pump water over an extended period of time is unlikely.
0]6] This event is considered reportable under T.S. 6.9.1.9.b equipment failure.
07
0 8 L SO COMP. VALVE
SUBCODE SUBCODE CODE SUBCODE COMPONENT CODE SUBCODE SU
17 REPORT   7 9
ACTION FUTURE SEFECT SHUTDOWN HOURS (22) SUBMITTED FORM SUB. SUPPLIER MANUFACTURER SUBMITTED FORM SUB. SUPPLIER MANUFACTURER B 5 8 0 (24) A 25 (25) A 40 (27)
The cause for the coupling failure is most likely the result of high vibration
induced by badly worn bearings. The defective component and the worn bearings
are being replaced. The cause for the bearing wear is under investigation.
1 4 L 80
FACILITY STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32  1 5 G 28 0 0 0 0 29 NA A 31 High pump vibration observed  7 8 9 10 12 13 44 45 46 80
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) NA NA NA NA NA NA
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39
1 7 0 0 0 37 Z 38 NA 7 8 9 PERSONNEL INJURIES 13
NUMBER DESCRIPTION (4) NA
LOSS OF OR DAMAGE TO FACILITY 43  TYPE DESCRIPTION NA  NA
PUBLICITY (45) ISSUED DESCRIPTION (45)
NA NA 68 69 80.  Ron Warren 2405 (717) 948-8138
NAME OF PREADER RON Warren PHONE (717) 940-0130