(7-77)	LICENSEE EVENT REPORT
	CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1	M A P P S 1 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 1 4 5 6 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
O 1 8	REPORT L 6 0 5 0 - 0 2 9 3 7 0 3 2 6 8 0 8 0 4 0 9 8 0 9 SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80
0 2	On March 26, 1980, utilizing approved station procedure number TP80-37 entitled
0 3	"U.T. Examination of Jet Pump Beams", PNPS jet pumps were examined. As a result of
0 4	this testing, Jet Pump Beams 1, 3 & 15 were found to have discontinuities. The
0 5	flawed beams have been replaced.
0 6	
0 7	
0 8	- 3
0 9	SYSTEM CAUSE CAUSE COMPONENT CODE SUBCODE SUBCODE C B 11 E 12 D 13 P U M P X X 14 K 15 Z 16
7 8	9 10 11 12 13 18 19 20 SEQUENTIAL SEQUENTIAL SEQUENTIAL CODE TYPE NO. OCCURRENCE REPORT NO. OCCURRENCE TYPE NO. OCCURRENCE NO. O
	ACTION FUTURE ACTION ON PLANT SHUTDOWN METHOD HOURS 22 ATTACHMENT SUBMITTED FORM SUB. PRIME COMP. SUPPLIER MANUFACTURER [A 18 Z 19 Z 20 Z 21
1 0	Replacement, in kind, of the beam bolt assemblies on Jet Pumps 1, 3 and 15 has been
11	completed. Approved Station Procedure number 80-42 entitled Replacing Beams on
1 2	Reactor Vessel Jet Pumps was utilized for this maintenance. The procedure requires
1 3	detensioning the jet pumps, replacing the beams, and tack welding the lock nuts.
1 4 7 8	9 80
1 5	FACILITY STATUS SPOWER OTHER STATUS OTHER ST
	ELEASED OF RELEASE AMOUNT OF ACTIVITY 35 N.A. LOCATION OF RELEASE 36
1 7	PERSONNEL EXPOSURES NUMBER O 0 0 0 37 YES DESCRIPTION 39 N.A.
1 8	PERSONNEL INJURIES NUMBER DESCRIPTION 41 0 0 0 40 N.A.
7 8	9 11 12 LOSS OF OR DAMAGE TO FACILITY 43 TYPE DESCRIPTION 43
7 8	PUBLICITY (2) N.A. N.A.
2 0	ISSUED DESCRIPTION (45) N.A.
7 8	9 10 8 004170191 68 69 80 5 0 617-746-7900 9