(7.77)	LICENSEE EVENT REPORT
0	CONTROL BLOCK:
	M AY K R I O O O O O O O O O O O O O O O O O O
CON'T	REPORT L 6 0 5 0 0 0 2 9 0 0 4 0 7 8 0 8 0 5 0 7 8 0 9 SOURCE 60 61 DOCKET NUMBER 68 68 69 EVENT DATE 74 75 REPORT DATE 80
01.]	EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
0 3	for the Fire Detection System. The system is required to be operational
0 4	[per T.S. 3.3.3.4. A previous event was reported as LER 80-10. Since]
0 5	the Plant was in a shutdown condition and the action statements were
06	[met there were no adverse effects to the public health and safety.]
0 7	
08	
09 78	SYSTEM CAUSE CAUSE COMPONENT CODE SUBCODE SUBC
	Image: Number Num Number Number Number Number Number Number Number Number Number Nu
	ACTION FUTURE EFFECT SHUTDOWN HOURS 22 ATTACHMENT NPRD-4 FORM SUB. PRIME COMP. COMPONENT MANUFACTURER LA (8) Z (3) Z (2) Z (2) L (0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0
10	CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) The root cause of this event was a failure of the voltage
111	indicating light, manufactured by the Chicago Minature Company.
[1]2]	A fire patrol was established until the system was returned to
13	service. The light was replaced in kind and the system monitored for
14	normal operation, No further corrective action is planned.
7 8	9 FACILITY STATUS & POWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32
1 5	$ \begin{array}{c c c c c c c c c c c c c c c c c c c $
1 6	LOCATION OF RELEASE AMOUNT OF ACTIVITY (35) UCATION OF RELEASE (36) NA NA 10 10 11 44 45 LOCATION OF RELEASE (36) NA 80
17	PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39 0 0 37 Z 38 NA
7 8	9 PERSONNEL INJURIES NUMBER DESCRIPTION (41) 80
1 8	
119	LOSS OF OR DAMAGE TO FACILITY (43)
7 8	9 10 PUBLICITY ISSUED DESCRIPTION (5) NRC USE ONLY
2 0	$ \underbrace{\sum_{g} N_{g}}_{0} \underbrace{40}_{10} \underbrace{10}_{0} 1$
	NAME OF PREPARER LESTER D. FRENCH PHONE: (413) 625-6140