

### LICENSEE EVENT REPORT

CONTROL BLOCK: \_\_\_\_\_ ①

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | N | C | B | E | P | \_\_\_\_\_ | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | ③ | 4 | 1 | 1 | 1 | 1 | ④ | \_\_\_\_\_ | ⑤

CON'T  
01 | REPORT SOURCE | L | ⑥ | 0 | 5 | 0 | - | 0 | 3 | 2 | 5 | ⑦ | 0 | 4 | 1 | 7 | 8 | 0 | ⑧ | 0 | 5 | 0 | 6 | 8 | 0 | ⑨

#### EVENT DESCRIPTION AND PROBABLE CONSEQUENCES ⑩

02 | During a reactor startup, rod position indication for CRD 14-11 was lost for the  
03 | "tens" digit from positions "40-48." All other position indications were normal.  
04 | This event poses no threat to the public health or safety.  
05 | \_\_\_\_\_  
06 | \_\_\_\_\_  
07 | \_\_\_\_\_  
08 | Technical Specifications 3.1.3.7, 6.9.1.9b.

09 | SYSTEM CODE | I | D | ⑪ | CAUSE CODE | E | ⑫ | CAUSE SUBCODE | A | ⑬ | COMPONENT CODE | I | N | S | T | R | U | ⑭ | COMP. SUBCODE | E | ⑮ | VALVE SUBCODE | Z | ⑯ |

#### CAUSE DESCRIPTION AND CORRECTIVE ACTIONS ⑳

10 | After initial troubleshooting, it is believed the problem is a ground in the PIP  
11 | probe, located inside the drywell. This problem will be corrected during the next  
12 | outage of sufficient length. Engineering is investigating to determine if a generic  
13 | problem exists.  
14 | \_\_\_\_\_

15 | FACILITY STATUS | C | ⑲ | % POWER | 0 | 0 | 0 | ⑳ | OTHER STATUS | N/A | ㉓ | METHOD OF DISCOVERY | A | ㉔ | DISCOVERY DESCRIPTION | Operator Surveillance | ㉖ |

16 | ACTIVITY CONTENT RELEASED OF RELEASE | Z | ㉗ | AMOUNT OF ACTIVITY | N/A | ㉙ | LOCATION OF RELEASE | N/A | ㉛ |

17 | PERSONNEL EXPOSURES NUMBER | 0 | 0 | 0 | ㉜ | TYPE | Z | ㉝ | DESCRIPTION | N/A | ㉞ |

18 | PERSONNEL INJURIES NUMBER | 0 | 0 | 0 | ㉟ | DESCRIPTION | N/A | ㊱ |

NAME OF PREPARER A. C. Tollison, Jr.

PHONE: (919) 457-9521

NRC USE ONLY

GPO 91-7-92